District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 <u>Revised August 24, 2018</u> Submit to appropriate OCD District office

)

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party XTO Energy	OGRID 5380		
Contact Name Kyle Littrell	Contact Telephone 432-221-7331		
Contact email Kyle_Littrell@xtoenergy.com	Incident # (assigned by OCD)		
Contact mailing address 522 W. Mermod, Carlsbad, NM 88220			

Location of Release Source

Latitude	32.622056		Longitude	-103.851442		
	(NAD 83 in decimal degrees to 5 decimal places)					
Site Name	Hackberry 34 CTB		Site Type Tank Ba	attery		
Date Relea	se Discovered 02/29/2020		API# (if applicable)			
Unit Lette	er Section Township	Range	County			

Unit Letter	Section	Township	Range	County
А	34	19S	31E	Eddy

Surface Owner: State Federal Tribal Private (Name: _____

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)				
Crude Oil	Volume Released (bbls) 20	Volume Recovered (bbls) 20		
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)		
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No		
Condensate	Volume Released (bbls)	Volume Recovered (bbls)		
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)		
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)		

Cause of Release:

A release of oil occurred due to overflow line being opened, oil then released out of an unsecured manway plate. Fluid was released into an impermeable containment. A vacuum truck recovered approximately 20 bbls of oil from the containment. A 48-hour advance notice of containment inspection was provided by email to NMOCD District 2. The containment was visually inspected and was determined to be insufficient. Delineation for deferral will be conducted by a third party contractor.

Page 2 of 3

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?
release as defined by	
19.15.29.7(A) NMAC?	N/A
🗌 Yes 🖾 No	
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
N/A	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \square The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

N/A

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: <u>Adrian Baker</u>	Title: <u>SH&E Coordinator</u>
Signature:Quh	Date:3/13/20
email:Adrian_Baker @xtoenergy.com	Telephone:4322363808
OCD Only	
Received by:	Date:

.

Location:	Hackberry 34 CTB		
Spill Date:	2/29/2020		
	Area 1		
Approximate A	rea =	112.30	cu. ft.
	VOLUME RECOVERED		
Total Crude Oil	=	20.00	bbls
	TOTAL VOLUME OF LEAK		
Total Crude Oil	=	20.00	bbls

TOTAL VOLUME RECOVERED

Total Crude Oil =

.

20.00 bbls