District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural** Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM2013640481
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: BTA Oil Producers, LLC	OGRID: 260297
Contact Name: Bob Hall	Contact Telephone: 432-682-3753
Contact email: bhall@btaoil.com	Incident # (assigned by OCD)
Contact mailing address: 104 S. Pecos St., Midland, TX 79701	***

Location of Release Source

Latitude: 32.06591° Longitude: -103.62886°

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Mesa 8105 # 9, 11, 13, 18 Tank Battery			Tank Battery	Site Type: Tank Batte	ery
Date Release Discovered: 5/12/2020		API# (if applicable) Neares	API# (if applicable) Nearest well: Mesa 8015 JV-P #011H API #30-025-42847		
Unit Letter	Section	Township	Range	County	
N	1	26S	32E	Lea	

					700	
Surface Owne	r: State	□ Federal □ Tr	ribal Private (A	Va m e)

Nature and Volume of Release

Crude Oil	Volume Released (bbls) 45 BBL	Volume Recovered (bbls) 45 BBL
☐ Produced Water		
M Produced water	Volume Released (bbls) 130 BBL	Volume Recovered (bbls) 130 BBL
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	⊠ Yes □ No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
Cause of Release		

The body of a dump valve on the Mesa 18H separator washed out. A total of 175 BBL fluid was released into the secondary containment of the Mesa 9/11/13/18 tank battery that included the Mesa 18H separator.

The volume was determined by measurement of the volume of fluid recovered by vacuum truck. The entire release was contained inside of secondary containment for the tank battery built for the production equipment and tanks for the Mesa 8105 #9, 11, 13, and 18 wells.

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	NRM2013640481
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?			
release as defined by 19.15.29.7(A) NMAC?	The spill volume was greater than 25 BBL, which the NMOCD Rules define as a major			
	release.			
⊠ Yes □ No				
ICALC				
	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? rovided by email distribution of this C-141 Initial Response to NMOCD and BLM personnel			
overseeing the area.	Tovided by email distribution of this e 141 mittal nesponse to Nivided and belvi personnel			
0				
	Initial Response			
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury			
The source of the rele	ease has been stopped.			
	s been secured to protect human health and the environment.			
	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.			
_	ecoverable materials have been removed and managed appropriately.			
	d above have <u>not</u> been undertaken, explain why:			
has begun, please attach	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.			
I hereby certify that the infor	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and			
public health or the environn	required to report and/or file certain release notifications and perform corrective actions for releases which may endanger nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have			
tailed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In				
and/or regulations.	f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws			
Printed Name: Bob Hall	Title: Environmental Manager			
20.100				
Signature: / / Duc	Signature: Date: 5/13/2020			
email: bhall@btaoil.com Telephone: 432-682-3753				
email: bhall@btaoil.com Telephone: 432-682-3753				
OCD Only				
Received by: _Ramona	Marcus Date: 5/15/2020			
	Date: 3/13/2020			