District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Unit Letter

M

Section

05

Township

26S

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM2034559088
District RP	
Facility ID	
Application ID	

### **Release Notification**

#### **Responsible Party**

Responsible Party Marathon Oil Permian LLC	OGRID 372098		
Contact Name Melodie Sanjari	Contact Telephone 575-988-8753		
Contact email msanjari@marathonoil.com	Incident # (assigned by OCD)		
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 822	20		
Location of	Release Source		
Latitude 32.06560374 Longitude (NAD 83 in decima	-103.39695431 l degrees to 5 decimal places)		
Site Name: CAVE LION 5 TB FEDERAL #001H	Site Type Oil & Gas Facility		
Date Release Discovered 11/26/2020	API# (if applicable) 30-025-44087		

# Surface Owner: State Federal Tribal Private (Name: \_\_\_\_\_\_)

Range

35E

#### Nature and Volume of Release

Lea

County

Materia	l(s) Released (Select all that apply and attach calculations or specific	justification for the volumes provided below)
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls) 14.8	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
Cause of Release	·	·

Operator arrived on location to a failure on a 4" threaded T that resulted in the release of approx. 14.8 bbl. of produced water inside of the lined containment. The source was isolated for repairs and as the crew had a pressure wash trailer in-tow, the area was washed and all fluids recovered to prevent slip/trips/falls during the repair process. A 48 hour notice will be sent out prior to a liner integrity inspection.

- 27		-		~
- 43	ann	٠,	0	•
-	uvv	~	•	Ι.
_		_		

Incident ID	NRM2034559088
District RP	
Facility ID	
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release?
19.15.29.7(A) NMAC?	
☐ Yes ⊠ No	
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
	Initial Response
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.
	as been secured to protect human health and the environment.
Released materials ha	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.
☐ All free liquids and re	ecoverable materials have been removed and managed appropriately.
If all the actions describe	d above have <u>not</u> been undertaken, explain why:
has begun, please attach	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
regulations all operators are public health or the environi failed to adequately investig	remation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger ment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have gate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
Printed Name: Mel	lodie Sanjari
Signature: Melod	<u>Lie Sanjari</u> Date: 12/1/2020
email: <u>msanjari@mara</u>	<u>thonoil.com</u> Telephone: <u>575-988-8753</u>
OCD Only	
Received by: Ramona	a Marcus Date: 12/10/2020

#### NRM2034559088

## **Spill Calculation Tool**



	Length (ft.)	Width (ft.)	Avg. Liquid Depth (in.)	% Oil	Total Volume (bbls)	Water Volume (bbls)	Oil Volume (bbls)
Rectangle Area #1	100	40	0.25		14.84	14.84	0.00
Rectangle Area #2					0.00	0.00	0.00
Rectangle Area #3					0.00	0.00	0.00
Rectangle Area #4					0.00	0.00	0.00
Rectangle Area #5					0.00	0.00	0.00
Rectangle Area #6					0.00	0.00	0.00
Rectangle Area #7					0.00	0.00	0.00
Rectangle Area #8					0.00	0.00	0.00
-				Liquid Volume:	14.84	14.84	0.00
	Length (ft.)	Width (ft.)	Avg. Saturated Depth (in.)	% Oil	Total Volume (bbls)	Water Volume (bbls)	Oil Volum (bbls)
	Length (ft.)	Width (ft.)	•	% Oil			
Rectangle Area #1				0%	0.00	0.00	0.00
Rectangle Area #2				0%	0.00	0.00	0.00
Rectangle Area #3				0%	0.00	0.00	0.00
Rectangle Area #4				0%	0.00	0.00	0.00
Rectangle Area #5				0%	0.00	0.00	0.00
Rectangle Area #6				0%	0.00	0.00	0.00
Rectangle Area #7					0.00	0.00	0.00
Rectangle Area #8					0.00	0.00	0.00
				Saturated Volume	0.00	0.00	0.00
<u>Volume R</u>	Recovered and no	t included in Stand	ling Liquid Inputs	. % Oil	Total Volume (bbls)	Water Volume (bbls)	Oil Volumo (bbls)
					Total Volume	Water Volume	Oil Volume