District 1
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NRM2034960665
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: BTA Oil Producers, LLC	OGRID: 260297
Contact Name: Bob Hall	Contact Telephone: 432-682-3753
Contact email: bhall@btaoil.com Incident # (assigned by OCD)	
Contact mailing address: 104 S. Pecos St., Midland, TX 79701	

Location of Release Source

Latitude: 32.38511° Longitude: -103.43559°

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Chiso 14 State 8711 Flowline	Site Type: Oil Well	
Date Release Discovered: 11/28/2020	API# (if applicable) Nearest well: Chiso 14 State 8711 #3H	
	API #30-025-43614	

Unit Letter	Section	Township	Range	County
Р	14	22S	34E	Lea

Surface Owner: State Federal Tribal [oxtimes Private (Name: Merchant Livestock,	PO Box 1105, Eunice, NM 88231)
---	--	--------------------------------

Nature and Volume of Release

Materia	nl(s) Released (Select all that apply and attach calculations or specific	justification for the volumes provided below)	
Crude Oil	Volume Released (bbls) 7 BBL	Volume Recovered (bbls) 0 BBL	
Produced Water	Volume Released (bbls) 12 BBL	Volume Recovered (bbls) 0 BBL	
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	⊠ Yes □ No	
☐ Condensate	Volume Released (bbls)	Volume Recovered (bbls)	
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)	
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)	
Cause of Release		0.4	
Flowline leak.			

The buried flowline was excavated in the vicinity of the leak. Then, additional excavation was conducted in order to reach flowline connections to replace the failed portion of the pipe. Any soil that was wetted by the released fluid has been stockpiled on location.

(See attached spill calculation spreadsheet.)

Received by OCD: 12/3/2020 1:40:10 PM Form C-141 State of New Mexico

Page 2

State of New Mexico
Oil Conservation Division

P	age	2	0	f3
	-			1

Incident ID NRM2034960665

District RP
Facility ID
Application ID

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?		
☐ Yes ⊠ No			
If YES, was immediate noti	ice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?		
	Initial Response		
The responsible par	rty must undertake the following actions immediately unless they could create a safety hazard that would result in injury		
The source of the releas	se has been stopped.		
☐ The impacted area has l	been secured to protect human health and the environment.		
Released materials have	e been contained via the use of berms or dikes, absorbent pads, or other containment devices.		
All free liquids and reco	overable materials have been removed and managed appropriately.		
If all the actions described a	above have not been undertaken, explain why:		
has begun, please attach a	C the responsible party may commence remediation immediately after discovery of a release. If remediation narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			
Printed Name: Bob Hall	Title: Environmental Manager		
Signature:	Date: 12/3/2020		
email: bhall@btaoil.cor	Telephone: 432-682-3753		
OCD Only			
Received by: Ramona M	arcus Date: 12/14/2020_		

Location Chiso 14 State Flowline

API # 30-025-43614 **Spill Date** 11/28/2020

Spill Dimensions

ENTER - Length of Spill	27 feet
ENTER - Width of Spill	27 feet
ENTER - Saturation Depth of Spill	12 inches

ENTER - Porosity Factor 0.15 decimal

Oil Cut - Well Test / Vessel Throughput or Contents

Oil 0.38
Water 0.62
Calculated Oil Cut 0.38

Volume Recovered in Truck / Containment

ENTER - Recovered Oil 0 BBL
ENTER - Recovered Water 0 BBL

Calculated Values

Release of Oil in Soil - Unrecovered 7 BBL
Release of Water in Soil - Unrecovered 12 BBL
Unrecovered Total Release 19 BBL

Calculated Values

Total Release of Oil

Total Release of Water

Total Release

Types of Soil	Porosity Factor
Gravel	0.25
Sand	0.20
Clay/silt/sand Mix	0.15
Clay	0.05
Caliche	0.03
Unknown	0.25

(Length X Width X Depth X 1 ft/12 in) X Porosity 5.615 ft³ / BBL X Oil Cut
(or Water Cut)

calculated

calculated

7 *BBL*

12 *BBL*

19 **BBL**