

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2036337003
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Plains Pipeline, L.P.	OGRID 713291
Contact Name Amber Groves	Contact Telephone 575-200-5517
Contact email algroves@paalp.com	Incident # (assigned by OCD)
Contact mailing address 3112 W. US Hwy 82, Lovington, NM 88260	

Location of Release Source

Latitude 32.640918

Longitude -103.814648

(NAD 83 in decimal degrees to 5 decimal places)

Site Name Plains COG Screwdriver 24 Fed Com 2H	Site Type LACT Unit
Date Release Discovered 12/22/2020	API# (if applicable)

Unit Letter	Section	Township	Range	County
P	24	19S	31E	Eddy

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 20 bbls	Volume Recovered (bbls) 2 bbls
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release


Center piston failure of the triplex pump of the LACT Unit.

Incident ID	nAPP2036337003
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Immediate notification given via e-mail to Jim Griswold, Bradford Billings, Mike Bratcher, Cristina Eads, Robert Hamlet and Victoria Venegas on 12/22/2020.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Amber Groves</u>	Title: <u>Remediation Coordinator</u>
Signature: 	Date: <u>12/28/2020</u>
email: <u>algroves@paalp.com</u>	Telephone: <u>(575)200-5517</u>
<u>OCD Only</u>	
Received by: <u>Ramona Marcus</u>	Date: <u>1/7/2021</u>

Amber L Groves

From: David Guerrero Jr
Sent: Monday, December 28, 2020 9:31 AM
To: Amber L Groves
Cc: Jose C DeLao
Subject: COG Screwdriver Release Justification

Amount lost for the Screwdriver 24 Fed Com 2H release is approximately 20bbbls of crude.

This is based on measurements of release area around the LACT skid and measurement estimates under the producer owned tank liner:

Based on Liquid Spill Calculator

- Average measurements of release area near LACT Skid: 15' x 16' x 1" (12x16x1x.015 = 3.6bbbls)
- Average measurements of release under producer owned liner: 30' x 30' x 1" (30x30x1x.015 = 13.5bbbls)

Based on Soil Calculator

- Average measurement of contaminated soil near LACT Skid: 15' x 16' x 1" @ a 20% Estimated Pore Space = 2.1 bbbls.

Thank you,

DAVID GUERRERO JR
PLAINS ALL AMERICAN
DISTRICT MANAGER, PPN
(432) 202-9397 | (432) 758-8002
DGUERRERO@PAALP.COM