

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals, and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-059-20248

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

BRAVO DOME CO2 GAS UNIT

1. Type of Well
OIL WELL GAS WELL OTHER CO2

8. Well No.
1834-171G

2. Name of Operator
AMOCO PRODUCTION COMPANY

9. Pool name or Wildcat
BRAVO DOME CO2 GAS UNIT

3. Address of Operator
P.O. Box 303, AMISTAD, NEW MEXICO 88410

4. Well Location
Unit Letter G : 1650 Feet From The North Line and 1650 Feet From The East Line
Section 17 Township 18N Range 34E NMPM Union _____ County _____

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4778 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103.

12/2/97
Drill out CIBP @ 2485'.
Spot 35 sacks of Class C cement @ 2542'.

12/3/97
Tag TOC @ 2460'
Circulate well with mud laden fluid
Pressure test 7" casing to 500 psi
Spot 20 sacks Class C cement @ 1953' - 1837'
Spot 5 sacks Class C cement @ 30' - 3'
Cutoff wellhead and anchors 3' below ground level
Cap well with steel plate. Install dry hole marker.
Cover pit and cellar. Clean location
Inspected 1/7/98 - OK RCP

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E. Truhler TITLE Operations Specialist DATE 12/5/97

TYPE OR PRINT NAME B. E. PROCHARD TELEPHONE NO. (505) 374-3053

(This space for State Use)
APPROVED BY R. E. Johnson TITLE DISTRICT SUPERVISOR DATE 1/12/98

CONDITIONS OF APPROVAL, IF ANY: