

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19-15-29 NMAC

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Frontier Field Services, LLC	Contact John Prentiss
Address 65 Mercado St. Durango, CO. 81301	Telephone No. 575-676-3528
Facility Name Maljamar Gas Plant	Facility Type Natural gas processing facility
Surface Owner Frontier Field Services, LLC	Mineral Owner
API No. N/A	

LOCATION OF RELEASE

Unit Letter	Section 14	Township 18S	Range 31E	Feet from the	North/South Line 4,652/1,333	Feet from the	East/West Line 2,533/2,763	County Eddy
-------------	----------------------	------------------------	---------------------	---------------	--	---------------	--------------------------------------	-----------------------

Latitude **32° 75' 43.16" N** Longitude **-103° 84' 19.31" W**

NATURE OF RELEASE

Type of Release Heavy condensate from tank	Volume of Release est. 3bbl to surface and ≤ 6bbl to subsurface	Volume Recovered ~3bbl of free liquid recovered from surface and ~6bbl excavated
Source of Release Tank ran-over	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 6/16/15 @ 13:45 hrs.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones- NMOCD Randy Pair- BLM	
By Whom? Harley Everhart - EHS Technician III	Date and Hour 1/17/15 @ 12:15 hrs.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

RECEIVED

By OCD District 1 at 9:22 am, Jun 23, 2015

Describe Cause of Problem and Remedial Action Taken.*

On 6/16/2015, an oilfield crew discovered a drip-tank running over and a puddle of heavy condensates gathered on the surface. It was determined by Frontier Field Service employee that a grazing cow had used a valve handle to satisfy an itch, while doing so, open the valve feeding the drip tank. The valve was immediately shut and removed to prevent future occurrences. Notifications were made internally to operation's leadership and environmental. Frontier estimated the release to exceed 5bbl and made prompt notifications to NMOCD and BLM.



On 6/17/2015 approximately 3bbl of free liquid was recovered from the surface with a hydrovac truck and disposed at an OCD approved facility.

Describe Area Affected and Cleanup Action Taken.*

BLM requested a meeting on 6.19.2015, to discuss additional remediation procedures should they deem it necessary. Therefore, remediation is suspended until further instructions from BLM.

The cause and conditions of the spill was identified and alleviated. Excavation will commence until TPH, BTEX, and Benzene are below the levels outlined in "NMOCD Guidelines for Remediation of Leaks, Spills, and Releases". Impacted soils will be transported to an OCD approved facility for disposal and the area will be backfilled with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Harley Everhart		Approved by Environmental Specialist: 	
Title: EHS Technician III		Approval Date: 06/23/2015	Expiration Date: 09/25/2015
E-mail Address: heverhart@akaenergy.com		Conditions of Approval: Site samples required. Delineate and remediate as per NMOCD guides. Geotag photographs of remediation required.	
Date: 6/18/2015 Phone: 575-513-4922		Attached <input type="checkbox"/> 22115 1RP-3685	

* Attach Additional Sheets If Necessary

nKJ1517434094
pKJ1517434408