

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico
Energy Minerals and Natural Resources
JUN 11 2015 Oil Conservation Division
RECEIVED 1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Hat Mesa State 31 State #001	Facility Type: Exploration and Production

Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	API No. 30-025-34575
------------------------------------	------------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 31	Township 20S	Range 33E	Feet from the 660	North/South Line North	Feet from the 1980	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.535014° Longitude -103.700780°

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 5.25 bbls	Volume Recovered 4 bbls
Source of Release Circulating Pump	Date and Hour of Occurrence Date and Time unknown	Date and Hour of Discovery 5/28/2015 approx. 4 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Bad connection on circulating pump caused oil to leak. Pumper shut down unit and closed valves. Standing fluids were recovered from ground and pump containment. Connection was repaired.

Describe Area Affected and Cleanup Action Taken.*

Leak affected 56 square feet of well pad within the earthen containment. Impacted area will be investigated and addressed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth		Approved by Environmental Specialist: 	
Title: Assistant Remediation Foreman		Approval Date: 07/14/2015	Expiration Date: 10/14/2015
E-mail Address: ACRuth@basspet.com		Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guides. Geotagged photographs of remediation required.	
Date: 6/10/2015 Phone: 432-661-0571		Attached <input type="checkbox"/> ogrid 260737 1RP-3726	

* Attach Additional Sheets If Necessary

pJXK1519550308

nJXK1519550074