

RECEIVED

By Jamie at 3:46 pm, Sep 22, 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Dusty Wilson
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5771
Facility Name	State P Central Battery	Facility Type	Battery
Surface Owner	State	Mineral Owner	API No. 30-025-12180

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	32	22S	38E					Lea County, NM

Latitude N 32.34449° Longitude W 103.08889°**NATURE OF RELEASE**

Type of Release	Oil and produced water	Volume of Release	6 bbls oil, 15 bbls produced water	Volume Recovered	5 bbls
Source of Release	Gasket failure on the heater treater	Date and Hour of Occurrence	09/04/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, Jamie Keyes, & Tomas Oberding-NMOCD		
By Whom?	Kathy Purvis, NBC International	Date and Hour	09/08/2015		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



Gasket failure on the heater treater caused 6 bbls of oil and 15 bbls of produced water to leak onto the ground, inside the berm. A vacuum truck recovered 5 bbls of fluids and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 15' x 30' on location inside the berm. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:			
Printed Name:	Dusty Wilson	Approved by Environmental Specialist:	
Title:	Environmental Advisor	Approval Date:	09/22/2015
		Expiration Date:	11/22/2015
E-mail Address:	Dusty.Wilson@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	9/21/15	Discrete site samples required. Delineate and remediate per NMOCD guidelines.	IRP 3871
Phone:	(432) 685-5771	Geotagged photos of remediation required.	

* Attach Additional Sheets if Necessary

pJXK1526556708

nJXK1526556571