

RECEIVED

By JKeyes at 8:37 am, Oct 22, 2015

APPROVED

By JKeyes at 8:37 am, Oct 22, 2015



Stipulations:

Ensure BLM concurrence/approval.

Mallon 34-16

CLOSURE REPORT

Release Date: 6/14/2015

UL/ Sec 34, T19 south, R34 east, Lea County NM

API # 30-025-32818

October 19, 2015

Prepared by:

Environmental Department
Diversified Field Service, Inc.
206 West Snyder
Hobbs, NM 88240
Phone: (575)964-8394
Fax: (575)393-8396

Table of Contents

- 1 Introduction
- 2 Site Activities
- 3 Conclusion

APPENDICES

Appendix I – Initial C-141

Appendix II – Site Photographs

Appendix III – Site Diagram

Appendix IV – Laboratory Analyses/Field Data/Groundwater Search

Appendix V – Final C-141

Mallon 34-16

1 INTRODUCTION

Cimarex Energy has retained Diversified Field Service, Inc. (DFSI) to address environmental issues for the site detailed herein.

The site is located west of Hobbs, NM, in Lea County. The leak site resulted from a hole developing in an oil tank. The impacted area is inside a lined firewall of the battery. Approximately 345 bbls of oil was released, and 290 bbls recovered. A C-141 was submitted to the NMOCD on July 23, 2015. The C-141 is attached.

2 SITE ACTIVITIES

On July 30, 2015, DFSI personnel delineated 3 sample points of the leak area. Each sample was tested for chloride levels as well as BTEX. The BTEX samples were performed using a Mini Rae Photoionization Detector (PID). Clean samples were taken to a lab for confirmation. The results are attached.

On October 12, DFSI personnel returned to the location to begin excavation. The contaminated soil inside the bermed facility was removed to 2' BGS. All contaminated material was hauled to an approved NM state disposal. Fresh caliche was brought in for backfill, and the berms were knocked down. After backfill, the area was rolled and made even with the existing pad.

Because there was no eminent danger of groundwater impact or threat to life, further delineation or removal of soil will occur at the time the facility is abandoned.

Photos can be viewed in Appendix II.

3 CONCLUSION

DFSI, on behalf of Cimarex, respectfully requests the closure of the regulatory file for the site.

Appendix I

INITIAL FORM C-141

Diversified Field Service, Inc.
206 W. Snyder
Hobbs, NM 88240
(575) 964-8394

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Mallon 34-16	Facility Type	production
Surface Owner	fed	Mineral Owner	
		API No.	30-025-32818

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	34	19S	34E					Lea

Latitude 32.614819 Longitude -103.554779

NATURE OF RELEASE

Type of Release	oil	Volume of Release	345 bbls	Volume Recovered	290 bbls
Source of Release	tank	Date and Hour of Occurrence	06/14/15	Date and Hour of Discovery	06/14/15
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones/Shelly Tucker		
By Whom?	Christine Alderman	Date and Hour	07/23/2015 10:30 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A hole developed in the bottom of a steel oil tank. During initial cleanup a breach in the liner was discovered and the tank and liner has been removed.

Describe Area Affected and Cleanup Action Taken.*

An environmental consultant will be onsite to delineate and a work plan will be submitted for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Christine Alderman	Approved by Environmental Specialist:		
Title: ESH Supervisor	Approval Date:	Expiration Date:	
E-mail Address: calderman@cimarex.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7/23/15	Phone: 432-853-7059		

* Attach Additional Sheets If Necessary

Appendix II

SITE PHOTOS



Mallon 34-16

PHOTO PAGE

10/19/15



Lease sign marking location



Spill area inside bermed facility



Spill area inside bermed facility



Spill area inside bermed facility



Excavating contaminated area to 2' BGS



Excavating contaminated area to 2' BGS; knocking down berms



Finishing excavation of contaminated area



Completely excavated contaminated area



Excavated area backfilled with fresh caliche



Using roller to even out area parallel to pad



Completed location



Completed location

Appendix III

SITE MAP

Diversified Field Service, Inc.
206 W. Snyder
Hobbs, NM 88240
(575) 964-8394

Site Diagram

Cimarex, Mallon 34-16

Sec. 34 T19S R34E

Lea County, NM

Drafted By: Lance Crenshaw, 7-28-15

0 0.00275 0.0055 0.011 Miles

Legend



Misc_points

Types


-  Electrical Box
-  Power Pole
-  Headers
-  Injection
-  Pumpjacks
-  Tanks
-  Valves
-  Other
-  Soil Bores
-  sample_pts
-  Source

Pipeline





Type


-  Above Ground Line
-  Buried Line

Spill

-  <all other values>

Spill_Media

-  Oil and Produced H2O
-  Oil
-  Other
-  Produced Water



Spill Area:
6,766 sq. ft.

Lance Crenshaw
GIS Technician

Soil Remediation and Ground Water Remediation
Environmental Assessments
Regulatory Compliance



Environmental

DFS

Services

Office: 575-964-8394

Fax: 575-964-8396

Cell: 575-441-2359

Email: lcrenshaw@diversifiedfsi.com

Source: Esri, DigitalGlobe, GeoEye, i-cu
swisstopo, and the GIS User Community

Appendix IV

LABORATORY ANALYSES

Diversified Field Service, Inc.
206 W. Snyder
Hobbs, NM 88240
(575) 964-8394

Diversified Environmental Services

Company Name:	CIMAREX
Location Name:	MALLON 34 FED#16

SP Date: 7/30/2015
Rel Date:

[illegible]

	Lab Confirmation Sample
	Field Sampling
	Needs Delineation and confirmation samples



PHONE (575) 393-2326 ° 101 E. MARLAND ° HOBBS, NM 88240

August 05, 2015

CHRISTINE ALDERMAN
CIMAREX ENERGY CO.-MIDLAND
600 N. MARIENFELD ST, SUITE 600
MIDLAND, TX 79701

RE: MALLON 34 FED #16

Enclosed are the results of analyses for samples received by the laboratory on 07/30/15 14:33.

Cardinal Laboratories is accredited through Texas NELAP under certificate number T104704398-13-5. Accreditation applies to drinking water, non-potable water and solid and chemical materials. All accredited analytes are denoted by an asterisk (*). For a complete list of accredited analytes and matrices visit the TCEQ website at www.tceq.texas.gov/field/qa/lab_accred_certif.html.

Cardinal Laboratories is accredited through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2	Haloacetic Acids (HAA-5)
Method EPA 524.2	Total Trihalomethanes (TTHM)
Method EPA 524.4	Regulated VOCs (V1, V2, V3)

Accreditation applies to public drinking water matrices.

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

A handwritten signature in black ink that reads "Celey D. Keene". The signature is written in a cursive style with a large, stylized 'C' and 'K'.

Celey D. Keene
Lab Director/Quality Manager

Analytical Results For:

CIMAREX ENERGY CO.-MIDLAND
CHRISTINE ALDERMAN
600 N. MARIENFELD ST, SUITE 600
MIDLAND TX, 79701
Fax To: UNK-NOWN

Received: 07/30/2015
Reported: 08/05/2015
Project Name: MALLON 34 FED #16
Project Number: NONE GIVEN
Project Location: NOT GIVEN

Sampling Date: 07/30/2015
Sampling Type: Soil
Sampling Condition: Cool & Intact
Sample Received By: Judy Garcia

Sample ID: SP. 1 @ 7' (H501984-01)

BTEX 8021B			mg/kg		Analyzed By: MS				
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	08/04/2015	ND	1.92	96.2	2.00	0.311	
Toluene*	<0.050	0.050	08/04/2015	ND	1.95	97.4	2.00	0.357	
Ethylbenzene*	<0.050	0.050	08/04/2015	ND	2.10	105	2.00	0.478	
Total Xylenes*	<0.150	0.150	08/04/2015	ND	5.55	92.4	6.00	0.104	
Total BTEX	<0.300	0.300	08/04/2015	ND					

Surrogate: 4-Bromofluorobenzene (PID) 111 % 85.6-137

Chloride, SM4500Cl-B			mg/kg		Analyzed By: AP				
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	176	16.0	08/03/2015	ND	400	100	400	3.92	

TPH 8015M			mg/kg		Analyzed By: MS				
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	07/31/2015	ND	202	101	200	3.18	
DRO >C10-C28	<10.0	10.0	07/31/2015	ND	182	91.0	200	4.59	

Surrogate: 1-Chlorooctane 111 % 47.2-157

Surrogate: 1-Chlorooctadecane 120 % 52.1-176

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



Celey D. Keene, Lab Director/Quality Manager

Analytical Results For:

CIMAREX ENERGY CO.-MIDLAND
CHRISTINE ALDERMAN
600 N. MARIENFELD ST, SUITE 600
MIDLAND TX, 79701
Fax To: UNK-NOWN

Received: 07/30/2015
Reported: 08/05/2015
Project Name: MALLON 34 FED #16
Project Number: NONE GIVEN
Project Location: NOT GIVEN

Sampling Date: 07/30/2015
Sampling Type: Soil
Sampling Condition: Cool & Intact
Sample Received By: Judy Garcia

Sample ID: SP. 1 @ 8' (H501984-02)

BTEx 8021B		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	08/04/2015	ND	1.92	96.2	2.00	0.311	
Toluene*	<0.050	0.050	08/04/2015	ND	1.95	97.4	2.00	0.357	
Ethylbenzene*	<0.050	0.050	08/04/2015	ND	2.10	105	2.00	0.478	
Total Xylenes*	<0.150	0.150	08/04/2015	ND	5.55	92.4	6.00	0.104	
Total BTEx	<0.300	0.300	08/04/2015	ND					

Surrogate: 4-Bromofluorobenzene (PID) 112 % 85.6-137

Chloride, SM4500CI-B		mg/kg		Analyzed By: AP					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	240	16.0	08/03/2015	ND	400	100	400	3.92	

TPH 8015M		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	08/03/2015	ND	207	103	200	1.74	
DRO >C10-C28	<10.0	10.0	08/03/2015	ND	179	89.3	200	5.83	

Surrogate: 1-Chlorooctane 109 % 47.2-157

Surrogate: 1-Chlorooctadecane 114 % 52.1-176

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



Celey D. Keene, Lab Director/Quality Manager

Analytical Results For:

CIMAREX ENERGY CO.-MIDLAND
CHRISTINE ALDERMAN
600 N. MARIENFELD ST, SUITE 600
MIDLAND TX, 79701
Fax To: UNK-NOWN

Received: 07/30/2015
Reported: 08/05/2015
Project Name: MALLON 34 FED #16
Project Number: NONE GIVEN
Project Location: NOT GIVEN

Sampling Date: 07/30/2015
Sampling Type: Soil
Sampling Condition: Cool & Intact
Sample Received By: Judy Garcia

Sample ID: SP. 2 @ 2' (H501984-03)

BTX 8021B		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	08/04/2015	ND	1.92	96.2	2.00	0.311	
Toluene*	<0.050	0.050	08/04/2015	ND	1.95	97.4	2.00	0.357	
Ethylbenzene*	<0.050	0.050	08/04/2015	ND	2.10	105	2.00	0.478	
Total Xylenes*	<0.150	0.150	08/04/2015	ND	5.55	92.4	6.00	0.104	
Total BTX	<0.300	0.300	08/04/2015	ND					

Surrogate: 4-Bromofluorobenzene (PID) 114 % 85.6-137

Chloride, SM4500CI-B		mg/kg		Analyzed By: AP					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	272	16.0	08/03/2015	ND	400	100	400	3.92	

TPH 8015M		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	08/03/2015	ND	207	103	200	1.74	
DRO >C10-C28	<10.0	10.0	08/03/2015	ND	179	89.3	200	5.83	

Surrogate: 1-Chlorooctane 107 % 47.2-157

Surrogate: 1-Chlorooctadecane 120 % 52.1-176

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



Celey D. Keene, Lab Director/Quality Manager

Analytical Results For:

CIMAREX ENERGY CO.-MIDLAND
CHRISTINE ALDERMAN
600 N. MARIENFELD ST, SUITE 600
MIDLAND TX, 79701
Fax To: UNK-NOWN

Received: 07/30/2015
Reported: 08/05/2015
Project Name: MALLON 34 FED #16
Project Number: NONE GIVEN
Project Location: NOT GIVEN

Sampling Date: 07/30/2015
Sampling Type: Soil
Sampling Condition: Cool & Intact
Sample Received By: Judy Garcia

Sample ID: SP. 2 @ 3' (H501984-04)

BTX 8021B		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	08/04/2015	ND	1.92	96.2	2.00	0.311	
Toluene*	<0.050	0.050	08/04/2015	ND	1.95	97.4	2.00	0.357	
Ethylbenzene*	<0.050	0.050	08/04/2015	ND	2.10	105	2.00	0.478	
Total Xylenes*	<0.150	0.150	08/04/2015	ND	5.55	92.4	6.00	0.104	
Total BTX	<0.300	0.300	08/04/2015	ND					

Surrogate: 4-Bromofluorobenzene (PID) 112 % 85.6-137

Chloride, SM4500CI-B		mg/kg		Analyzed By: AP					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	320	16.0	08/03/2015	ND	400	100	400	3.92	

TPH 8015M		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	08/03/2015	ND	207	103	200	1.74	
DRO >C10-C28	<10.0	10.0	08/03/2015	ND	179	89.3	200	5.83	

Surrogate: 1-Chlorooctane 97.7 % 47.2-157

Surrogate: 1-Chlorooctadecane 103 % 52.1-176

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



Celey D. Keene, Lab Director/Quality Manager

Analytical Results For:

CIMAREX ENERGY CO.-MIDLAND
CHRISTINE ALDERMAN
600 N. MARIENFELD ST, SUITE 600
MIDLAND TX, 79701
Fax To: UNK-NOWN

Received: 07/30/2015
Reported: 08/05/2015
Project Name: MALLON 34 FED #16
Project Number: NONE GIVEN
Project Location: NOT GIVEN

Sampling Date: 07/30/2015
Sampling Type: Soil
Sampling Condition: Cool & Intact
Sample Received By: Judy Garcia

Sample ID: SP. 3 @ 5' (H501984-05)

BTEx 8021B		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	08/04/2015	ND	1.92	96.2	2.00	0.311	
Toluene*	<0.050	0.050	08/04/2015	ND	1.95	97.4	2.00	0.357	
Ethylbenzene*	<0.050	0.050	08/04/2015	ND	2.10	105	2.00	0.478	
Total Xylenes*	<0.150	0.150	08/04/2015	ND	5.55	92.4	6.00	0.104	
Total BTEx	<0.300	0.300	08/04/2015	ND					

Surrogate: 4-Bromofluorobenzene (PID) 116 % 85.6-137

Chloride, SM4500CI-B		mg/kg		Analyzed By: AP					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	<16.0	16.0	08/03/2015	ND	400	100	400	3.92	

TPH 8015M		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	08/03/2015	ND	207	103	200	1.74	
DRO >C10-C28	38.9	10.0	08/03/2015	ND	179	89.3	200	5.83	

Surrogate: 1-Chlorooctane 108 % 47.2-157

Surrogate: 1-Chlorooctadecane 112 % 52.1-176

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



Celey D. Keene, Lab Director/Quality Manager

Analytical Results For:

CIMAREX ENERGY CO.-MIDLAND
CHRISTINE ALDERMAN
600 N. MARIENFELD ST, SUITE 600
MIDLAND TX, 79701
Fax To: UNK-NOWN

Received: 07/30/2015
Reported: 08/05/2015
Project Name: MALLON 34 FED #16
Project Number: NONE GIVEN
Project Location: NOT GIVEN

Sampling Date: 07/30/2015
Sampling Type: Soil
Sampling Condition: Cool & Intact
Sample Received By: Judy Garcia

Sample ID: SP. 3 @ 6' (H501984-06)

BTX 8021B		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	08/04/2015	ND	1.92	96.2	2.00	0.311	
Toluene*	<0.050	0.050	08/04/2015	ND	1.95	97.4	2.00	0.357	
Ethylbenzene*	<0.050	0.050	08/04/2015	ND	2.10	105	2.00	0.478	
Total Xylenes*	<0.150	0.150	08/04/2015	ND	5.55	92.4	6.00	0.104	
Total BTX	<0.300	0.300	08/04/2015	ND					

Surrogate: 4-Bromofluorobenzene (PID) 114 % 85.6-137

Chloride, SM4500CI-B		mg/kg		Analyzed By: AP					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	<16.0	16.0	08/03/2015	ND	400	100	400	3.92	

TPH 8015M		mg/kg		Analyzed By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	08/03/2015	ND	207	103	200	1.74	
DRO >C10-C28	<10.0	10.0	08/03/2015	ND	179	89.3	200	5.83	

Surrogate: 1-Chlorooctane 114 % 47.2-157

Surrogate: 1-Chlorooctadecane 135 % 52.1-176

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



Celey D. Keene, Lab Director/Quality Manager

Notes and Definitions

ND	Analyte NOT DETECTED at or above the reporting limit
RPD	Relative Percent Difference
**	Samples not received at proper temperature of 6°C or below.
***	Insufficient time to reach temperature.
-	Chloride by SM4500Cl-B does not require samples be received at or below 6°C Samples reported on an as received basis (wet) unless otherwise noted on report


Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



Celey D. Keene, Lab Director/Quality Manager



Page 9 of 9

(575) 393-2326 FAX (575) 393-2476

[illegible]



New Mexico Office of the State Engineer **Water Column/Average Depth to Water**

No records found.

Basin/County Search:

County: Lea

PLSS Search:

Section(s): 34, 33, 35

Township: 19S

Range: 34E

Appendix V

FINAL C-141

Diversified Field Service, Inc.
206 W. Snyder
Hobbs, NM 88240
(575) 964-8394

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Mallon 34-16	Facility Type	Production

Surface Owner	Federal	Mineral Owner		Lease No.	30-025-32818
---------------	---------	---------------	--	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	34	19S	34E					Lea

Latitude 32.614819 Longitude -103.554779

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	345 bbls	Volume Recovered	290 bbls
Source of Release	Tank	Date and Hour of Occurrence	6-14-15	Date and Hour of Discovery	6-14-15
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones/Shelly Tucker		
By Whom?	Christine Alderman	Date and Hour	7-23-15 10:30 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A hole developed in the bottom of a steel oil tank. During initial cleanup a breach in the liner was discovered and the tank and liner was removed.

Describe Area Affected and Cleanup Action Taken.* The area affected was inside a soil berm. DCSI Services dug up the contaminated soil to 2' BGS. The berms were knocked down and fresh caliche was brought in for backfill. The area was then leveled with a roller and made part of the existing pad. All contaminated soil was hauled to an approved NM state disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION		
Printed Name: Christine Alderman	Approved by District Supervisor:		
Title: ESH Supervisor	Approval Date:	Expiration Date:	
E-mail Address: calderman@cimarex.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 10/19/15	Phone: 432-853-7059		

* Attach Additional Sheets If Necessary