

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company OCCIDENTAL PERMIAN LTD.	Contact TONY AGUILAR
Address 1017 W. Stanolind Road, Hobbs	Telephone No. (575)397-8251
Facility Name NORTH HOBBS UNIT RCF/WIB	Facility Type OIL AND GAS PRODUCTION FACILITY

Surface Owner Occidental Permian LTD.	Mineral Owner HOBBS (G-SA)	Lease No.
---------------------------------------	----------------------------	-----------

LOCATION OF RELEASE

Unit Letter H	Section 25	Township 18-S	Range 37-E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	---------------

Latitude 32°43'14.96" Longitude 103°11'59.65"



NATURE OF RELEASE

Type of Release Gas	Volume of Release 115 MCF	Volume Recovered 0
Source of Release RCF FLARE SSM EVENTS	Date and Hour of Occurrence 10/19/2015 2:05:00 PM	Date and Hour of Discovery 10/19/2015 2:05:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom? NA	Date and Hour NA	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* Cause: FLARED AT THE NORTH HOBBS UNIT REJECTION COMPRESSOR FACILITY (RCF). A-TRAIN DOWN DUE TO SUCTION VALVE FAIL. EOR Remedial Action Taken: A-TRAIN WAS DEPRESSURIZED AND RESTARTED BACK UP.		
Describe Area Affected and Cleanup Action Taken.* ALL GAS BURNED AT FLARE.		

RECEIVED

By JKeyes at 3:33 pm, Oct 22, 2015

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: TONY AGUILAR		Approved by District Supervisor: 	
Title: <u>HES Specialist</u>	Approval Date: <u>10/22/2015</u>	Expiration Date: <u>///</u>	
E-mail Address: RAYMOND_AGUILAR@OXY.COM	Conditions of Approval:		Attached <input type="checkbox"/>
Date: <u>10-20-15</u> Phone: (575)397-8251	///		1RP 3937

* Attach Additional Sheets If Necessary

nJXK1529555802
pJXK1529555916