

**RECEIVED**

By JKeyes at 9:08 am, Nov 12, 2015

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.**Release Notification and Corrective Action****OPERATOR**☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Dusty Wilson
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5771
Facility Name	South Mattix Yeso Satellite	Facility Type	Satellite
Surface Owner	Doom	Mineral Owner	
		API No.	30-025-21307

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	15	24S	37E					Lea County, NM

Latitude N 32.21246° Longitude W 103.14967°**NATURE OF RELEASE**

Type of Release	Oil and Produced water	Volume of Release	1 bbl oil, 9 bbls produced water	Volume Recovered	0 bbls
Source of Release	Stress/fatigue of a 4" fiberglass production trunk line	Date and Hour of Occurrence	10/05/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, Jamie Keyes-NMOCD		
By Whom?	Kathy @ BBC International Inc.	Date and Time	10/19/2015		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Stress/fatigue of a 4" fiberglass production trunk line caused 1 bbl of oil and 9 bbls of produced water to leak onto the ground. No fluids were recovered and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 90' x 100' off location on the road and in the pasture. Remediation will be completed in accordance with the remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:

Printed Name: Dusty Wilson

Title: Environmental Advisor

E-mail Address: Dusty\_Wilson@oxy.com

Date: 11-9-15

Phone: (432) 685-5771

Approved by Environmental Specialist:

Approval Date: 11/12/2015

Expiration Date: 01/12/2016

Conditions of Approval:

Discrete site samples required. Delineate and remediate per NMOCD guidelines.

Geotagged photos of remediation required.

Attached ☐

IRP 3974

\* Attach Additional Sheets If Necessary