

## Bratcher, Mike, EMNRD

---

**From:** Everhart, Harley <heverhart@akaenergy.com>  
**Sent:** Monday, October 19, 2015 9:24 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Busch, Greg; Calderon, Joe; Prentiss, John  
**Subject:** Cedar Brakes Spill\_3685\_10.19.15  
**Attachments:** Cedar Break 12inch Lateral\_Sample Location\_10.15.2015.pdf; Cedar Breaks\_Remediation\_Lab Results\_10.15.15.pdf

**Importance:** High

Mr. Bratcher,

Re: Cedar Brakes Spill\_3685

Per your requested, Frontier Field Services remove 20 cubic yards of additional soil on the SW Wall. Attached is the location of Sample #7 and Cardinal Labs Analytical results.

The cause and conditions of the spill was identified and alleviated. Excavation is now complete, TPH, BTEX, and Benzene are below the levels outlined in "NMOCD Guidelines for Remediation of Leaks, Spills, and Releases". All impacted soils was transported to an OCD approved facility for disposal. This area will now be backfilled with clean soil and a final report with supporting documentation will be sent upon completion.

Should you have any comments or concerns, please do not hesitate to contact me.

Respectfully,

*Harley Everhart*

EH&S Compliance

(575) 677-5140 - Direct  
(575) 513-4922 - Cell  
(575) 676-2401 - Fax  
[heverhart@akaenergy.com](mailto:heverhart@akaenergy.com)



**CONFIDENTIALITY NOTICE:**

This email, including attachments, may include confidential and/or proprietary information, and may be used only by the person or entity to which it is addressed. Please do not read, copy or disseminate this communication unless you are the intended addressee. If you have received this communication in error, please permanently delete and call (575) 677-5140 immediately and ask to speak to the sender of this communication. Also, please notify immediately via email that you have received this message in error.