RECEIVED State of New Mexico By JKeyes at 3:17 pm, Nov 18, 2015 Energy Minerals and Natural Re

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Santa Fe, INIVI 87505													
Release Notification and Corrective Action													
						OPERATOR 🗍 Ini] Initia	al Report	\boxtimes	Final Repor	
Name of Company EOG Resources Inc.						Contact Zane Kurtz						^	
Address 5509 Champions Drive, Midland, TX 79706						Telephone No. (432) 686-3667							
Facility Name Red Hills North Unit 706						Facility Type Water Injection Well							
Surface Owner BLM Mineral Owner						r BLM API No. 30-025-32814							
				LOCA	τιο	N OF REJ	LEASE						
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/We	st/West Line County				
1	7	258	34E	1830		South	660	Ea	st	Lea			
Latitude 32.1427						Longitude	-103 5026						
NATURE OF RELEASE													
Type of Release Produced water Volume of Release 20 BBLs										e Recovered		Is	
Source of Release						Volume of Release 20 BBLs Volume Recovered 0 BBLs Date and Hour of Occurrence Date and Hour of Discovery							
4" pipeline rupture Was Immediate Notice Given?						6/26/2015 at approximately 7:00am 6/26/2015 at approximately 9:30am							
Was Immedi	ate Notice (No 🗌 Not Red	guired	If YES, To Whom?								
By Whom?						Date and Hour							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
🗌 Yes 🛛 No													
If a Watercourse was Impacted, Describe Fully.*													
APPROVED													
By JKeyes at 3:17 pm, Nov 18, 2015													
Describe Cause of Problem and Remedial Action Taken.*													
Describe Cat			ulai Actio	II Taken.									
		ted near the w	vellhead r	uptured approximat	tely 10	feet below gr	ound surface. The	e line was	uncovere	ed by excava	ation ar	id repaired	
upon discove	ry.												
Describe Area Affected and Cleanup Action Taken.*													
Impacted soi	was excava	ated and dispo	osed of in	a landfill. A 20 mil	liner	was placed in	areas where chlor	ide conce	ntrations	extended de	eper th	an 4 feet	
Impacted soil was excavated and disposed of in a landfill. A 20 mil liner was placed in areas where chloride concentrations extended deeper than 4 feet below ground surface. The excavated area was backfilled with cleans soil and revegetated.													
I harabu carti	fy that the i	nformation ai	ven obove	e is true and comple	ate to t	he hest of my	knowledge and w	nderstand	that nurs	uent to NM		lec and	
				nd/or file certain re									
				ce of a C-141 repor									
				v investigate and repotence of a C-141 repotence of									
		vs and/or regu							101 0		itii uiij		
2 1							OIL CONS	SERVA	TION	DIVISIC	<u>N</u>		
Signature:						A 1							
Printed Name: Zane Kurtz						Approved by Environmental Specialist:							
Title: Sr. Environmental Rep						Approval Date: 11/18/2015 Expiration			Date: ///				
E-mail Addre	ess: Zan	e_KurTZ	resauces.	(IN	^P Conditions of Approval:				Attached				
	-18-15		431.425.20	23	· /// 1RP 3704								
Attach Addi	ional Shee	ts If Necess		~	I	•				•			

* Attach Additional Sheets If Necessary