

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Dusty Wilson
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5771
Facility Name	State CM Btry	Facility Type	Battery
Surface Owner	Mineral Owner	API No.	30-025-01574

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
NE ¼	2	18S	33E					Lea County, NM

Latitude N 32.78167° Longitude W 103.63077°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	50 bbl oil, 60 bbls produced water	Volume Recovered	100 bbls
Source of Release	Heater treater manway plate gasket blew out	Date and Hour of Occurrence	10/28/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, Jamie Keyes-NMOCD		
By Whom?	Kathy @ BBC International Inc.	Date and Time	10/29/2015		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					

**RECEIVED**

By Kellie Jones at 10:13 am, Nov 23, 2015

Describe Cause of Problem and Remedial Action Taken.\*



Heater treater manway plate gasket blew out leaking 50 bbls of oil and 60 bbls of produced water. A vacuum truck recovered 100 bbls of fluid and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 25' x 100' on location inside the berm and 50' x 100' outside of the berm both on and off the location. Remediation will be completed in accordance with the remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Dusty Wilson	Approval Date: 11/23/2015	Expiration Date: 01/23/2016
Title: Environmental Advisor	Conditions of Approval:	
E-mail Address: Dusty.Wilson@oxy.com	Site samples required. Delineate and remediate as per MNOCDC guides. Geotag photographs of remediation required.	Attached <input type="checkbox"/> 1RP-3990
Date: 11/18/2015	Phone: (432) 685-5771	

\* Attach Additional Sheets If Necessary

nKJ1532736778  
pKJ1532736969