<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## Energy Minerals and Natural

**RECEIVED** State of New Mexi By JKeyes at 12:29 pm, Dec 11, 2015

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## **Release Notification and Corrective Action**

						OPERA'	ΓOR			al Report 🔲 Fin	al Report	
						Contact Randy Gladden, Production Foreman						
						<b>Telephone No.</b> 575-513-9463						
Facility Na	<b>me</b> Bilbrey	33 Federal	Com 3H			Facility Ty	pe Oil					
Surface Owner Federal Mineral Owner						r Federal API N			o 30-025-41806			
	LOCATION OF RELEASE											
Unit Letter   Section   Township   Range   Feet from the   No.						rth/South Line Feet from the East/West Line				County		
J 33 21S 32E 2600					5	South 1350			East Lea			
<b>Latitude:</b> 32.4350951 N <b>Longitude:</b> 103.6755529 W												
NATURE OF RELEASE												
Type of Release Produced Water Release										Recovered 11 BBLS PW & .5		
Source of Release Water line						1			BBL oil  Date and	Date and Hour of Discovery		
Source of Release Water line									12/3/2015			
Was Immediate Notice Given?   ☐ Yes ☐ No ☐ Not Required						If YES, To Whom?						
						Jim Amos BLM Kelly Jones OCD						
By Whom? Jim Huerta, Assistant Production Foreman						Date and Hour						
, , , , , , , , , , , , , , , , , , , ,							BLM 12/10/15 @ 11:16 am					
Was a Watercourse Reached?							OCD 12/10/15 @ 11:23 am  If YES, Volume Impacting the Watercourse					
Was a Watercourse Reacned?  ☐ Yes ☐ No						N/A						
If a Waterco	ourse was II	npacted, Des	scribe Ful	ly.*								
Describe Cause of Problem and Remedial Action Taken.*												
Produced water was released from water line due to corrosion. Wells producing to this line were immediately shut in to prevent further release. Clamp was												
placed on the	corroded sp	oot then the p	ermanent i	repairs were made	e.							
Describe Ar	ea Affected	and Cleanu	Action 7	Taken.*								
12 BBLS of j	produced wa	ter and .5 BE	BL of oil w	as released affect						ed water and .5 BBL of		
				ease originated fro ill be contacted fo			ning between the	heater ti	reater and v	vater knockout. All rele	ased	
Tiulu Telliallie	d on pad. E.	nvnonmentar	agency w	in be contacted it	or remedi	ation.						
										suant to NMOCD rules		
										eases which may endan		
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state.	or local lav	vs and/or regu	ılations.		1		OH 60::	ODD I		PH HOLON		
Signature: Sarah Gallegos-Troublefield						OIL CONSERVATION DIVISION						
Signature. Sur mir gimego y-11 omrej tem						Jan L byer						
Printed Name: Sarah Gallegos-Troublefield						Approved by Environmental Specialist:						
Title: Field Admin Support						Approval Date: 12/11/2015						
Anto A loid A Rullin Support						Приоти Вис.						
E-mail Address: Sarah.Gallegos-Troublefield@dvn.com						Conditions of Approval:				Attached		
Date: 12/10/2015 Phone: 575.748.1864						Discrete site samples required. Delineate and				1RP 4011		
Attach Additional Sheets If Necessary						Temperature per 1 mile CB guidennes.				nJXK1534544732 pJXK1534544888		







