

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation	Contact Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name NEDU 503W	Facility Type: Injection Well

Surface Owner State	Mineral Owner	API No. 30-025-06473
---------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter K	Section 10	Township 21S	Range 37E	Feet from the 2080'	North/South Line FSL	Feet from the 2080'	East/West Line FWL	County Lea
------------------	---------------	-----------------	--------------	------------------------	-------------------------	------------------------	-----------------------	---------------

Latitude N32.4918556 Longitude W103.1526871

NATURE OF RELEASE

Type of Release: produced water	Volume of Release 65 barrels of produced water	Volume Recovered 60 barrels of produced water
Source of Release: Fiberglass Line	Date and Hour of Occurrence Unknown 11/21/2015	Date and Hour of Discovery 11/21/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones (NMOCD)	
By Whom? Bruce Baker	Date and Hour 11/23/2015	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Kellie Jones at 8:20 am, Dec 11, 2015

Describe Cause of Problem and Remedial Action Taken.*

The 2 inch nipple corroded on the main trunk line resulting in the loss of fluid. A line was isolated and repaired. A vacuum truck was dispatched to pick-up standing fluid.

Describe Area Affected and Cleanup Action Taken.*

Majority of the release was contained on the lease road with approximately 1,000 square feet of pasture affected. The release has been mapped and was delineated on 12/8/2015 and samples were sent to commercial laboratory for analysis.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Approved by Environmental Specialist: <i>Kelly Jones</i>	
Title: Environmental Technician	Approval Date: 12/11/2015	Expiration Date: 02/11/2016
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/9/2015 Phone: (432) 631-6982	Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation recommended.	IRP-4009

* Attach Additional Sheets If Necessary

nKJ1534531167
pKJ1534531312