

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
By JKeyes at 7:28 am, Mar 09, 2016
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company DCP Midstream, LP	Contact Jon Bebbington	
Address 10 Desta Drive, Suite 400 West	Telephone No. 432-620-4207; 432-413-3601	
Facility Name V-3-7-2 Sweet Gas Pipeline	Facility Type Gas Pipeline	
Surface Owner Smith Ranch	Mineral Owner	API No.

LOCATION OF RELEASE

Unit Letter	Section 32	Township 19S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.61789 Longitude -103.79030

NATURE OF RELEASE

Type of Release: Condensate/ Gas	Volume of Release 6 bbls condensate, 2.33 MCF Gas	Volume Recovered
Source of Release Gas Pipeline	Date and Hour of Occurrence unk	Date and Hour of Discovery 2-19-2016 12:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

DCP Midstream's V-3-7-2 8-inch steel sweet gas pipeline was reported to have a blowing leak. DCP's construction crew was dispatched to depressurize and repair the line.

Describe Area Affected and Cleanup Action Taken.*

An estimated six bbls of condensate leaked from the line and impacted a 30' x 50' area on private land. DCP will vacuum up free liquids and remediate the area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jon D. Bebbington	Approved by Environmental Specialist: 	
Title: Princ. Environmental Engineer	Approval Date: 03/09/2016	Expiration Date: 05/09/2016
E-mail Address: jdbbebbington@dcpmidstream.com	Conditions of Approval: Discrete site samples only. Delineate and remediate per NMOCD guidelines. Geotagged photos of remediation recommended.	Attached <input type="checkbox"/> IRP 4203
Date: 3-7-16 Phone: 432-620-4207		

* Attach Additional Sheets If Necessary

nJXK1606926695
pJXK1606926828