

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 9:46 am, Mar 10, 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	MK Stewart Tank Battery	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	30-025-22432
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	28	23S	37E					Lea County, NM

Latitude N 32.27069° Longitude W 103.16246°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	70 bbls oil, 5 bbls produced water	Volume Recovered	37 bbls
Source of Release	Hole in fire tube on heater treater	Date and Hour of Occurrence	02/20/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jamie Keyes-NMOCD, Shelly Tucker-BLM		
By Whom?	Cliff Brunson @ BBC International	Date and Hour	02/21/2016 @ 4:25 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A hole in the fire tube caused 70 bbls of oil and 5 bbls of produced water to spill inside the berm. A vacuum truck recovered 27 bbls of oil and the fire tube was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 140' x 20' on location inside the berm. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:					
Printed Name:	Casey Summers	Approved by Environmental Specialist: 			
Title:	NM Environmental Advisor	Approval Date:	03/10/2016	Expiration Date:	05/10/2016
E-mail Address:	Casey.Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>	
Date:	3-9-16	Phone:	(575) 513-8289	Discrete site samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/IRP 4206 approval.	

* Attach Additional Sheets If Necessary

nJXK1607034900
pJXK1607035089