<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexic RECEIVED Energy Minerals and Natural

By JKeyes at 8:45 am, Jun 01, 2016

Form C-141 Revised August 8, 2011

accordance with 19.15.29 NMAC.

pJXK1615331445

Oil Conservation Divis 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action	Release	Notification:	and Correct	ive Action
--	---------	---------------	-------------	------------

						OPERA'							
Name of Company: Cimarex Energy						Contact: Gloria Garza							
Address: 600 N Marienfeld Ste 600 Midland TX						Telephone No. 432-234-3204							
Facility Name: Double X 25 Federal No. 4H						Facility Type: Well							
Surface Owner: Federal Mineral Owner					wner	r API No.: 30-025-40690							
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the		/South Line	Feet from the	East/V	Vest Line	County			
C	25	24S	32E	330	FNL	, Boden Bine	2055	FWL		Lea			
Latitude: 32.11' 42" NLongitude: -103. 37' 48" W													
NATURE OF RELEASE													
Type of Relea	se: Produc	ed Water	*******			Volume of Release: 10 BBLS Volume Recovered: 5 B					BBLS	j	
Source of Release; Well					•	5					four of Discovery:		
						5/28/2016 8:30 AM 5/28/2016 8:30 AM							
Was Immedia	ite Notice C		Yes [	No Not Re	quired	If YES, To Whom? Shelly Tucker/Jamic Keyes							
By Whom? G	loria Garza					Date and Hour: 5/29/2016 4:00 PM							
Was a Watero		hed?				If YES, Vo	lume Impacting t	he Wate	ercourse.				
			Yes 🛚	] No									
If a Watercou	rse was Im	nacted. Descri	ibe Fully.*	*									
		,	•										
Describe Cau	se of Proble	em and Remo	dial Action	n Taken *						, ,			
We were har	ving issues	s at the well.	the float	switch did kill t	he we	ll but the uni	t kept flowing c	ausing	the stuffin	g box to b	urn up	releasing	
We were having issues at the well, the float switch did kill the well but the unit kept flowing causing the stuffing box to burn up releasing fluid out of stuffing box containment.													
	Ü												
D													
Describe Area Affected and Cleanup Action Taken.*  We will remediate the impacted soil.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws and/or regulations.  OIL CONSERVATION DIVISION													
	- A			_			OIL CON	<u>SERV</u>	ATION	DIVISIO	<u>N(</u>		
Signature: (MUTULU (NWTULL)													
Approved by Environmental Specialist:													
Printed Name: Gloria Garza													
m'd Equa						A	06/01/201	6	Cumination '	08/01	/2016	ŀ	
Title: ESH S	pecialist					Approval Dat	е;		Expiration 1	Date:			
E-mail Addre	ss: ggarzad	@cimarex.con	n			Conditions of	Approval:			1	$\Box$		
	opmin	-y						e and re	mediate pe	Attached			
Date: 5/29/16 Phone: 432-234-3204 Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/													
Attach Addit	ional Shee	ets If Necess	arv		-	approval.				nJXK161	533137	<i>12.</i>	