

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 3:09 pm, Jun 09, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: WARBLER STATE COM #002Y	Facility Type: Battery

Surface Owner: State	Mineral Owner: State	API No. 30-025-42904
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 28	Township 21S	Range 31E	Feet from the 195'	North/South Line North	Feet from the 2010'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.456445 Longitude 103.579041

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 100bbls Produced Water	Volume Recovered: 98bbls Produced Water
Source of Release: Produced Water Tank	Date and Hour of Occurrence: 06-07-2016 9:00 pm	Date and Hour of Discovery: 06-07-2016 9:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jaime Keyes - NMOCD / Amber Groves - SLO	
By Whom? Robert Grubbs Jr.	Date and Hour: 06-08-2016 12:51 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a failure in the Pressure Control Switch. The Pressure Control Switch has been replaced.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr		Approved by Environmental Specialist: 	
Title: Sr. Environmental Coordinator		Approval Date: 06/09/2016	Expiration Date: 08/09/2016
E-mail Address: rgrubbs@concho.com		Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.	
Date: June 9, 2016 Phone: 432-683-7443		Attached <input type="checkbox"/> IRP 4307	

* Attach Additional Sheets If Necessary

nJXK1616154408
pJXK1616154491