REVIEWED

By Kristen Lynch at 8:28 am, Sep 21, 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## **Release Notification and Corrective Action**

			KCIC	asc mount	auo		DOD	Cuon			<b>7</b> 4-5	
Name of Company Dayon Energy Production Company						OPERATOR					Final Report	
Name of Company Devon Energy Production Company Address 6488 Seven Rivers Hwy Artesia, NM 88210						Contact Danny Velo, Production Foreman  Telephone No. 575.703.3360						
Facility Na			111 00210		Facility Type Oil Well							
•	•											
Surface Owner Federal Mineral Owner						r Federal API No				30-025-2786	<u>i1</u>	
LOCATION OF RELEASE												
Unit Letter Section Township Range Feet from the Nor 15 17S 32E 710					North	h/South Line Feet from the 2310		East/West Line FEL		County Lea		
Latitude: 32.8292618 Longitude: -103.7532425												
NATURE OF RELEASE												
Type of Release							Volume of Release   Volume Recovered					
Produced Wa	iter (PW) ar			27BBLS PW & 10BBLS Oil 0BBLS								
Source of Re								Hour of Disco	very			
Gasket on fire tube flange Was Immediate Notice Given?							7/15/2016 @ 9:00AM 7/15/2016 @ 9:00AM If YES, To Whom?					
Yes No Not Required												
By Whom?						Date and Hour						
Ky Scott, Assistant Production Foreman						NMOCD-Mike Bratcher 7/15/2016@11:00AM						
Was a Watercourse Reached?						BLM-Shelly Tucker 7/15/2016@11.02AM  If YES, Volume Impacting the Watercourse						
Yes No						N/A	orume impacting	, the vv	ater course			
If a Waterco	ourse was I	mpacted, Des	cribe Full	y.*								
Describe Cause of Problem and Remedial Action Taken.*												
27 BBLS of PW and 10BBLS oil was released due to leaking gasket on fire tube flange on heater treater. Isolated the line and transferred line to a test												
heater to prevent further release. Well is currently shut in. Repairs were made.												
D "1 4	A 66 4 1	1.01	A 41 7	7.1 4								
		l <b>and Cleanu</b> r BBLS oil was			ket on fi	re tube flange	e on heater treater	OBBL	S were reco	vered. Release	d fluid flowed in	
a Southeaster	n direction.	The approximation	mate total	area affected on	pad was	30ft by 24ft.					4ft by 24ft on the	
Southeast sid	e. An envii	conmental con	npany will	be contacted for	remedia	ation.						
							knowledge and u					
							nd perform correc					
							arked as "Final R					
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state,	or local lav	ws and/or regu	ılations.									
a. 0				OIL CONSERVATION DIVISION								
Signature: $\mathcal{D}$	ana De			V . 9								
Printed Name	e: Dana De	eLaRosa			Approved by Environmental Specialist:							
									11/21/2	016		
Title: Field Admin Support						Approval Da	te: 9/21/2016		Expiration	Date: 11/21/2	010	
E-mail Address: dana.delarosa@dvn.com						NMOCD Accepts Conditions of Approval: Discrete Samples Only  Attached						
Z AMA A A STEED OF THE CHILD WAS A STREET OF THE CHILD						Notify NMOCD prior to all sampling events to					_	
Date: 7/18/2016 Phone: <b>575.746.5594</b>						allow for witnessing 1RP 4446						

## 27BBLS Oil & 10 BBLS Oil\_7,15,16 Lynx Federal 1 WGS\_1984\_Web\_Mercator\_Auxiliary\_Sphere Prepared by: Dana DeLaRosa Map is current as of: 18-Jul-2016 devon



