REVIEWED

By Kristen Lynch at 2:32 pm, Nov 02, 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action													
						OPERAT	OR	[	Initial	Report	х□	Final Report	
Name of Company Matador Production Company						Contact Catherine Green							
Address 500 N Main St Ste 1 Roswell NM 88201						Telephone No.575-623-6601							
Facility Name Young Deep Unit 23						Facility Type Oil Well							
Surface Owner Mineral Owner						r Federal API No.30-025-29896							
LOCATION OF RELEASE													
Unit Letter J	Section 18S	Township 09	Range 32E	Feet from the 2310	North S	n/South Line	Feet from the 1980	East/V E	West Line County Lea				
Latitude_32.3761017 Longitude103.7692566													
NATURE OF RELEASE  Type of Release Fire in Heater Treater  Volume of Release 35 bbls  Volume Recovered 8 bbls													
Type of Release Fire in Heater Treater Source of Release Heater Treater								Volume Recovered 8 bbls  Date and Hour of Discovery 9:20pm Feb.					
Source of Kelease fleater Treater						9pm Feb. 6, 2016 6, 2				2016			
Was Immediate Notice Given?  x☐ Yes ☐ No ☐ Not						If YES, To Whom? Catherine Green							
Required		AL	_ 103 [			Cambridge Grown							
By Whom? Clay Stevens						Date and Hour 9:20pm Feb. 6, 2016							
Was a Watercourse Reached?  ☐ Yes x☐ No						If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.* Fire occurred in Heater Treater at approximately 9pm Feb. 6, 2016. Well was turned off, 8 bbls of fluid was recovered after fire was extinguished. Soil samples were collected in and out of berm. Contaminated soil was properly disposed of, and containment was rebuilt. Heater Treater was removed from service and replaced. Burnt gas meters were removed and replaced.													
Describe Area Affected and Cleanup Action Taken.*													
Area in and outside of berm was sampled, contaminated soil was removed and replaced. Process equipment that was damaged by fire was removed and replaced. Berm was rebuilt.													
regulations a public health should their or or the environ	ll operators or the envi operations h nment. In a	are required tronment. The nave failed to	o report are acceptance acceptanc	e is true and comp nd/or file certain r ce of a C-141 report investigate and r otance of a C-141	release of ort by the remedia	notifications and NMOCD matter than the notion of the noti	nd perform correct parked as "Final Rition that pose a thr	tive act eport" d eat to gr	ions for relations for relations for relations from the count water	eases which ieve the op- r, surface w	n may en erator of vater, hu	ndanger f liability ıman health	
						OIL CONSERVATION DIVISION							
Signature: Catherine Green						Approved by Environmental Specialist:							
Printed Name Catherine Green:						11/2/2016							
Title: Regulatory Analyst						Approval Date: 11/2/2016 Expiration Date: N/A			A				
E-mail Address: cgreen@matadorresources.com						Conditions of Approval: N/A Attached   Attached							
Date: Oct. 2	25, 2016	Pho	one: 575-6	23-6601									

<sup>\*</sup> Attach Additional Sheets If Necessary