

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Airacuda Federal #002H	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-40407
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter B	Section 31	Township 25S	Range 33E	Feet from the 330	North/South Line North	Feet from the 1980	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.0934601 Longitude -103.609169

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 42 bbls	Volume Recovered: 15 bbls
Source of Release: Sight Glass	Date and Hour of Occurrence: June 23, 2017 10:00 am	Date and Hour of Discovery: June 23, 2017 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu - NMOCD / Ms. Tucker - BLM	
By Whom? Rebecca Haskell	Date and Hour: June 23, 2017 1:41 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

**RECEIVED**

By Olivia Yu at 1:26 pm, Jul 03, 2017

Describe Cause of Problem and Remedial Action Taken.\*

The release was due to a broken sight glass on a heater treater. The sight glass was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The release occurred within the lined facility with overspray in the adjacent pasture. A vacuum truck was dispatched to remove all freestanding fluids. The gravel and remaining oil will be taken to disposal. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>by</i>	
Title: Senior HSE Coordinator	Approval Date: 7/3/2017	Expiration Date:
E-mail Address: rhaskell@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 26, 2017 Phone: 432-683-7443	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

\* Attach Additional Sheets If Necessary

NMOCD requests confirmatory  
laboratory analyses of discrete soil  
samples from impacted pasture area.

1RP-4743

nOY1718449237

pOY1718449915