From: Shoemaker, Mike

To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD; Shelly Tucker (stucker@blm.gov); Yu, Olivia, EMNRD

Cc: Fulks, Brett; Menoud, Denise

Subject: RE: Spill Notification for the Shire 22 Fed 1H (now Arabian 30-19 FC 1H-Spill 1)

Date: Thursday, November 16, 2017 3:20:02 PM

Attachments: image001.png

C-141 - Arabian 30-19 FC 1H - Spill 1 10.18.17.doc

Crystal,

Please see the revised C-141 with the corrected API # for the Arabian 30-19 Fed Com 1 (API#30-025-43176). Per our conversation I have also included Olivia on the e-mail chain and will include her on all correspondence going forward for this release.

If you need any additional information please let me know.

Thanks,

Mike Shoemaker EHS Representative

Devon Energy Corporation

6488 Seven Rivers Highway Artesia, New Mexico 88210 575-746-5566 Office 575-513-5035 Mobile



From: Shoemaker, Mike

Sent: Thursday, November 02, 2017 7:39 PM

To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; Shelly Tucker (stucker@blm.gov) <stucker@blm.gov>

Cc: Fulks, Brett (Brett.Fulks@dvn.com) <Brett.Fulks@dvn.com>; Menoud, Denise

(Denise.Menoud@dvn.com) <Denise.Menoud@dvn.com>

Subject: Spill Notification for the Shire 22 Fed 1H (now Arabian 30-19 FC 1H-Spill 1)

Good Evening,

Attached please find the Initial C-141 and GIS Image for the 396 bbls produced water released at the Arabian 30-19 FC 1H-Spill 1(Initially reported as the Shire 22 Fed 1H-see e-mail chain below) on 10.18.17.

Per your recent guidance on C-141s I have updated the naming conventions and pads that these locations have been associated to. My updates can be found in red in the e-mail chain below. If you have any questions please let me know.

Please note that the API number tagged for the Arabian 30-19 FC 1H would indicate that this release should be sent to Olivia in District 1. I originally notified the District 2 based off of the APIs # for the locations that were originally tagged for this release (All 30-015-XXXXX). Based on the GPS coordinates for where the actual release occurred I believe it will stay with

the District 2 Office as it is just inside Eddy County but if this is incorrect please let me know and I will adjust it accordingly.

Thank you,

Mike Shoemaker EHS Representative

Devon Energy Corporation

6488 Seven Rivers Highway Artesia, New Mexico 88210 575-746-5566 Office 575-513-5035 Mobile



From: Shoemaker, Mike

Sent: Thursday, October 19, 2017 5:46 PM

To: Weaver, Crystal, EMNRD <<u>Crystal.Weaver@state.nm.us</u>>; Bratcher, Mike, EMNRD <<u>mike.bratcher@state.nm.us</u>>; Shelly Tucker (<u>stucker@blm.gov</u>) <<u>stucker@blm.gov</u>>

Cc: Fulks, Brett (<u>Brett.Fulks@dvn.com</u>) <<u>Brett.Fulks@dvn.com</u>>

Subject: Spill Notification for the Shire 22 Fed 1H and the Snapping 2 State 9

Good Evening,

Devon had the following two releases which occurred simultaneously at 11:46 PM on 10/18/17. The two incidents are described below.

- 1. Shire 22 Fed 1H (API # 30-015-43222) now Arabian 30-19 FC 1H-Spill 1
 - a. The following GPS coordinates were taken at the point of the release (Lat:32.114514° N, Long: -103.758858°W) ½ mile south of the Shire 22 FED 1 H-During rigging up of layflat hose a victrolic end connector was removed from hose in order to fit hose under cattle guard. When the contract company reassembled the end to the hose they failed to tighten the clamp bolts. After hydro testing the line to 100 PSI they began the frac job. During stage 2 the victrolic connection blew out of the hose. Approximately 396 bbls of produced water was released with 240 bbls of produced water being recovered.
- 2. Snapping 2 State 9 H (API # 30-015-43023) now Arabian 30-19 FC 1H-Spill 2 (this was also updated on C-141 to reflect that it is in better proximity to the Shire rather than the Snapping)
 - a. The following GPS coordinates were taken at the point of the release
 (Lat:32.091466° N, Long: -103.757313°W updated to Lat:32.102724° N, Long:
 -103.7757986°W original coordinates were incorrect. The coordinates in the C-141
 reflect this update also) 600′ west of Snapping 2 State 9 H During rigging up of
 layflat hose a victrolic end connector was removed from hose in order to fit hose
 under cattle guard. When the contract company reassembled the end to the hose

they failed to tighten the clamp bolts. After hydro testing to 100 PSI they began the frac job. During stage 2 the victrolic connection blew out of the hose. Approximately 397 bbls of produced water was released with 0 bbls of produced water being recovered.

An initial C-141 will be completed and sent to the NMOCD and BLM. If you have any additional question please let me know.

Thanks,

Mike Shoemaker EHS Representative

Devon Energy Corporation

6488 Seven Rivers Highway Artesia, New Mexico 88210 575-746-5566 Office 575-513-5035 Mobile



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.