From: Groves, Amber

To: Yu, Olivia, EMNRD; Zack Thomas; Ben J. Arguijo

Cc: <u>Billings, Bradford, EMNRD; Trinity</u>

Subject: RE: Closure Request Merit 32 DM St. Com #1H

Date: Thursday, December 7, 2017 12:20:47 PM

Attachments: image004.png

image006.png image007.png image008.png image001.png

Good Afternoon,

NMSLO agrees with NMOCD on closure of this release.

Thank you,

Amber Groves

Remediation Specialist
Field Operations Division
(575)392-3697
(575)263-3209 cell
New Mexico State Land Office
2827 N. Dal Paso Suite 117
Hobbs, NM 88240

*The New Mexico State Land Office will be closed from 12/22/2017 at 1pm - 01/01/2018. The office will reopen on 01/02/2018. Happy Holidays!

CONFIDENTIALITY NOTICE - This e-mail transmission, including all documents, files, or previous e-mail messages attached hereto, may contain confidential and/or legally privileged information. If you are not the intended recipient, or a person responsible for delivering it to the intended recipient, you are hereby notified that you must not read this transmission and that any disclosure, copying, printing, distribution, or use of any of the information contained in and/or attached to this transmission is STRICTLY PROHIBITED. If you have received this transmission in error, please immediately notify the sender and delete the original transmission and its attachments without reading or saving in any manner. Thank you.

From: Yu, Olivia, EMNRD [mailto:Olivia.Yu@state.nm.us]

Sent: Tuesday, October 31, 2017 2:59 PM

To: Zack Thomas <zthomas@mewbourne.com>; Ben J. Arguijo <ben@trinityoilfieldservices.com>;

Groves, Amber <agroves@slo.state.nm.us>

Cc: Billings, Bradford, EMNRD < Bradford. Billings@state.nm.us>; Trinity

<todd@trinityoilfieldservices.com>

Subject: RE: Closure Request Merit 32 DM St. Com #1H

Mr. Thomas:

Please note that there is an error in the date at the bottom of page 2 of the closure report.

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **1RP-4724** closed. This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Like approval from NMSLO is required. Please see the attachment for your records.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Zack Thomas [mailto:zthomas@mewbourne.com]

Sent: Tuesday, October 24, 2017 3:46 PM

To: Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us >; Ben J. Arguijo < ben@trinityoilfieldservices.com >;

Groves, Amber <agroves@slo.state.nm.us>

Cc: Billings, Bradford, EMNRD < Bradford.Billings@state.nm.us; Trinity

<todd@trinityoilfieldservices.com>

Subject: Closure Request Merit 32 DM St. Com #1H

Olivia,

Attached is the remediation summary along with the final C141. Let me know if there are any more concerns. Thanks

3. Thomas

Zack Thomas

Environmental Rep. Mewbourne Oil Company PO Box 5270 Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252

(575) 602-2188

Email: zthomas@Mewbourne.com



From: Yu, Olivia, EMNRD [mailto:Olivia.Yu@state.nm.us]

Sent: Thursday, October 19, 2017 9:16 AM **To:** Zack Thomas; Ben J. Arguijo; Groves, Amber

Cc: Billings, Bradford, EMNRD; Trinity

Subject: RE: Backfill Request - Merit 32 DM St. Com #1H (1RP-4724)

Mr. Thomas:

Will a closure report summarizing the remedial work completed not be submitted for 1RP-4724? If not, a short synopsis along with optimally georeferenced and dated photo documentation of the remediation are still required.

Thanks, Olivia

From: Zack Thomas [mailto:zthomas@mewbourne.com]

Sent: Tuesday, October 17, 2017 10:38 AM

To: Ben J. Arguijo

ben@trinityoilfieldservices.com; Groves, Amber agroves@slo.state.nm.us

Cc: Yu, Olivia, EMNRD < <u>Olivia.Yu@state.nm.us</u>>; Billings, Bradford, EMNRD < <u>Bradford.Billings@state.nm.us</u>>; Trinity < <u>todd@trinityoilfieldservices.com</u>>

Subject: RE: Backfill Request - Merit 32 DM St. Com #1H (1RP-4724)

Olivia,

Attached is the Final C141.

3. Thomas

Zack Thomas

Environmental Rep. Mewbourne Oil Company PO Box 5270 Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252

(575) 602-2188

Email: zthomas@Mewbourne.com



From: Ben J. Arguijo [mailto:ben@trinityoilfieldservices.com]

Sent: Thursday, October 12, 2017 4:11 PM

To: Groves, Amber

Cc: Yu, Olivia, EMNRD; Billings, Bradford, EMNRD; Trinity; Zack Thomas **Subject:** Re: Backfill Request - Merit 32 DM St. Com #1H (1RP-4724)

Thank you, Ms. Groves.

Ben J. Arguijo Environmental Project Manager Trinity Oilfield Services P.O. Box 2587 Hobbs, NM 88241 (575)390-7208 ben@trinityoilfieldservices.com

On Thu, Oct 12, 2017 at 3:05 PM, Groves, Amber <agraves@slo.state.nm.us> wrote: Good Afternoon,

NMSLO agrees with NMOCD on backfill approval.

Thank you,



Amber_Groves

Remediation Specialist
Field Operations Division

(575)392-3697 (575)263-3209 cell New Mexico State Land Office 2827 N. Dal Paso Suite 117 Hobbs, NM 88240

.....

CONFIDENTIALITY NOTICE - This e-mail transmission, including all documents, files, or previous e-mail messages attached hereto, may contain confidential and/or legally privileged information. If you are not the intended recipient, or a person responsible for delivering it to the intended recipient, you are hereby notified that you must not read this transmission and that any disclosure, copying, printing, distribution, or use of any of the information contained in and/or attached to this transmission is STRICTLY PROHIBITED. If you have received this transmission in error, please immediately notify the sender and delete the original transmission and its attachments without reading or saving in any manner. Thank you.

From: Ben J. Arguijo [mailto:ben@trinityoilfieldservices.com]

Sent: Friday, October 06, 2017 8:33 AM

To: Yu, Olivia, EMNRD < <u>Olivia. Yu@state.nm.us</u>>

Cc: Billings, Bradford, EMNRD < <u>Bradford.Billings@state.nm.us</u>>; Groves, Amber < <u>agroves@slo.state.nm.us</u>>; Trinity < <u>todd@trinityoilfieldservices.com</u>>; Zack Thomas

< <u>zthomas@mewbourne.com</u>>

Subject: Re: Backfill Request - Merit 32 DM St. Com #1H (1RP-4724)

Yes, the facility will be lined separately.

Thank you.

Ben J. Arguijo Environmental Project Manager Trinity Oilfield Services P.O. Box 2587 Hobbs, NM 88241 (575)390-7208 ben@trinityoilfieldservices.com

On Fri, Oct 6, 2017 at 7:59 AM, Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us > wrote:

Mr. Arguijo:

Thank you for your patience. Backfill approval is granted for 1RP-4724. To clarify, will the tank battery and pump be lined separately?

Like approval from NMSLO required.

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Ben J. Arguijo [mailto:ben@trinityoilfieldservices.com]

Sent: Friday, September 22, 2017 1:34 PM

To: Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us>

Cc: Billings, Bradford, EMNRD < <u>Bradford.Billings@state.nm.us</u>>; Groves, Amber < <u>agroves@slo.state.nm.us</u>>; Trinity < <u>todd@trinityoilfieldservices.com</u>>; Zack Thomas

<<u>zthomas@mewbourne.com</u>>

Subject: Re: Backfill Request - Merit 32 DM St. Com #1H (1RP-4724)

Olivia,

Auger holes were advanced in the same spots as the original Floor #2 and Floor #3 samples. We had marked the locations with a GPS, but the actual sample spots were still visible the day we augered.

Sample Wall #15b was collected approximately 2 feet from the original Wall #15 sample. There was simply a single dirty spot in that wall, which is actually attributable to a drip (non-reportable and distinct from the 1RP-4724 release) from the end of one of the risers that had connected the circulating pump and the adjacent facility to the piping in the former battery. We removed the circulating pump, risers, and approximately 20 feet of the pipes and excavated the underlying soil, including the areas of Wall #15 and Wall #15b.

I was not present for the sampling event, and, upon speaking with my Tech, I have learned that Wall #15b was actually collected at floor level (approximately 1.75'). So, there is a typo in the table I submitted last week, in which I had listed the sample depth as 1'. An updated copy of the data table is attached, along with an updated Sample Location Map. I apologize for any confusion.

Thanks.

Ben

Ben J. Arguijo Environmental Project Manager Trinity Oilfield Services P.O. Box 2587 Hobbs, NM 88241 (575)390-7208 ben@trinityoilfieldservices.com

On Fri, Sep 22, 2017 at 7:33 AM, Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us > wrote:

Good morning Mr. Arguijo:

Thank you for the additional delineation documentation for 1RP-4724. A couple of

questions:

- 1. Where were the Floor #2, Floor #3, and Wall 15 samples taken? Please provide a scaled map updated with the recent sample locations.
- 2. Are there additional samples at greater depths for the Wall 15 location?

Thanks, Olivia

From: Ben Arguijo [mailto:ben@trinityoilfieldservices.com]

Sent: Thursday, September 21, 2017 6:31 PM

To: Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us >

Cc: Billings, Bradford, EMNRD < <u>Bradford.Billings@state.nm.us</u>>; Groves, Amber < <u>agroves@slo.state.nm.us</u>>; Trinity < <u>todd@trinityoilfieldservices.com</u>>; Zack Thomas < <u>zthomas@mewbourne.com</u>>

Subject: Re: Backfill Request - Merit 32 DM St. Com #1H (1RP-4724)

Olivia,

Just following up on this. Mewbourne would like to get the release closed ASAP so they can begin rebuilding the tank battery.

Thank you.

Ben

Ben J. Arguijo Environmental Project Manager Trinity Oilfield Services & Rentals, LLC (575)390-7208

On Sep 12, 2017, at 2:25 PM, Ben J. Arguijo < ben@trinityoilfieldservices.com > wrote:

Olivia,

Attached please find an updated soil chemistry data table and the most recent laboratory analytical report.

Thank you.

Ben

Ben J. Arguijo Environmental Project Manager Trinity Oilfield Services P.O. Box 2587 Hobbs, NM 88241 (575)390-7208

ben@trinityoilfieldservices.com

On Mon, Sep 11, 2017 at 9:37 AM, Ben J. Arguijo < ben@trinityoilfieldservices.com> wrote:

Olivia,

As we discussed in your office last Wednesday, we utilized an auger to further delineate Floor #2 and Floor #3 on Tuesday, 9/5. We were able to obtain clean samples and advanced both of the boreholes an additional 5 feet for confirmation. Laboratory analytical results are pending.

We will be removing the recirculating pump adjacent to Wall #15 today or tomorrow in order to facilitate further excavation and sampling in that area.

If possible, we would like to begin installing the liner and backfilling by the end of this week.

I will send you copies of the lab reports from the additional sampling once they are available, along with an updated soil chemistry data table.

Thank you.

Ben

Ben J. Arguijo Environmental Project Manager Trinity Oilfield Services P.O. Box 2587 Hobbs, NM 88241 (575)390-7208 ben@trinityoilfieldservices.com

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com