Office	State of New Mexico	Form C-103
District I Energy, N 1625 N. French Dr., Hobbs, NM 88240	Minerals and Natural Resources	May 27, 2004 WELL API NO.
District II *	NSERVATION DIVISION	30-025-34849
District III 122	20 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd Aztec NM 87410	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	· · · · · · · · · · · · · · · · · · ·	o. State on & das Lease No.
SUNDRY NOTICES AND REP		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERIPROPOSALS.)		Eunice Monument South Unit
	Other	8. Well Number 709
2. Name of Operator XTO Energy Inc.		9. OGRID Number 005380
3. Address of Operator		10. Pool name or Wildcat
200 N. Loraine, Suite 800, Midland, Texas 79701		Eunice Monument Grayburg San Radio
4. Well Location		0001(1900
Unit LetterK:_1330_feet from	theSouth_ line and2421	feet from theWestline
	21-S Range 36-E NMPM	Lea County
11. Elevation 3574' GL	(Show whether DR, RKB, RT, GR, etc.	
Pit or Below-grade Tank Application or Closure		
Pit type Steel Depth to Groundwater 200' Dista	nce from nearest fresh water well 1000+	Distance from nearest surface water 1000+
·		onstruction Material
12 Check Appropriate B	ox to Indicate Nature of Notice,	Report or Other Data
		Report of Other Data
NOTICE OF INTENTION T		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND A		
TEMPORARILY ABANDON	= 1	<del>-</del>
PULL OR ALTER CASING  MULTIPLE CO	OMPL CASING/CEMEN	T JOB
OTHER:	X OTHER:	erio de la companya della companya della companya de la companya de la companya della companya
10 5 1 1 1 1 1		
		d give pertinent dates, including estimated date
of starting any proposed work). SEE RULI		d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
of starting any proposed work). SEE RULI or recompletion.	E 1103. For Multiple Completions: At	
of starting any proposed work). SEE RULF or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20").	E 1103. For Multiple Completions: At pump. MI & rack up 2 7/8" WS.  ##, J-55 ST&C (Nominal ID is 6.456" & dr	ttach wellbore diagram of proposed completion
of starting any proposed work). SEE RULF or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. Po	E 1103. For Multiple Completions: At pump. MI & rack up 2 7/8" WS.  ##, J-55 ST&C (Nominal ID is 6.456" & dr  OH w/ WS & tools.	trach wellbore diagram of proposed completion rift ID is 6.331") to CIBP @ 3900'. Knock CIBP to
of starting any proposed work). SEE RULF or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20").	E 1103. For Multiple Completions: At pump. MI & rack up 2 7/8" WS.  ##, J-55 ST&C (Nominal ID is 6.456" & dr  OH w/ WS & tools.	trach wellbore diagram of proposed completion rift ID is 6.331") to CIBP @ 3900'. Knock CIBP to
of starting any proposed work). SEE RULF or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spf log ran in April 2000 for correlation purposes 1) 3752' (1') 3 holes	E 1103. For Multiple Completions: At pump. MI & rack up 2 7/8" WS.  ##, J-55 ST&C (Nominal ID is 6.456" & dr  OH w/ WS & tools.	trach wellbore diagram of proposed completion rift ID is 6.331") to CIBP @ 3900'. Knock CIBP to
of starting any proposed work). SEE RULF or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spf log ran in April 2000 for correlation purposes I) 3752' (1') 3 holes II) 3770' (1') 3 holes	E 1103. For Multiple Completions: At pump. MI & rack up 2 7/8" WS.  ##, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.	trach wellbore diagram of proposed completion rift ID is 6.331") to CIBP @ 3900'. Knock CIBP to
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spf log ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  II) 3770' (1') 3 holes  III) 3778-90(12') 36 holes	E 1103. For Multiple Completions: At pump. MI & rack up 2 7/8" WS.  ##, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.	trach wellbore diagram of proposed completion rift ID is 6.331") to CIBP @ 3900'. Knock CIBP to
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spf log ran in April 2000 for correlation purposes  I) 3752' (1') 3 holes  II) 3770' (1') 3 holes  III) 3778-90(12') 36 holes  IV) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes	E 1103. For Multiple Completions: At pump. MI & rack up 2 7/8" WS.  ##, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.	trach wellbore diagram of proposed completion rift ID is 6.331") to CIBP @ 3900'. Knock CIBP to
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spf log ran in April 2000 for correlation purposes  I) 3752' (1') 3 holes  II) 3770' (1') 3 holes  III) 3778-90(12') 36 holes  IV) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes  Total (38') 114 holes	E 1103. For Multiple Completions: At pump. MI & rack up 2 7/8" WS.  #, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  E(120 deg phase). Perf following Grayburg	trach wellbore diagram of proposed completion rift ID is 6.331") to CIBP @ 3900'. Knock CIBP to
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spf log ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  II) 3770' (1') 3 holes  III) 3778-90(12') 36 holes  IV) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes  Total (38') 114 holes  With existing perfs (3792-3923 (255 holes)), total number	E 1103. For Multiple Completions: At pump. MI & rack up 2 7/8" WS. 0#, J-55 ST&C (Nominal ID is 6.456" & dr DH w/ WS & tools. (120 deg phase). Perf following Grayburg of holes is 369. RD Gray Wireline.	rift ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spf log ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  II) 3770' (1') 3 holes  III) 3778-90(12') 36 holes  IV) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes  Total (38') 114 holes  With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production	pump. MI & rack up 2 7/8" WS.  "#, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  "(120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load I	triach wellbore diagram of proposed completion with ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spf log ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  II) 3770' (1') 3 holes  III) 3778-90(12') 36 holes  IV) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes  Total (38') 114 holes  With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production 5) RU Cudd. Pump 5000 gallons 15% NEFE & diverter in Attempt to achieve 5 bpm. Monitor backside for commun	pump. MI & rack up 2 7/8" WS.  "#, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  "(120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load in 5 stages per the attached pumping schedu	rift ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spf log ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  II) 3770' (1') 3 holes  III) 3778-90(12') 36 holes  IV) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes  Total (38') 114 holes  With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production 5) RU Cudd. Pump 5000 gallons 15% NEFE & diverter in Attempt to achieve 5 bpm. Monitor backside for commun 6) Flowback well to tank with steel lines.	pump. MI & rack up 2 7/8" WS.  "#, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  "(120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load in 5 stages per the attached pumping schedu	rift ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PG 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spl log ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  II) 3770' (1') 3 holes  III) 3778-90(12') 36 holes  IV) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes  Total (38') 114 holes  With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production 5) RU Cudd. Pump 5000 gallons 15% NEFE & diverter in Attempt to achieve 5 bpm. Monitor backside for commun 6) Flowback well to tank with steel lines.  7) Once well is dead, release packer & TOH w/ WS.	pump. MI & rack up 2 7/8" WS.  "#, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  "(120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load in 5 stages per the attached pumping schedulication. RD Cudd.	trach wellbore diagram of proposed completion with ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL  Dackside with 2% KCL. Set packer @ +/- 3710'. le. Maximum treating pressure should be 4000 psi.
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spf log ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  II) 3770' (1') 3 holes  III) 3778-90(12') 36 holes  IV) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes  Total (38') 114 holes  With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production 5) RU Cudd. Pump 5000 gallons 15% NEFE & diverter in Attempt to achieve 5 bpm. Monitor backside for commun 6) Flowback well to tank with steel lines.	pump. MI & rack up 2 7/8" WS.  "#, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  "(120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load in 5 stages per the attached pumping schedulication. RD Cudd.	trach wellbore diagram of proposed completion with ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL  Dackside with 2% KCL. Set packer @ +/- 3710'. le. Maximum treating pressure should be 4000 psi.
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spf log ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  11) 3770' (1') 3 holes  11) 3778-90(12') 36 holes  1V) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes  Total (38') 114 holes  With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production 5) RU Cudd. Pump 5000 gallons 15% NEFE & diverter in Attempt to achieve 5 bpm. Monitor backside for commun 6) Flowback well to tank with steel lines.  7) Once well is dead, release packer & TOH w/ WS.  8) TIH w/ prod tbg. ND BOP. NU WH. TIH w/ rods & p. Midland engineering.	pump. MI & rack up 2 7/8" WS.  "#, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  "(120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load In 5 stages per the attached pumping schedulication. RD Cudd.	thach wellbore diagram of proposed completion with ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL  backside with 2% KCL. Set packer @ +/- 3710'. le. Maximum treating pressure should be 4000 psi.
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spl log ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  11) 3770' (1') 3 holes  11) 3778-90(12') 36 holes  11) 3778-90(12') 36 holes  1V) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes  Total (38') 114 holes  With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production 5) RU Cudd. Pump 5000 gallons 15% NEFE & diverter in Attempt to achieve 5 bpm. Monitor backside for commun 6) Flowback well to tank with steel lines.  7) Once well is dead, release packer & TOH w/ WS.  8) TIH w/ prod tbg. ND BOP. NU WH. TIH w/ rods & p.	pump. MI & rack up 2 7/8" WS.  19#, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  10 (120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load in 5 stages per the attached pumping schedulication. RD Cudd  bump. Return well to production. Shoot fluid complete to the best of my knowledges.	trach wellbore diagram of proposed completion with ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL backside with 2% KCL. Set packer @ +/- 3710'. le. Maximum treating pressure should be 4000 psi. uid levels & report levels & production tests to e and belief. I further certify that any pit or below-
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spillog ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  II) 3770' (1') 3 holes  III) 3778-90(12') 36 holes  IV) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes  Total (38') 114 holes  With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production 5) RU Cudd. Pump 5000 gallons 15% NEFE & diverter in Attempt to achieve 5 bpm. Monitor backside for commun 6) Flowback well to tank with steel lines.  7) Once well is dead, release packer & TOH w/ WS.  8) TIH w/ prod tbg. ND BOP. NU WH. TIH w/ rods & p Midland engineering.  I hereby certify that the information above is true and grade tank has been/will be constructed or closed according to	pump. MI & rack up 2 7/8" WS.  "#, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  "(120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load In 5 stages per the attached pumping schedulication. RD Cudd.  pump. Return well to production. Shoot flucture.  d complete to the best of my knowledge of NMOCD guidelines , a general permit	trach wellbore diagram of proposed completion with ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL backside with 2% KCL. Set packer @ +/- 3710'. le. Maximum treating pressure should be 4000 psi. and levels & report levels & production tests to le and belief. I further certify that any pit or below-or an (attached) alternative OCD-approved plan
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spl log ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  11) 3770' (1') 3 holes  11) 3778-90(12') 36 holes  11) 3778-90(12') 36 holes  1V) 3792-96 (4') 12 holes  V) 3880-3900 (20') 60 holes  Total (38') 114 holes  With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production 5) RU Cudd. Pump 5000 gallons 15% NEFE & diverter in Attempt to achieve 5 bpm. Monitor backside for commun 6) Flowback well to tank with steel lines.  7) Once well is dead, release packer & TOH w/ WS.  8) TIH w/ prod tbg. ND BOP. NU WH. TIH w/ rods & p. Midland engineering.  I hereby certify that the information above is true and	pump. MI & rack up 2 7/8" WS.  DH, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  (120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load In 5 stages per the attached pumping schedulication. RD Cudd.  Dump. Return well to production. Shoot fluid complete to the best of my knowledge NMOCD guidelines , a general permit	trach wellbore diagram of proposed completion with ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL  backside with 2% KCL. Set packer @ +/- 3710'. le. Maximum treating pressure should be 4000 psi.  and levels & report levels & production tests to le and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spillog ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  11) 3770' (1') 3 holes  11) 3778-90(12') 36 holes  11) 3792-96 (4') 12 holes  12) 3880-3900 (20') 60 holes  13) Total (38') 114 holes  14) With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production 5) RU Cudd. Pump 5000 gallons 15% NEFE & diverter in Attempt to achieve 5 bpm. Monitor backside for commun 6) Flowback well to tank with steel lines.  1) Once well is dead, release packer & TOH w/ WS.  2) TIH w/ prod tbg. ND BOP. NU WH. TIH w/ rods & p. Midland engineering.  1 hereby certify that the information above is true and grade tank has been/will be constructed by closed according to SIGNATURE  Type or print name	pump. MI & rack up 2 7/8" WS.  DH, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  (120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load In 5 stages per the attached pumping schedulication. RD Cudd.  Dump. Return well to production. Shoot fluid complete to the best of my knowledge NMOCD guidelines , a general permit	trach wellbore diagram of proposed completion with ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL  backside with 2% KCL. Set packer @ +/- 3710'. le. Maximum treating pressure should be 4000 psi.  and levels & report levels & production tests to le and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spillog ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  11) 3770' (1') 3 holes  11) 3778-90(12') 36 holes  11) 3778-90(12') 36 holes  11) 3792-96 (4') 12 holes  12) 3880-3900 (20') 60 holes  13 Total (38') 114 holes  14 With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production 5) RU Cudd. Pump 5000 gallons 15% NEFE & diverter in Attempt to achieve 5 bpm. Monitor backside for commun 6) Flowback well to tank with steel lines.  7) Once well is dead, release packer & TOH w/ WS.  8) TIH w/ prod tbg. ND BOP. NU WH. TIH w/ rods & p. Midland engineering.  I hereby certify that the information above is true and grade tank has been/will be constructed by closed according to SIGNATURE	pump. MI & rack up 2 7/8" WS.  DH, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  (120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load In 5 stages per the attached pumping schedulication. RD Cudd.  Dump. Return well to production. Shoot fluid complete to the best of my knowledge NMOCD guidelines , a general permit	packside with 2% KCL. Set packer @ +/- 3710°.  Ide. Maximum treating pressure should be 4000 psi.  The and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan .  Telephone No.
of starting any proposed work). SEE RULE or recompletion.  1) MIRU PU, ND WH, NU BOP. TOH with rods, tbg & 2) PU & RIH w/ Bit & Scraper on 2 7/8" WS (Csg is 7" 20 bottom of hole. PBTD is 3926'. Bottom perf is 3923'. PO 3) RU Gray Wireline. RIH w/ 4" casing guns loaded 3 spillog ran in April 2000 for correlation purposes  1) 3752' (1') 3 holes  11) 3770' (1') 3 holes  11) 3778-90(12') 36 holes  11) 3792-96 (4') 12 holes  12) 3880-3900 (20') 60 holes  13) Total (38') 114 holes  14) With existing perfs (3792-3923 (255 holes)), total number 4) TIH w/ treating packer on 2 7/8" WS. Test production 5) RU Cudd. Pump 5000 gallons 15% NEFE & diverter in Attempt to achieve 5 bpm. Monitor backside for commun 6) Flowback well to tank with steel lines.  1) Once well is dead, release packer & TOH w/ WS.  2) TIH w/ prod tbg. ND BOP. NU WH. TIH w/ rods & p. Midland engineering.  1 hereby certify that the information above is true and grade tank has been/will be constructed by closed according to SIGNATURE  Type or print name	pump. MI & rack up 2 7/8" WS.  "#, J-55 ST&C (Nominal ID is 6.456" & dr  DH w/ WS & tools.  "(120 deg phase). Perf following Grayburg  of holes is 369. RD Gray Wireline.  tbg in hole to 5000 psi below slips. Load In 5 stages per the attached pumping schedulication. RD Cudd.  pump. Return well to production. Shoot flucture.  d complete to the best of my knowledge of NMOCD guidelines , a general permit	trach wellbore diagram of proposed completion with ID is 6.331") to CIBP @ 3900'. Knock CIBP to g intervals. Tie into Baker Atlas SBT/CBL/CCL  backside with 2% KCL. Set packer @ +/- 3710'. le. Maximum treating pressure should be 4000 psi.  and levels & report levels & production tests to le and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan