

New Mexico Oil Conservation Division, District I

1625 N. French Drive

Hobbs, NM 88240

Form 3160-5
(August 2007)

UNITED STATES

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

HOBBS OCD

JUN 24 2011

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED Use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Celero Energy II, LP

3a. Address

400 W. Illinois, Ste. 1601 Midland TX 79701

3b. Phone No. (include area code)

(432)686-1883

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL & 1980' FEL
(G) Sec 10, T14S, R31E

5. Lease Serial No.

LC-068474

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Drickey Queen Sand Unit #32

9. API Well No.

30-005-01023

10. Field and Pool or Exploratory Area

Caprock; Queen

11. Country or Parish, State

Chaves, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Acidize☐ Deepen☐ Production (Start/Resume)☐ Water Shut-Off☐ Subsequent Report☐ Alter Casing☐ Fracture Treat☐ Reclamation☐ Well Integrity☐ Final Abandonment Notice☐ Casing Repair☐ New Construction☐ Recomplete☐ Other☐ Change Plans☐ Plug and Abandon☐ Temporarily Abandon☒ Convert to Injection☐ Plug Back☐ Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

1. POOH w/production equipment.

2. Run bit & scraper to TD.

3. Run CIL. Run packer & test casing.

4. Acidize with 1500 gals inhibited 7.5 % HCL.

5. Run plastic coated injection tubing & packer, perform MIT & shut in pending injection permit.

APPROVED FOR 3 MONTH PERIOD
ENDING DEC 31 2011

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)

Lisa Hunt

Title Regulatory Analyst

Signature

Lisa Hunt

Date 05/23/2011

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/S/ DAVID R. GLASS

Title PETROLEUM ENGINEER

Date

JUN 17 2011

Approval Subject To Calling The BLM Roswell Field Office At Least 24 Hours Prior To The Scheduled Mechanical Integrity Test (MIT). For Wells In Chaves And Roosevelt County, Call (575) 627-0205 Or After Office Hours Call (575) 420-2832.

which would

Office

for any person knowingly and willfully to make to any department or agency of the United States any false, untruthful, or misleading statement or omission, or to obstruct or interfere with any lawfully authorized investigation or other official business of any department or agency of the United States.

JUN 28 2011