Form 3160-5 (June 2015)

Rec'd 07/13/20 - NMOCD

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM97153

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

6. If Indian, Allottee or Tribe Name

abandoned well. Use form 3160-3 (APD) for such proposals.				o. If malan, motice of	Titoe i vanie	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.		
Type of Well ☐ Gas Well ☐ Other				8. Well Name and No. VACA DRAW 9418 10 FEDERAL 21H		
2. Name of Operator Contact: SAMMY HAJAR BTA OIL PRODUCERS LLC E-Mail: shajar@btaoil.com				9. API Well No. 30-025-47392-00-X1		
3a. Address 104 S. PECOS MIDLAND, TX 79701	ne No. (include area code) 32-682-3753		10. Field and Pool or Exploratory Area JOHNSON RANCH WOLFCAMP			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State		
Sec 10 T25S R33E SWSW 42 32.138969 N Lat, 103.564560			LEA COUNTY, NM			
12. CHECK THE AP	PPROPRIATE BOX(ES) TO IND	ICATE NATURE OF	F NOTICE,	REPORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Nation of Intent	☐ Acidize ☐	Deepen	☐ Production (Start/Resume)		☐ Water Shut-Off	
Notice of Intent Notice of Intent	☐ Alter Casing ☐	Hydraulic Fracturing	☐ Reclama	ation	□ Well Integrity	
☐ Subsequent Report	☐ Casing Repair ☐	New Construction	☐ Recomp	lete	⊠ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Tempora	arily Abandon	Change to Original A PD	
	☐ Convert to Injection ☐	Plug Back	■ Water D	Pisposal		
following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi BTA OIL PRODUCERS LLC F	RESPECTFULLY REQUESTS THE SEE ATTACHED DOCUMENT	nultiple completion or recorder all requirements, including E FOLLOWING BATC FOR MORE DETAILS	mpletion in a ring reclamation	iew interval, a Form 3160- n, have been completed an G CHANGES TO TH	4 must be filed once d the operator has	
Com	Electronic Submission #521287 vo For BTA OIL PRODU Imitted to AFMSS for processing by	CERS LLC, sent to the	Hobbs			
Name(Printed/Typed) SAMMY H						
Signature (Electronic S	Submission)	Date 07/08/20)20			
	THIS SPACE FOR FED	ERAL OR STATE (OFFICE US	SE		
_Approved By_OLABODE_AJIBOLA		TitlePETROLEU	JM ENGINE	EER	Date 07/09/2020	
Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu		Office Hobbs				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime for a statements or representations as to any ma		willfully to ma	ke to any department or a	gency of the United	

Revisions to Operator-Submitted EC Data for Sundry Notice #521287

Operator Submitted BLM Revised (AFMSS)

APDCH NOI Sundry Type: OTHER NOI

NMNM97153 Lease: NMNM97153

Agreement:

Operator: BTA OIL PRODUCERS, LLC BTA OIL PRODUCERS LLC

104 S. PECOS MIDLAND, TX 79701 104 S. PECOS MIDLAND, TX 79701 Ph: 432-682-3753 Ph: 4326823753

Admin Contact:

SAMMY HAJAR REGULATORY ANALYST E-Mail: shajar@btaoil.com SAMMY HAJAR REGULATORY ANALYST E-Mail: shajar@btaoil.com

Ph: 432-682-3753 Ph: 432-682-3753

Tech Contact:

SAMMY HAJAR REGULATORY ANALYST E-Mail: shajar@btaoil.com SAMMY HAJAR REGULATORY ANALYST E-Mail: shajar@btaoil.com

Ph: 432-682-3753 Ph: 432-682-3753

Location:

NM LEA COUNTY

State: County: NM LEA

Field/Pool: JOHNSON RANCH/WOLFCAMP JOHNSON RANCH WOLFCAMP

VACA DRAW 9418 10 FEDERAL 21H Sec 10 T25S R33E SWSW 420FSL 1305FWL Well/Facility:

VACA DRAW 9418 10 FEDERAL 21H Sec 10 T25S R33E SWSW 420FSL 1305FWL

32.138968 N Lat, 103.564561 W Lon 32.138969 N Lat, 103.564560 W Lon

BATCH DRILLING SEQUENCE OF THE 21H and 23H:

- -SPUD Vaca Draw #23H drill 14-3/4" hole and set 10-3/4" csg
- -Walk to Vaca Draw #21H, SPUD 14-3/4" hole and set 10-3/4" csg test BOP, drill 9-7/8" hole and set 7-5/8" csg
- -Walk to Vaca Draw #23H, test BOP, drill 9-7/8" hole and set 7-5/8" csg, drill 6-3/4" hole and set 5-1/2" \times 5" casing.
- -Walk to Vaca Draw #21H, test BOP, drill 6-3/4" hole and set 5-1/2" x 5" casing.
- -Rig release