Form 3160-5 March 2012) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			SOCE			
SUNDRY NOTICES AND REPORTS ON WELLS JAN 2 3 21 MMNM 108969 NMNM 061863-A - BHL Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals						
SUBMIT IN TRIPLICATE – Other instructions on page 2.				nit of CA/Agreeme	nt, Name and/or No.	
I. Type of Well					/	
Oil Well Gas Well Other				8. Well Name and No. Cotton Draw 32 State Fed Com 1H		
2. Name of Operator Devon Energy Production Company, L.P.				9. API Well No. 30-025-40583		
3a. Address 3b. Phone No. (include area code) 333 W. Sheridan Avenue 405-228-4248				10. Field and Pool or Exploratory Area Delaware; North Paduca		
4. Location of Well (<i>Footage, Sec., T.,R.,M., or Survey Description</i>) NE/4 SE/4 2310 FSL & 660 FEL, Sec 32, 24S, 32E, Unit I SE/4 SE/4 330 FSL & 600 FEL, Sec 5, 25S, 32E, Unit P				11. County or Parish, State Lea County, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA						
TYPE OF SUBMISSION TYPE OF AC				fion		
Notice of Intent		cpen [cture Treat [Production (Start/Resume)	Water Shut-Off Well Integrity	
Subsequent Report		w Construction	Recomplete		Other Completion	
Final Abandonment Notice		g and Abandon 🛛 📘 g Back 🔹	Temporarily Water Dispo			
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 9/10/12 - 9/20/12 - MIRU Key WSU 6009 - PU & RIH w/ bit & tbg, tag @ 5,999', MU swivel, circ & rotate down to DV Tool @ 6,006'. DO DV Tool & CHC. Tested csg to 3,000 psi, ok, POOH w/ tbg, RDMO WSU 6009, MIRU Key WSU 6003, PU & RIH w/tbg, tag FC @ 15,474'. DO cmt to 15,520', CHC & test csg @ 3,000 psi, good. POOH. MIRU J-W WL RIH & log from 7900' to 4100' w/ 1000 psi on csg; TOC @ 4330'. RDMO WL, test annular & BOP @ 1000 psi, good test. MU & RIH w/ perf guns. Perf interval from 8,709' - 15,507' w/ 270 holes. MIRU BHI, Frac 9 stages w/ 2,044,312# 20/40 WS, 77,107# 100 mesh WS, 632,906# 20/40 SLC, 13,852 gals 7.5% HCL, FL w/2,478 bbls slick water. RD WL & BHI. RU flow back manifold, RU WH to gas buster tank, rig in 2 FB tanks & open well. 9/21/12 - 10/5/12 - Flow back well. MIRU Key WSU #6003. Kill well w/ 30 bbls brine. ND Frac valve & sleeve, NU & test BOP, RIH w/ 2-3/8" tbg, DO & CHC to PBTD @ 15,520'. POOH w/tbg, MU & RIH w/ ESP pumps & tbg, set intake @ 8,125' & set tbg @ 8,397'. POOH w/ tbg, ND annular & BOP, NU WH, Test connections, test pump, pump well into tanks. 10/6/12 - 10/18/12 - Pump went down, MIRU Key WSU & spooling truck, ND WH, NU BOP & annular BOP, POOH w/tbg, found broken shaft, replaced pump, RIH w/ tbg, CHC, POOH w/tbg. MU & RIH w/ pump & tbg, land pump, NU WH, make connections, start pumping, TOP. 10/19/12 - 10/22/12 - Test pump & RDMO WSU & Release rig. TOP.						
14. I hereby certify that the foregoing is Patti Riechers	irue and correct. (Name (<i>Primed/Typed)</i>	Title Regulatory	Specialist			
Signature PAHI, Din Anna Date 12/20/2012				LIGOEDTED FOR RECORD		
THIS SPACE FOR FEDERAL OR STATE OFFICE'USE						
Approved by						
Conditions of approval, if any, are attached that the applicant holds legal or equitable entitle the applicant to conduct operations		would Office	2	JAN da	MANAGEMENT	
Title 18 U.S.C. Section 1001 and Title 42 fictitious or fraudulent statements or repu	3 U.S.C. Section 1212, make it a crime for any esentations as to any matter within its jurisdic	person knowingly and tion.	willfully to make	CARI SBAD	Dragency of the United States any false, FIELD UFFICE	
(Instructions on page 2)						
			\smile		am !	