Form 3160-5 (August 2007)

1. Type of Well

32.615048 N Lat, 103.524271 W Lon

Sec 35 T19S R34E NESE 1980FSL 560FEL

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

HOBBS OCD	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010		
~ c 201	5. Lease Serial No.		

SUNDRY NOTICES AND REPORTS ON WEL Do not use this form for proposals to drill or to re-e abandoned well. Use form 3160-3 (APD) for such pr

Do not use this form for proposals to abandoned well. Use form 3160-3 (APL	drill or to re-enter an FEB 20	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instruc	7. If Unit or CA/Agreement, Name and/or No. 891007465B		
Type of Well  Gas Well Other	niection	8. Well Name and No. MRU 351	
Name of Operator Contact:  LINN OPERATING INCORPORATED E-Mail: tcallahan@	9. API Well No. 30-025-20302-00-S1		
Address 600 TRAVIS STREET SUITE 5100 HOUSTON, TX 77002	3b. Phone No. (include area code) Ph: 281-840-4272	10. Field and Pool, or Exploratory PEARL	
Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, and State	

LEA COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION					
<ul><li>□ Notice of Intent</li><li>☑ Subsequent Report</li><li>□ Final Abandonment Notice</li></ul>	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	<ul> <li>☑ Production (Start/Resume)</li> <li>☐ Reclamation</li> <li>☐ Recomplete</li> <li>☐ Temporarily Abandon</li> <li>☐ Water Disposal</li> </ul>	☐ Water Shut-Off ☐ Well Integrity ☐ Other		

1/16/2013 - MIRUPU FLOW WELL BACK TO WATER STATION. UNLOAD WS PUT ON RACK. WAIT ON FLANGE FOR WH. SISD.

1/17/2013 - ND WH NU BOP & PAN. POH W/ 142 JTS 2 3/8 IPC TBG. RIH W/ 4 3/4 BIT, 5 1/2" CSG SCRAPER, ON 2 3/8 WS TAG FILL @ 4843.44' W/ 152 JTS IN HOLE. PERFS COVERED 285' POH W/ 2 3/8 WS, 5 1/2" CSG SCRAPPER, 4 3/4" BIT, SISD, WAITING ON REVERSE PIT.

1/18/2013 - SICP 40 PSI. RIH W/ 4 3/4 BIT, 4 3 1/3 DC'S ON 2 3/8 WS 150 JTS. TAG FILL. BREAK CIRC CLEAN OUT FILL TO 5129' CIRC CLEAN. POH W/ 2 3/8 WS TO 3600' SISD.

1/21/2013 - POH W/ 2 38" WS,,4 3 1/2" DC'S, 4 3/4 BIT. RIH W/ 5 /2" 14-20# RBP TO 315' SET OK. ND PAN & BOP, CHANGE OUT WH. NU BOP & PAN. RLSE RBP POH W/ TBG & RBP. SISD. 4" LINER HERE. HOBBS

					_
14. I hereby certify t	that the foregoing is true and correct.  Electronic Submission #197378 verific  For LINN OPERATING INCOR  Committed to AFMSS for processing by KU	POŔAT	ED, sent to the Hobbs		_
Name (Printed/Ty	ped) TERRY B CALLAHAN	Title	REGULATORY SPECIALIST III		
Signature	(Electronic Submission)	Date	02/07/2013		_
	THIS SPACE FOR FEDERA	AL OR	STATE OFFICE USE		<u>-</u>
A(	CCEPTED		AMES A AMOS	5 . 00/00/00/10	=

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds to apply the subject lease which would entitle the applicant to condition operations the condition of the subject lease. Office Hobbs Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

<sup>13.</sup> Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

## Additional data for EC transaction #197378 that would not fit on the form

## 32. Additional remarks, continued

RENTAL INSPECTING CSG.

1/22/2013 - PU & RIH W/ 5 1/2X4" CSG PKR 4" PUMP OUT CEMENTING SLEEVE & 102 JTS 4" 11.60# CSG TO 4545', SET PKR W/ 15 PTS COMPRESSION. RD CSG CREW. RU PAR FIVE MIX & PUMP 175 SKS. CMT. DISPLACE W/52 BBLS WTR. BUMP PLUG 3500 PSI. RD PAR 5 SISD.

1/23/2013 - SICP 30 PSI. RIH W/ 4" RBP ON 2 3/8 WS TO 315' SET RBP. LOAD CSG ND PAN & BOP. WELD ON 4" BELL NIPPLE. NU WH. NU BOP & PAN. RLSE RBP POH W/ WS & RBP. RIH W/ 4" AS1X TREATING PKR., 2 3/8 WS 141 JTS. TO 4500' SET PKR. SISD. RU CRAIN ACIDIZE W/ 2500 GAL 15% NEFE HCL ACID IN 2 EQUAL STATES SEPERATED BY 1000 SALT BLOCK. MAX

RU CRAIN ACIDIZE W/ 2500 GAL 15% NEFE HCL ACID IN 2 EQUAL STATES SEPERATED BY 1000 SALT BLOCK. MAX PRESSURE 2283 PSI. AVG. PRESSURE 2100 PSI. ISIP 1190 PSI.5 MIN 745 PSI. 10 MIN 681 PSI. 15 MIN 630 PSI. AVG RATE 4 BBL MIN. TOTAL LOAD 97 BBLS. SI 1 HR. BACK FLOW 100 BBLS 3 HRS.WELL DEAD. RLSE PKR POH W/ 2 3/8 WS & PKR LAYING DWN TBG & PKR. RIH W/ 4" INJ PKR & 23 JTS 2 3/8 IPC TBG. SISD.

1/24/2013 - RU CRAIN ACIDIZE W/ 2500 GAL 15% NEFE HCL ACID IN 2 EQUAL STATES SEPERATED BY 1000 SALT BLOCK. MAX PRESSURE 2283 PSI. AVG. PRESSURE 2100 PSI. ISIP 1190 PSI.5 MIN 745 PSI. 10 MIN 681 PSI. 15 MIN 630 PSI. AVG RATE 4 BBL MIN. TOTAL LOAD 97 BBLS. SI 1 HR. BACK FLOW 100 BBLS 3 HRS.WELL DEAD. RLSE PKR POH W/ 2 3/8 WS & PKR LAYING DWN TBG & PKR. RIH W/ 4" INJ PKR & 23 JTS 2 3/8 IPC TBG. SISD.

1/25/2013 - MIRU MONK TBG TESTERS RIH W/ 4" INJ PKR ON 2 3/8" IPC TBG 142 JTS. RD MONK SET PKR LOAD TBG W/ 10 BBLS. WTR. GET OFF ON OFF TOOL. PUMP 40 BBLS PKR FLUID. LATCH BACK ON TO PKR. TEST 590 PSI FOR 30 MINS. GOOD CHART. ND PAN & BOP. NU WH. PUMP OUT SLEEVE 1600 PSI. RD PUMP TRK. RDMOPU. LEFT WELL ON INJ. MARK WHITTAKER W/ OCD VERBAL ON OK TO RUN CHART.

Copy of MIT Chart and Procedures Attached, Original sent to OCD Hobbs Office

