
	Form C-103 Revised August 1, 2011
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St. Artesia NM 88210 OIL CONSERVATION DIVISION	WELL API NO. 30-025-36425
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 MAR 0 6 1220 South St. Francis Dr.	 5. Indicate Type of Lease STATE FEE FEE Fee Fee
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Rio Blanco 4 Federal Com
PROPOSALS.) 1. Type of Well: Oil Well Gas Well <u>Other—SWD-R 13410</u>	8. Well Number
2. Name of Operator Devon Energy Production Co, LP	9. OGRID Number 6137
3. Address of Operator51333 W Sheridan Avenue, Oklahoma City, OK 7310251	10. Pool name or Wildcat 296103 Bell-Eate;Devonian, Northeast (SWD)
4. Well Location	fort from the Forth Hard
Unit Letter_J:1650feet from theSouth line and1650 _Section4Township23SRange34EMarkowski	feet from theEastline //
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3424 KB; 3400 GL	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	RK 🔲 ALTERING CASING 🗌
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN DOWNHOLE COMMINGLE Image: Complement of the second	П 108 П
OTHER: OTHER: OTHER: SWD OTHER: SWD OTHER: O	Conversion SWD-R 13410
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	
	ompletions: Attach wellbore diagram of
proposed completion or recompletion.	ompletions: Attach wellbore diagram of
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b	bit & scraper. Clean out to 14,460'.
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO	bit & scraper. Clean out to 14,460'. DH w/work string and RBP.
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. ''. Circulate inhibited 10# brine.
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 5. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing.	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. 5'. Circulate inhibited 10# brine. 1 test. Andy Garcia w/BLM witnessed.
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 5. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine.	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. '. Circulate inhibited 10# brine. I test. Andy Garcia w/BLM witnessed. bing. Set packer @ 14,431'.Circulate
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 5. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine. 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. '. Circulate inhibited 10# brine. I test. Andy Garcia w/BLM witnessed. bing. Set packer @ 14,431'.Circulate BLM witnessed.
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 5. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine. 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B 8. 40725/12: Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 9. 40/26/12: Injection test @ 4.5 bpm @ 1100 psi.	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. I'. Circulate inhibited 10# brine. It test. Andy Garcia w/BLM witnessed. Ding. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KCl.
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 6. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine. 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B 8. 4/27/25/12: Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 9. 4/26/12: Injection test @ 4.5 bpm @ 1100 psi. 10. 1/18/13: Perform Step Rate Test: Step 1-1 bpm @ 16 psi; Step 2-2 bpm @ 160 psi; Step	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. D'. Circulate inhibited 10# brine. H test. Andy Garcia w/BLM witnessed. Ding. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KCl.
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 6. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine. 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B 8. 40725/12: Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 9. 40/26/12: Injection test @ 4.5 bpm @ 1100 psi. 10. 1/18/13: Perform Step Rate Test: Step 1-1 bpm @ 16 psi; Step 2-2 bpm @ 160 psi; Step Step 5-5 bpm @ 1,490 psi; Step 6-6 bpm @ 2,180 psi; Step 7-7 bpm @ 2,870 psi. SI. 11. 2/15/13- Hooked up pump truck and injected total of 260 bbl. Injected 4.5 bpm @ 200	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. 5'. Circulate inhibited 10# brine. 1 test. Andy Garcia w/BLM witnessed. bing. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KC1. pp 3-3 bpm @ 490 psi; Step 4-4 bpm @ 960 psi
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 6. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine. 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B 8. 40725/12: Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 9. 40/26/12: Injection test @ 4.5 bpm @ 1100 psi. 10. 1/18/13: Perform Step Rate Test: Step 1-1 bpm @ 16 psi; Step 2-2 bpm @ 160 psi; Step Step 5-5 bpm @ 1,490 psi; Step 6-6 bpm @ 2,180 psi; Step 7-7 bpm @ 2,870 psi. SI. 11. 2/15/13- Hooked up pump truck and injected total of 260 bbl. Injected 4.5 bpm @ 200	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. 5'. Circulate inhibited 10# brine. 1 test. Andy Garcia w/BLM witnessed. bing. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KC1. cp 3-3 bpm @ 490 psi; Step 4-4 bpm @ 960 psi
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 6. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine. 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B 8. 40725/12: Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 9. 40/26/12: Injection test @ 4.5 bpm @ 1100 psi. 10. 1/18/13: Perform Step Rate Test: Step 1-1 bpm @ 16 psi; Step 2-2 bpm @ 160 psi; Step 5. 5 bpm @ 1,490 psi; Step 6-6 bpm @ 2,180 psi; Step 7-7 bpm @ 2,870 psi. SI. 11. 2/15/13- Hooked up pump truck and injected total of 260 bbl. Injected 4.5 bpm @ 200 water for injection until flowline and facility installation is complete.	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. V. Circulate inhibited 10# brine. I test. Andy Garcia w/BLM witnessed. bing. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KC1. pp 3-3 bpm @ 490 psi; Step 4-4 bpm @ 960 psi 00 psi. Will continue to temporarily truck haul
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 5. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine. 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B 5. 4/17/25/12: Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 9. 20/26/12: Injection test @ 4.5 bpm @ 1100 psi. 10. 1/18/13: Perform Step Rate Test: Step 1-1 bpm @ 16 psi; Step 2-2 bpm @ 160 psi; Step 5. 5 bpm @ 1,490 psi; Step 6-6 bpm @ 2,180 psi; Step 7-7 bpm @ 2,870 psi. SI. 11. 2/15/13- Hooked up pump truck and injected total of 260 bbl. Injected 4.5 bpm @ 200 water for injection until flowline and facility installation is complete.	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. 5'. Circulate inhibited 10# brine. 1 test. Andy Garcia w/BLM witnessed. bing. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KCl. pp 3-3 bpm @ 490 psi; Step 4-4 bpm @ 960 psi
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 6. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine. 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B 8. 40725/12: Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 9. 40/26/12: Injection test @ 4.5 bpm @ 1100 psi. 10. 1/18/13: Perform Step Rate Test: Step 1-1 bpm @ 16 psi; Step 2-2 bpm @ 160 psi; Step Step 5-5 bpm @ 1,490 psi; Step 6-6 bpm @ 2,180 psi; Step 7-7 bpm @ 2,870 psi. SI. 11. 2/15/13- Hooked up pump truck and injected total of 260 bbl. Injected 4.5 bpm @ 200 water for injection until flowline and facility installation is complete. Spud Date: Rig Release Date: Rig Release Date:	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. Circulate inhibited 10# brine. I test. Andy Garcia w/BLM witnessed. Ding. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KCl. p 3-3 bpm @ 490 psi; Step 4-4 bpm @ 960 psi 0 psi. Will continue to temporarily truck haul D = R - 13 U
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 5. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine. 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B 8. W725/12: Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 9. W/26/12: Injection test @ 4.5 bpm @ 1100 psi. 10. 1/18/13: Perform Step Rate Test: Step 1-1 bpm @ 16 psi; Step 2-2 bpm @ 160 psi; Step Step 5-5 bpm @ 1,490 psi; Step 6-6 bpm @ 2,180 psi; Step 7-7 bpm @ 2,870 psi. SI. 11. 2/15/13- Hooked up pump truck and injected total of 260 bbl. Injected 4.5 bpm @ 200 water for injection until flowline and facility installation is complete. Spud Date: Rig Release Date: Rig Release Date: Rig Release Date: Note the best of my knowledge Rig Release Date: Rig Release Date:	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. Circulate inhibited 10# brine. I test. Andy Garcia w/BLM witnessed. Ding. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KCl. p 3-3 bpm @ 490 psi; Step 4-4 bpm @ 960 psi 0 psi. Will continue to temporarily truck haul D = R - 13 U
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 5. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine. 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B 3. 400725/12: Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 9. 9. 0/26/12: Injection test @ 4.5 bpm @ 1100 psi. 10. 1/18/13: Perform Step Rate Test: Step 1-1 bpm @ 16 psi; Step 2-2 bpm @ 160 psi; Step 5.5 bpm @ 1,490 psi; Step 6-6 bpm @ 2,180 psi; Step 7-7 bpm @ 2,870 psi. SI. 11. 2/15/13- Hooked up pump truck and injected total of 260 bbl. Injected 4.5 bpm @ 200 water for injection until flowline and facility installation is complete. Spud Date: Rig Release Date: Rig Release Date: Rig Release Date:	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. Circulate inhibited 10# brine. I test. Andy Garcia w/BLM witnessed. Ding. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KCl. Dr 3-3 bpm @ 490 psi; Step 4-4 bpm @ 960 psi 0 psi. Will continue to temporarily truck haul D = R - 13 H O ge and belief.
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 6. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B 8. 600 psi for 30 minutes. Good test. Andy Garcia w/B 9. 7/2/2. Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 9% 0/26/12: Injection test @ 4.5 bpm @ 1100 psi. 10. 1/18/13: Perform Step Rate Test: Step 1-1 bpm @ 16 psi; Step 2-2 bpm @ 160 psi; Step 5-5 bpm @ 1,490 psi; Step 6-6 bpm @ 2,180 psi; Step 7-7 bpm @ 2,870 psi. SI. 11. 2/15/13- Hooked up pump truck and injected total of 260 bbl. Injected 4.5 bpm @ 200 water for injection until flowline and facility installation is complete. Spud Date: Rig Release Date: Spud Date: Rig Release Date: Sugar Release Date: Sugar Release Date: Spud Date: Rig Release Date: Spud Date: Rig Release Date: Sugar Release Date: Sugar Release	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. '. Circulate inhibited 10# brine. It test. Andy Garcia w/BLM witnessed. bing. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KCl. ap 3-3 bpm @ 490 psi; Step 4-4 bpm @ 960 psi 10 psi. Will continue to temporarily truck haul D = R - 13 HO ge and belief. cian DATE <u>3-5-13</u>
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 6. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub w/inhibited 10# brine. 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B State 72/12: Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 02/6/26/12: Injection test @ 4.5 bpm @ 1100 psi. 10. 1/18/13: Perform Step Rate Test: Step 1-1 bpm @ 16 psi; Step 2-2 bpm @ 160 psi; Step 5-5 bpm @ 1,490 psi; Step 6-6 bpm @ 2,180 psi; Step 7-7 bpm @ 2,870 psi. SI. 11. 2/15/13- Hooked up pump truck and injected total of 260 bbl. Injected 4.5 bpm @ 200 water for injection until flowline and facility installation is complete. Spud Date: Rig Release Date: Spud Date: Spud Pail Stack For State	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. Circulate inhibited 10# brine. I test. Andy Garcia w/BLM witnessed. bing. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KCl. p 3-3 bpm @ 490 psi; Step 4-4 bpm @ 960 psi 00 psi. Will continue to temporarily truck haul $D = \frac{R - 1340}{2}$ ge and belief. cian DATE <u>3-5-13</u> PHONE: _405-552-4615
proposed completion or recompletion. 1. 3/28/12-MIRU. POOH w/existing production string and packer from 14,338'. 2. TIH w/2-7/8" workstring to test casing. Unable to work below 11,882'. RIH w/4-1/8" b 3. Circulate packer fluid and test casing to 1,000 psi from RBP @ 14,454'. Good test. POO 4. RIH w/ 3-1/2" X 2-7/8" Enertube/Ultratube lined injection tubing. Set packer @ 14,415 5. 4/17/12-Run MIT for BLM. Test to 800 psi. Would lose 80-90 psi in 30 minutes. Failed 6. POOH w/injection tubing. RIH w/3-1/2" X 2-7/8" Enertube/Ultratube lined injection tub 7. 4/23/12-Run MIT for BLM. Test to 800 psi for 30 minutes. Good test. Andy Garcia w/B 8. 600 psi for 30 minutes. Good test. Andy Garcia w/B 9. 7/2/2. Acidized Devonian formation with 895 gal 2% KCl, 3,000 gal 15% HCl acid, 9% 0/26/12: Injection test @ 4.5 bpm @ 1100 psi. 10. 1/18/13: Perform Step Rate Test: Step 1-1 bpm @ 16 psi; Step 2-2 bpm @ 160 psi; Step 5-5 bpm @ 1,490 psi; Step 6-6 bpm @ 2,180 psi; Step 7-7 bpm @ 2,870 psi. SI. 11. 2/15/13- Hooked up pump truck and injected total of 260 bbl. Injected 4.5 bpm @ 200 water for injection until flowline and facility installation is complete. Spud Date: Rig Release Date: Spud Date: Rig Release Date: Sugar Release Date: Sugar Release Date: Spud Date: Rig Release Date: Spud Date: Rig Release Date: Sugar Release Date: Sugar Release	bit & scraper. Clean out to 14,460'. DH w/work string and RBP. Circulate inhibited 10# brine. H test. Andy Garcia w/BLM witnessed. bing. Set packer @ 14,431'.Circulate BLM witnessed. 3,616 gal 2% KCl. ap 3-3 bpm @ 490 psi; Step 4-4 bpm @ 960 psi bit will continue to temporarily truck haul D = R - 13 410 ge and belief. cian DATE <u>3-5-13</u>

NUN-WELL POD # 2837058



.

