## HOBBS OCD

Conditions of Approval (if any):

1 2 2013				
Submit One Copy To Appropriate District AR 1 2 2013 State of N	New Mexi	co		Form C-103
State of N  Office  District I  1625 N. French Dr., Hobbs, NM 88240  State of N  Energy, Minerals a	and Natura	l Resources		March 18, 2009
1625 N. French Dr., Hobbs, NM 88240 RECEIVED		,	WELL API NO. /	
District II OIL CONICEDA		NOISION	30-025-11681	
1501 W. Gland 1We., 14testa, 1W 60210			5. Indicate Type of Le	
1000 Die Brogge Dd. Astee NM 97410			STATE	FEE 🛛
District IV Santa Fe, NM 87505		03	6. State Oil & Gas Lea	se No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEP! DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM	EN OR PLUG	BACK TO A	7. Lease Name or Unit B T LANEHART	Agréement Name
PROPOSALS.)  1. Type of Well:   Oil Well   Gas Well   Other			8. Well Number 004	
2. Name of Operator			9. OGRID Number	
BETTIS, BOYLE & STOVALL			002175	
3. Address of Operator			10. Pool name or Wildcat	
P.O. BOX 1240, GRAHAM, TX 76450			TANSIL YATES 7 RI	√ERS
4. Well Location			/	
Unit Letter_ B : 990feet from the NORTH li	ine and 231	0 feet from the EA	<u>ST</u> line /	
Section 21 Township 25S Range 37E NMPM County LEA				
11. Elevation (Show when 3075 GR	ether DR, R	YKB, RT, GR, etc.)	19 47 11 11 11	
12. Check Appropriate Box to Indicate Nature of N	lotice. Rei	port or Other Da	nta	and the second s
	, , , , , , , , ,			
NOTICE OF INTENTION TO:	_		EQUENT REPOR	
		REMEDIAL WORK	<del></del>	ERING CASING 🔲 '
TEMPORARILY ABANDON				ND A
PULL OR ALTER CASING		CASING/CEMENT .	JOB 📙	
OTHER:		☑ l'ocation is rea	dv-for OCD inspection	naffer P&A
OTHER:     Description   Descr				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above				
"				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR				
<u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.</u>				
FERMANENTLI STAMFED ON THE MARKET	N S SUKFA	ICE.		
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
ocd rules and the terms of the Operator's pit permit and closu from lease and well location.	ire plan. Al	I flow lines, produc	ction equipment and jui	ik have been removed
☐ All metal bolts and other materials have been removed. Po	ortable base	s have been remove	nd (Pourad angita conc	rata hagas da nat haya
to be removed.)	ntable base.	s have been remove	ca. (1 ourca onsite conc	rete bases do not have
All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordan	ice with 19.	15.35.10 NMAC.	All fluids have been rei	noved from non-
retrieved flow lines and pipelines.				
When all work has been completed return this form to the enny	nonniata Dia	stuint office to solve		
When all work has been completed, return this form to the appr	ropriate Dis	strict office to sched	iule an inspection.	
2/1/2/1	<i></i>	1111 01 /	1.10.1/	02/1/2
SIGNATURE Full T	TTLE_ <u>/{</u>	EGULATORY A	DAT DAT	E US/07/12
TYPE OR PRINT NAME KYLE BEREND E	e-mail: <u>/</u>	berendal bbs	OI / Com PHON	E 03/07/13 NE: 940-549-0780 UVZ
For State Use Only	Λ	1. >	\(\mathcal{C}\)	112
ADDROVED BY: I Vach Whateken T	от е ('А	Maria (	HII CON DA	いんしゅん 1 <i>2</i> かに