<del>•</del> .		e* •	•.					
Form 3160-5				SOCD	FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014			
() () (0010)	UNITED STATE							
(March 2012) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT				8 2013	5. Lease Serial No. NMNM-90161			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-ended					6. If Indian, Allottee or	Tribe Name		
Do not use this i abandoned well.	torm for proposals t Use Form 3160-3 (A	o arili or to PD) for suci	re-emecan h proposals	/ED s.				
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No. NMNM-116414 24427			
1. Type of Well					8. Well Name and No.			
Oil Well Gas Well Other					West Blinebry Drinka	ard Unit (WBDU) #054	(373	346)
2. Name of Operator Apache Corporation (873)					9. API Well No. 30-025-38200			
3a. Address 303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705	(include area code) 10. Field and Pool or E Eunice; B-T-D, North							
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish,			State		
2620' FSL & 2510' FEL UL J Sec 9 T21S R37E					Lea County, NM			
12. CHE0	CK THE APPROPRIATE BO	X(ES) TO INDI	CATE NATURE	OF NOTIC	CE, REPORT OR OTHE	ER DATA		
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF AC							
✓ Notice of Intent	Acidize	= .			uction (Start/Resume)	Water Shut-Off		
	Alter Casing				amation	Well Integrity	FS	
Subsequent Report Casing Report		New Construction Plug and Abandon			mplete porarily Abandon			
Final Abandonment Notice				· _ `	r Disposal			
determined that the site is ready for final inspection.) Apache would like to add perforations to, and acid stimulate the Blinebry and Drinkard formations, per the attached. SEE ATTACHED FOR CONDITIONS OF APPROVAL								
14. I hereby certify that the foregoing is	true and correct. Name (Printe	d/Typed)						
Reesa Holland Fisher Title Sr. Staff Reg Te				Reg Tech				
Signature Reesa Holland Fisher			Date 05/09/20	13		PROVED		
· 7	THIS SPACE	FOR FEDER	RAL OR ST	ATE OFF		V 0 0 00		
Approved by						FEM		 \
Condition of the			Title		Lifen	mp / rok	<u>900</u>	ر
Conditions of approval, if any, are attache that the applicant holds legal or equitable entitle the applicant to conduct operations	title to those rights in the subject				BUHAU OF	BAD FIELD OFFICE		
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a	a crime for any per	son knowingly an	d willfully to	o make to any department	or agency of the United Sta	ates any f	false,

fictitious or fraudulent statements or representations as to any matter within its jurisdiction. MAB/OCD 7/16/2013

(Instructions on page 2)

## WBDU 54 Proposed Procedure

Add perforations to, and acid stimulate the Blinebry and Drinkard formations

- **Day 1:** MIRU. POOH w/ rods and pump. Install BOP. Tag for fill and POOH w/ 2-7/8" tbg. RIH w/ 4-3/4" bit on 2-7/8" ws
- Day 2: Cont. RIH. Clean well to out +/- 6775' PBTD as necessary, POOH. RIH w/ scraper to +/-6700'
- Day 3: Cont. RIH w/scraper to +/-6700', POOH.

MIRU WL. Perforation depths based on a datum elevation of 3497' (KB elevation). Openhole logs with proposed perforations will be provided for correlation

Perforate the Drinkard from 6494-95', 6514-16', 22-24', 74-85', 6593-6604', 6641-45', 51-55', 58-60', 74-77' w/ 4 SPF, 90 deg phasing (40 ft, 160 shots)

Perforate the Blinebry from 5783-85', 86-88', 96-99', 5820-22', 74-76', 6130-32' w/ 4 SPF, 90 deg phasing (13 ft, 52 shots)

PU RIH w/ RBP and treating pkr


Day 4: Cont. RIH w/ RBP and treating pkr


Set RBP @ +/-6700'. Set pkr @ +/-6400'. Acidize the Drinkard w/8,800 gals 15% HCI-NE-FE BXDX acid and rock salt in three equal stages @ +/-10 BPM. Release pkr. Wash out salt. Release RBP

Re-set RBP @ +/-6180', set pkr @ +/-5600'. Acidize the Blinebry w/6,400 gals 15% HCl-NE-FE BXDX acid and rock salt in three equal stages @ +/-10 BPM. Release pkr. Wash out salt. Release RBP

POOH w/ 2-7/8" ws

Day 5: Cont. POOH w/ 2-7/8" ws. RIH w/ SN, 2-7/8" production tbg. ND BOP, set TAC, NU





West Blinebry Drinkard Unit 54 30-025-38200 Apache Corporation May 22, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by August 22, 2013.

. . .

- 1. Must conduct a casing integrity test before any work can be done. Submit results to BLM. The CIT is to be performed on the production casing per Onshore Oil and Gas Order 2.III.B.1.h. Submit results to BLM.
- 2. If CIT does not fail work is approved as written.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.

JAM 052213