
	UNITED STATES	1	OCD Hobbs		
	EPARTMENT OF THE IN	NTERIOR	HOBBS OCI	OMB No. 1004-0135 Expires July 31, 1996	
	GEMENT	f H H M A A	5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS					
Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name	
	PLICATE – Other instr	uctions on reve	rse side	7. If Unit or CA/Agreement, Name and/or N	
1. Type of Well X Oil Well Gas Well	8. Well Name and No.				
2. Name of Operator	GREGORY A #7				
DC ENERGY, LLC.	3				
3a. Address c/o Mike Pippin LLC		3b. Phone No. (include area code)		30-025-11867	
3104 N. Sullivan, Farmington, NM 87401		505-327-4573		10. Field and Rool or Emploratory Area SR	
4. Location of Well (Footage, Sec	c., T., R., M. or Survey Descrip	tion)		Queen SWD GB	
660' FSL & 2060' FWL Un					
Sec. 33, T25S, R37E				Los County New Moving	
	/			Lea County, New Mexico	
12. CHECK APPROPRIATE B	OX(ES) TO INDICATE NA	TURE OF NOTICE	, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent	Acidize	Deepen	Production	(Start/Resume) 🔲 Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamatio	n Well Integrity	
Subsequent Report	Casing Repair	New Constructi			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disp		
3065'-2480', Queen pr CIBP @ 3065'. PU & (25 sx gel/100 bbls wa rate w/water down 5-1/ Cut off csg below surfa specs. RD move off lo	erfs 3115'-3213' & top oump 68 sx cmt (585' in ter). Plug #2 (377'-Sur /2" csg & out bradenhea ace csg flange. Top off ocation, cut off anchors of See Affac La	of Yates @ 2530 5-1/2"). TOH. M face'), 8-5/8" cs ad valve. Pump of csgs w/cmt. Inst & restore location	<u>).</u> Set 5-1/2" CI NOC. Tag cmt. g shoe @ 327. cmt down 5-1/2" call P&A marker	w/all production equipment. <u>Plug</u> BP @ 3065'. TIH w/ tbg & tag 5-1/. W/tbg @ 2450', circ hole w/P&A Perf 3 SQ holes @ 377'. Establis csg & out bradenhead valve (~94 with cmt to comply with governme Ac-Sachm: T	
3065'-2480', Queen pr CIBP @ 3065'. PU & (25 sx gel/100 bbls wa rate w/water down 5-1/ Cut off csg below surfa specs. RD move off lo	erfs 3115'-3213' & top oump 68 sx cmt (585' in ter). Plug #2 (377'-Sur '2" csg & out bradenhea ace csg flange. Top off ocation, cut off anchors See Affao La autocol Coord	of Yates @ 2530 5-1/2"). TOH. M face'), 8-5/8" cs ad valve. Pump of csgs w/cmt. Inst & restore location	<u>).</u> Set 5-1/2" CI NOC. Tag cmt. g shoe @ 327. cmt down 5-1/2" call P&A marker	BP @ 3065'. TIH w/ tbg & tag 5-1/ W/tbg @ 2450', circ hole w/P&A Perf 3 SQ holes @ 377'. Establis csg & out bradenhead valve (~94 with cmt to comply with governme	
3065'-2480', Queen pr CIBP @ 3065'. PU & p (25 sx gel/100 bbls wa rate w/water down 5-1) Cut off csg below surfa specs. RD move off for Acjected	erfs 3115'-3213' & top pump 68 sx cmt (585' in ter). Plug #2 (377'-Sur /2" csg & out bradenhea ace csg flange. Top off boation, cut off anchors of See Affao La arthan Cond ing is true and correct	of Yates @ 2530 5-1/2"). TOH. M face'), 8-5/8" cs ad valve. Pump of csgs w/cmt. Inst & restore location	D:_ Set 5-1/2" CI NOC. Tag cmt. g shoe @ 327. Set 5-1/2" cmt down 5-1/2" Set 5-1/2" <t< td=""><td>BP @ 3065'. TIH w/ tbg & tag 5-1/ W/tbg @ 2450', circ hole w/P&A Perf 3 SQ holes @ 377'. Establis csg & out bradenhead valve (~94 with cmt to comply with governme Ac. Sabm: T</td></t<>	BP @ 3065'. TIH w/ tbg & tag 5-1/ W/tbg @ 2450', circ hole w/P&A Perf 3 SQ holes @ 377'. Establis csg & out bradenhead valve (~94 with cmt to comply with governme Ac. Sabm: T	
3065'-2480', Queen pr CIBP @ 3065'. PU & p (25 sx gel/100 bbls wa rate w/water down 5-1/ Cut off csg below surfa specs. RD move off lo the ference feed based based based 14. Thereby certify that the forego Name (Printed/Typed) Mike Pippin mike@p	erfs 3115'-3213' & top oump 68 sx cmt (585' in ter). Plug #2 (377'-Sur '2" csg & out bradenhea ace csg flange. Top off ocation, cut off anchors See Affao La autocol Coord	of Yates @ 2530 1 5-1/2"). TOH. N face'), 8-5/8" cs ad valve. Pump of csgs w/cmt. Inst & restore location Suredry	D:_ Set 5-1/2" CI NOC. Tag cmt. g shoe @ 327. Set 5-1/2" cmt down 5-1/2" Set 5-1/2" <t< td=""><td>BP @ 3065'. TIH w/ tbg & tag 5-1/ W/tbg @ 2450', circ hole w/P&A Perf 3 SQ holes @ 377'. Establis csg & out bradenhead valve (~94 with cmt to comply with governme</td></t<>	BP @ 3065'. TIH w/ tbg & tag 5-1/ W/tbg @ 2450', circ hole w/P&A Perf 3 SQ holes @ 377'. Establis csg & out bradenhead valve (~94 with cmt to comply with governme	
3065'-2480', Queen pr CIBP @ 3065'. PU & p (25 sx gel/100 bbls wa rate w/water down 5-1) Cut off csg below surfa specs. RD move off for F Aejecfecf. 14. I hereby certify that the foregon Name (Printed/Typed)	erfs 3115'-3213' & top pump 68 sx cmt (585' in ter). Plug #2 (377'-Sur (2" csg & out bradenhea ace csg flange. Top off ocation, cut off anchors See Attack attack Cord ing is true and correct ippinIlc.com	of Yates @ 2530 of 5-1/2"). TOH. N face'), 8-5/8" cs ad valve. Pump of csgs w/cmt. Insi & restore location Second ry Intel Date	<u>).</u> Set 5-1/2" CI NOC. Tag cmt. g shoe @ 327. cmt down 5-1/2" call P&A marker n. <i>Jafice</i> Petroleu	BP @ 3065'. TIH w/ tbg & tag 5-1/ W/tbg @ 2450', circ hole w/P&A Perf 3 SQ holes @ 377'. Establis csg & out bradenhead valve (~94 with cmt to comply with governme Ac. Sabm: T	
3065'-2480', Queen pr CIBP @ 3065'. PU & p (25 sx gel/100 bbls wa rate w/water down 5-1) Cut off csg below surfa specs. RD move off lo ★ Aejected Descored 14. I hereby certify that the forego Name (Printed/Typed) Mike Pippin mike@p Signature	erfs 3115'-3213' & top pump 68 sx cmt (585' in ter). Plug #2 (377'-Sur (2" csg & out bradenhea ace csg flange. Top off ocation, cut off anchors See Attack attack Cord ing is true and correct ippinIlc.com	of Yates @ 2530 15-1/2"). TOH. N face'), 8-5/8" cs ad valve. Pump of csgs w/cmt. Inst & restore location find of the Content of the Date CE FOR FEDERAL	<u>).</u> Set 5-1/2" CI NOC. Tag cmt. g shoe @ 327. cmt down 5-1/2" call P&A marker n. <i>Jafice</i> Petroleu	BP @ 3065'. TIH w/ tbg & tag 5-1/ W/tbg @ 2450', circ hole w/P&A Perf 3 SQ holes @ 377'. Establis csg & out bradenhead valve (~94 with cmt to comply with governme Ac.Sabm:T m Engineer (Agent) une 29, 2013	
3065'-2480', Queen pr CIBP @ 3065'. PU & p (25 sx gel/100 bbls wa rate w/water down 5-1) Cut off csg below surfa specs. RD move off lo ★ Aejected . Descellent Name (Printed/Typed) Mike Pippin mike@p Signature	erfs 3115'-3213' & top pump 68 sx cmt (585' in ter). Plug #2 (377'-Sur '2" csg & out bradenhea ace csg flange. Top off bration, cut off anchors See Affacta attact Corod ing is true and correct ippinIIc.com this spa med Approval of this notice does no equitable title to those rights in the s	of Yates @ 2530 a 5-1/2"). TOH. M face'), 8-5/8" cs ad valve. Pump of csgs w/cmt. Inst & restore location From Service of Title Date ACE FOR FEDERAL Title Office	D: Set 5-1/2" CI NOC. Tag cmt. g shoe @ 327'. Set 6-1/2" cmt down 5-1/2" Set 6-1/2" <t< td=""><td>BP @ 3065'. TIH w/ tbg & tag 5-1/ W/tbg @ 2450', circ hole w/P&A Perf 3 SQ holes @ 377'. Establis csg & out bradenhead valve (~94 with cmt to comply with governme Ac. Sabm: T</td></t<>	BP @ 3065'. TIH w/ tbg & tag 5-1/ W/tbg @ 2450', circ hole w/P&A Perf 3 SQ holes @ 377'. Establis csg & out bradenhead valve (~94 with cmt to comply with governme Ac. Sabm: T	
3065'-2480', Queen pr CIBP @ 3065'. PU & p (25 sx gel/100 bbls wa rate w/water down 5-1) Cut off csg below surfa specs. RD move off fc ★ Aejected Desceled Name (Printed/Typed) Mike Pippin mike@p Signature	erfs 3115'-3213' & top pump 68 sx cmt (585' in ter). Plug #2 (377'-Sur '2" csg & out bradenhea ace csg flange. Top off bration, cut off anchors See Affacta af	of Yates @ 2530 15-1/2"). TOH. M face'), 8-5/8" cs ad valve. Pump of csgs w/cmt. Inst & restore location Survedry Itile Date ACE FOR FEDERAL Office subject lease Vingly and willfully to m	D:_ Set 5-1/2" CI NOC. Tag cmt. g shoe @ 327'. cmt down 5-1/2" cmt down 5-1/2" call P&A marker n. Detroleu Detroleu Junt Constante USE SEPS AFD	BP @ 3065'. TIH w/ tbg & tag 5-1/ W/tbg @ 2450', circ hole w/P&A Perf 3 SQ holes @ 377'. Establis csg & out bradenhead valve (~94 with cmt to comply with governme Ac-Sachm: T m Engineer (Agent) une 29, 2013	

•


GREGORY A #7

Proposed After P&A Queen (N) Section 33, T-25-S, R-37-E, Lea County, NM





Current 6/29/13 Queen (N) Section 33, T-25-S, R-37-E, Lea County, NM



ан 2 алар	1		(
Form 3160-5 (August 1999) DE Bl				FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000 5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an				NMLC054667		
Do not use thi abandoned we	6. If Indian, Allotte	6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRI	7. If Unit or CA/Ag	7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well Oil Well Gas Well Oth		8. Well Name and No. GREGORY A 07				
2. Name of Operator XERIC OIL & GAS CORPORATION				30-025-11867-00-S1		
3a. Address P. O. BOX 352 MIDLAND, TX 79702		3b. Phone No. (include area cod Ph: 915.683.3171 Ext: 235 Fx: 915.683.6348		or Exploratory		
4. Location of Well (Footage, Sec., T		11. County or Paris	11. County or Parish, and State			
Sec 33 T25S R37E SESW 66		LEA COUNTY, NM				
12. CHECK APPF	ROPRIATE BOX(ES) TC	INDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
□ Notice of Intent		Deepen	Production (Start/Resume)	U Water Shut-Off		
	□ Alter Casing	Fracture Treat	Reclamation	Well Integrity		
Subsequent Report	🛛 Casing Repair	□ New Construction	Recomplete	□ Other		
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	 Temporarily Abandon Water Disposal 			
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi 1/23/04 TOH w/rods & tbg. S 1/24/04 Found hole in csg @ 1/25-2/15 Squeezed four times 2/16/04 Drill out CIBP @ 270 2/18/04 Run 2700' 3 1/2" 9.3; 2/19/04 TIH w/2 7/8" bit + 2 1 3148'. 2/20/04 Run production equip COPY MAILED TO NMOCD D	k will be performed or provide i operations. If the operation res bandonment Notices shall be file inal inspection.) Set CIBP @ 2700'. 1040'. s w/1000 Sx Class "C". S 00' & dump 150 Sx sand. # J-55 csg. Cement w/15 1/16" tbg and drill out float by the second drill out float coment & PWTP. DISTRICT I 2/27/04. true and correct. Electronic Submission #: For XERIC OIL & mitted to AFMSS for proce	the Bond No. on file with BLM/BI ults in a multiple completion or rec d only after all requirements, inclu queeze unsuccessful. 0 Sx Class "C". shoe & circulate sand out to shoe & circulate sand out to cass composition of the BLM We & GAS CORPORATION, sent to ssing by ARMANDO LOPEZ of	Il Information System	be filed within 30 days 160-4 shall be filed once		
Name(FrintearTypea) W. KILEL						
Signature (Electronic S	ubmission)	Date 02/27/2	2004			
=	THIS SPACE FO	R FEDERAL OR STATE	OFFICE USE			
ACCEPTED			DAVID R GLASS TitlePETROLEUM ENGINEER Date 03/0			
Conditions of approval, if any, are attached certify that the applicant holds legal or equivient would entitle the applicant to condu-	itable title to those rights in the	not warrant or subject lease Office Hobbs				
Title 18 U.S.C. Section 1001 and Title 43 U States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a c tatements or representations as f	rime for any person knowingly and o any matter within its jurisdiction	l willfully to make to any department o	or agency of the United		

2

6

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **