Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240		1	WELL API NO.
District II - (575) 748-1283			30-025-41094
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	S. I list St., Altesia, Nivi 80210 HORRE CO.		5. Indicate Type of Lease
000 Dia Denros Dd. Arton NM 97410			STATE S FEE .
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NMUG 1 87505	Santa Fe, NM 87	7303	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS: FO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		UG BACK TO A	7. Lease Name or Unit Agreement Name
		<u></u>	RONHOUSE 19 STATE COM
1. Type of Well: Oil Well 🛛 Gas Well 🔲 Other		1 8	3. Well Number 2H
2. Name of Operator		9	O. OGRID Number
Devon Energy Production Company, L.P.		1	6137 10. Pool name or Wildcat
 Address of Operator W. Sheridan Avenue, Oklahom 	a City, Oklahoma 73102-5010		WC-025 G-06 S183518A; BONE SPRING
4. Well Location			
Unit Letter_P:_	410 feet from the <u>S</u>	line and630	
Section 19	Township 18S		MPM Lea, County New Mexico
	11. Elevation (Show whether DR 3931.8'	P, RKB, RT, GR, etc.)	
12. Check Ap	opropriate Box to Indicate N	lature of Notice, R	eport or Other Data
NOTICE OF INT		1	EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE BLANC	REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS MULTIPLE COMPL	COMMENCE DRILL	
PULL OR ALTER CASING DOMANNOLE COMMUNICIE	MULTIPLE COMPL	CASING/CEMENT	JOB 📙
DOWNHOLE COMMINGLE			
OTHER:		OTHER: Completio	
Describe proposed or comple	eted operations. (Clearly state all	pertinent details, and g	give pertinent dates, including estimated date
of starting any proposed work proposed completion or record		C. For Multiple Comp	oletions: Attach wellbore diagram of
6/25/13 - 6/26/13 -MIRU WSU; PU & TI BHA. MIRU WL & run CCL & CBL fron	H w/ 4 ¾" bit and tbg, tag PBTD @ m 9,531' to 1,000'; TOC @ 1,240'.	13,790'; Circ 300 bbl 2% RD WL and test csg @ 3	6 KCL; test csg to 1,000 psi; POOH w/tbg & ,000psi; good test.
6/27/13 - 6/29/13 - PU & RIH w/perf gun WH; test lines to 9,000psi, good test, bleed		3' w/ 400 holes. POOH a	and ND BOP, NU frac valve, RU pump line to
6/30/13 – 7/9/13 - MIRU BHI, Frac 10 sta Slick water; flush w/2,927 bbls slick water		gals 15% HCL, 297,913#	20/40 SLC, 38,236# 100 Mesh, 2,528,988 gals
7/10/13 – 7/18/13 - Start flow back.			
7/19/13 – 7/22/13 - Pump 180 bbls brine v	vater to kill well. ND frac valve and s	sleeve NII B1 flange em	npty farc tanks, ND frac sleeve & capped WH. SI.
	vater to kill well. ND hae valve and s	neeve, we br nange, en	
7/23/13 - 8/3/13 - RUSWU, spot tbg & re stand back tbg. PU BHA & ESP, TIH & s	verse equipment, ND WH, NU BOP,	PU 4-3/4" bit & RIH, D	OO frac plugs; TIH to PBTD & CHC. POOH &
stand back tbg. PU BHA & ESP, TIH & s	verse equipment, ND WH, NU BOP, set intake @ 8,897', EOT @ 9,171'.	PU 4-3/4" bit & RIH, C RD WSU; TOP.	
	verse equipment, ND WH, NU BOP, set intake @ 8,897', EOT @ 9,171'.	PU 4-3/4" bit & RIH, C RD WSU; TOP.	
stand back tbg. PU BHA & ESP, TIH & s	verse equipment, ND WH, NU BOP, set intake @ 8,897', EOT @ 9,171'.	PU 4-3/4" bit & RIH, C RD WSU; TOP.	
I hereby certify that the information all SIGNATURE Type or print name David H. Cook	verse equipment, ND WH, NU BOP, set intake @ 8,897', EOT @ 9,171'. bove is true and complete to the b	PU 4-3/4" bit & RIH, E RD WSU; TOP.	DATE <u>08/12/2013</u>
I hereby certify that the information al	verse equipment, ND WH, NU BOP, set intake @ 8,897', EOT @ 9,171'. bove is true and complete to the b TITLE_RegulE-mail address	PU 4-3/4" bit & RIH, ERD WSU; TOP. Dest of my knowledge a	DATE 08/12/2013 PHONE: (405) 552-7848