Submit 1 Copy To Appropriate District Office	State of New I		•	Form C-103 Revised August 1, 2011
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and N	atural Resources	WELL API NO.	
<u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210		OIL CONSERVATION DIVISION		25-00308
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	Rio Brizzos Pd. Azieo NM 97410		5. Indicate Type of L STATE X	FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM	8/303	6. State Oil & Gas Le	ease No.
87505			303735	·
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name Rock Queen Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SOCD PROPOSALS.)				
1. Type of Well: Oil Well Gas Well Other Injection		8. Well Number 6		
2. Name of Operator Celero Energ		JAN 07 2014		247128
3. Address of Operator <sub>400</sub> W. Illi Midland, T	nois, Ste. 1601		10. Pool name or Wil	dcat
4. Well Location		RECEIVED	Caprock; Queen	/
Unit Letter F : 1980 feet from the N line and 1980 feet from the W line				
Section 30	Township 13S	Range 32E	NMPM C	ounty Lea
	11. Elevation (Show whether i	OR, RKB, RT, GR, etc.	)	
	4384'			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
	ITENTION TO:		SEQUENT REPO	
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🛛 CHANGE PLANS 🗌	REMEDIAL WOR		
PULL OR ALTER CASING		CASING/CEMEN		
OTHER:		OTHER:		
	bleted operations. (Clearly state a			
of starting any proposed w proposed completion or rec	ork). SEE RULE 19.15.7.14 NM	AC. For Multiple Co		bore diagram of
1. RIH w/BP & PS on workstring and spot 10 sx at 3044'. WOC a minimum of 4 hours and tag at/above <del>2994'.</del> Circulate minimum				
9.5 ppg salt mud to 1800', <del>PU to 2926' and spot 25 sx. WOC a minimum of 4 hours and tag at/above 2710'</del> . POOH.				
2. RU wireline and perforate (4) at 2200'. RIH w/packer and squeeze 50 sx into perfs at 2200'. POOH w/packer, RBIH w/BP&PS on workstring and tag at/above 2100'. POOH.				
3. RU wireline and jet cut 4-1/2" at 1770'. RD WL and recover 4-1/2" casing.				
4. RIH w/BP & PS on workstring to 1820' and spot 25 sx. WOC a minimum of 4 hours and tag at/above 1720'. Circulate minimum 9.5 ppg salt mud to surface & POOH.				
5. RU wireline and perforate (4) at 1500' and 427'. RIH w/packer and squeeze 50 sx into perfs at 1500'. WOC a minimum 4 hours				
and pressure test plug. Pull packer above 427' and establish circulation on 7"-by-9-5/8" annulus. POOH. 6. RIH with BP & PS and tag plug at/above 1400'. PU to 477' and fill 7" and 7"-by-9-5/8" annulus to surface with minimum 185 sx.				
POOH and top off 7" if necessary	ý.	-		·
7. Cut off wellhead, set P&A man	ker, fill cellar, clean and reclaim	location.	The Oil Conservati	on Division
A closed lopp system will be used	<del>d</del>	[ <b>D</b>	<del>AUST BE NOTIFI</del>	ED 24 Hours
Spud Date:	Rig Release	Date: Pr	ior to the beginning	g of operations
t		<b></b>		
I hereby certify that the information	above is true and complete to the	e best of my knowledg	e and belief.	· · · · · · · · · · · · · · · · · · ·
, , Л				
SIGNATURE LINA	Frint TITLE Reg	ulatory Analyst	DATE	01/08/2014
Type or print name Lisa Hunt	E-mail add	ess: <u>lhunt@celeroene</u>	rgy.com PHON	E: <u>(432)686-1883</u>
For State Use Only				
APPROVED BY: // Alux HIOW TITLE OMPLIANCE The DATE 1/8/2014 Conditions of Approval (if any)				
SATISFICIAL TRACTORIANCE AND AND A STREET				

JAN 0'8 2014



