

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION

HOBBS OCD

1220 South St. Francis Dr.
Santa Fe, NM 87505

JAN 13 2014

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-03858
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other SWD		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator ROCKY SMITH SWD SYSTEMS, INC		6. State Oil & Gas Lease No. B-1553
3. Address of Operator 1515 WAZEE, SUITE 350, DENVER, CO 80202		7. Lease Name or Unit Agreement Name STATE E TRACT 78
4. Well Location Unit Letter <u>G</u> : <u>1650</u> feet from the <u>N</u> line and <u>1650</u> feet from the <u>E</u> line Section <u>2</u> Township <u>17S</u> Range <u>36E</u> NMPM LEA County		8. Well Number <u>22</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3851		9. OGRID Number 270801
		10. Pool name or Wildcat ABO-SWD

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/2/2013 Moved in rigged up and installed BOP.

12/3/2013 Picked up 2 7/8" work string and tagged existing CIBP at 6241'. Circulated hole with mud.

12/4/2013 Spotted 35 sx class C cement on top of CIBP at 6241'. POOH to 4780' and spotted 25 sx class c cement. Did not tag as per OCD. POOH to 3700' and spotted 25 sx class c cement. Did not tag as per OCD. POOH to 3325' and spotted 45 sx class c cement. All plugs were displaced with MLF. POOH and SION.

12/6/2013 RIH and tagged cement at 2896'. POOH to 2300' and spotted 25 sx class c cement. Laid down remaining pipe and perforated at 325'. Pumped class c cement down 5 1/2" casing to perfs at 325' and up 5 1/2 X 9 5/8 and 9 5/9 X 13 3/8 annulus to surface. Took 253 sx.

12/9/2013 Cut off wellhead, installed marker, and cut off anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Scotty A Smith TITLE President DATE 12/24/2013
Type or print name Scotty A. Smith E-mail address: scotty@3forkres.com PHONE: 303.318.0717
For State Use Only
APPROVED BY: Mary Brown TITLE Compliance Officer DATE 1/14/2014
Conditions of Approval (if any):

JAN 14 2014