Hydrogen Sulfide Drilling Operations Plan

Fuggles 24 Federal Com 1H

Cimarex Energy Co. of Colorado Unit D, Section 24 T25S-R32E; Lea County, NM

30-025-41596 HOBBS OCD JAN 13 2014

RECEIVED

1 All Company and Contract personnel admitted on location must be trained by a qualified H₂S safety instructor to the following:

- A. Characteristics of H₂S
- B. Physical effects and hazards
- C. Proper use of safety equipment and life support systems.
- D. Principle and operation of H₂S detectors, warning system and briefing areas.
- E. Evacuation procedure, routes and first aid.
- F. Proper use of 30 minute pressure demand air pack.

2 H₂S Detection and Alarm Systems:

A. H₂S detectors and audio alarm system to be located at bell nipple, end of flow line (mud pit) and on derrick floor or doghouse.

3 Windsock and/or wind streamers:

- A. Windsock at mudpit area should be high enough to be visible.
- B. Windsock at briefing area should be high enough to be visible.

4 Condition Flags and Signs:

- A. Warning sign on access road to location.
- B. Flags to be displayed on sign at entrance to location. Green flag indicates normal safe condition. Yellow flag indicates potential pressure and danger. Red flag indicates danger (H2S present in dangerous concentration). Only emergency personnel admitted to location.

5 Well control equipment:

A. See exhibit "E"

6 Communication:

- A. While working under masks chalkboards will be used for communication.
- B. Hand signals will be used where chalk board is inappropriate.
- C. Two way radio will be used to communicate off location in case of emergency help is required. In most cases cellular telephones will be available at most drilling foreman's trailer or living quarters.

7 Drillstem Testing:

No DSTs or cores are planned at this time.

- 8 Drilling contractor supervisor will be required to be familiar with the effects H₂S has on tubular goods and other mechanical equipment.
- 9 If H₂S is encountered, mud system will be altered if necessary to maintain control of formation. A mud gas seperator will be brought into service along with H₂S scavengers if necessary.

H₂S Contingency Plan

Fuggles 24 Federal Com 1H

Cimarex Energy Co. of Colorado Unit D, Section 24 T25S-R32E; Lea County, NM

Emergency Procedures

In the event of a release of gas containing H₂S, the first responder(s) must:

- ★ Isolate the area and prevent entry by other persons into the 100 ppm ROE.
- ★ Evacuate any public places encompassed by the 100 ppm ROE.
- ★ Be equipped with H₂S monitors and air packs in order to control the release.
- ★ Use the "buddy system" to ensure no injuries occur during the response.
- ★ Take precautions to avoid personal injury during this operation.
- ★ Contact operator and/or local officials to aid in operation. See list of phone numbers attached.
- ★ Have received training in the:
 - ♦ Detection of H₂S, and
 - Measures for protection against the gas,
 - ♦ Equipment used for protection and emergency response.

Ignition of Gas Source

Should control of the well be considered lost and ignition considered, take care to protect against exposure to Sulfur Dioxide (SO₂). Intentional ignition must be coordinated with the NMOCD and local officials. Additionally, the NM State Police may become involved. NM State Police shall be the Incident Command on scene of any major release. Take care to protect downwind whenever there is an ignition of the gas.

Characteristics of H₂S and SO₂

Common	Chemical	Specific	Threshold	Hazardous	Lethal
Name	Formula	Gravity	Limit	Limit ***	Concentration
Hydrogen Sulfide	H₂S	1.189 Air=1	10 ppm	100 ppm/hr	600 ppm
Sulfur Dioxide	SO ₂	2.21 Air=1	2 ppm	N/A	1000 ppm

Contacting Authorities

Cimarex Energy Co. of Colorado's personnel must liaise with local and state agencies to ensure a proper response to a major release. Additionally, the OCD must be notified of the release as soon as possible but no later than 4 hours. Agencies will ask for information such as type and volume of release, wind direction, location of release, etc. Be prepared with all information available including directions to site. The following call list of essential and potential responders has been prepared for use during a release. Cimarex Energy Co. of Colorado's response must be in coordination with the State of New Mexico's "Hazardous Materials Emergency Response Plan" (HMER).

H₂S Contingency Plan Emergency Contacts

Fuggles 24 Federal Com 1H

Cimarex Energy Co. of Colorado Unit D, Section 24 T25S-R32E; Lea County, NM

Cimarex Energy Co. of Colora	800-969-4789				
Co. Office and After-Hours M					
Vara Damanana I					
<u>Key Personnel</u> Name	Title	Office		Mobile	
Larry Seigrist	Drilling Manager	432-620-1934	=	580-243-8285	
Scott Lucas	Field Drilling Super	432-020-1334	·	432-894-5572	
Roy Shirley	Field Superintendent	<u> </u>		432-634-3372	
toy shirley	riela Superintendent			432-034-2130	
	CC 8 CC		· -) U Com s 2004 G qual & 2000	
Artesia	د العلم و بشاه و بشاه و بينه و		9 a 4:5	10 600 0 600 0 600 0 600	
Ambulance		911			
State Police		575-746-2703		1 3	
City Police		575-746-2703			
Sheriff's Office		575-746-9888			
Fire Department	575-746-2701				
Local Emergency Planning (575-746-2122				
New Mexico Oil Conservati	575-748-1283				
		i			
<u>Carlsbad</u>		4			
Ambulance		911		,	
State Police		575-885-3137			
City Police		575-885-2111			
Sheriff's Office		575-887-7551			
Fire Department	575-887-6544				
Local Emergency Planning (575-887-6544				
US Bureau of Land Manage	575-887-6544				
Canta Fa					
<u>Santa Fe</u> New Mexico Emergency Re	505-476-9600				
New Mexico Emergency Re	505-827-9126				
New Mexico State Emerger	505-476-9635				
					
<u>National</u>					
National Emergency Respo	800-424-8802				
Medical Flight for Life - 4000 24th S	t · Lubback TV	806-743-9911			
Aerocare - R3, Box 49F; Lub	806-747-8923				
Med Flight Air Amb - 2301	505-842-4433				
	505-842-4949				
D All IVIEU SELVICE - 2303 C	Clark Carr Loop S.E.; Albuquerque, NM	JUJ-042-4343			
Other					
Boots & Coots IWC		800-256-9688	or	281-931-8884	
Cudd Pressure Control	432-699-0139	or	432-563-3356		
Halliburton		575-746-2757			
B.J. Services		575-746-3569	-	·	

