Form 3160-5 (August 2007) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD Hobbs				ON Exp	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an HOBBS OCD abandoned well. Use form 3160-3 (APD) for such proposals				1	2082A	
			<u> </u>	6. If Indian, Allo	ttee or Tribe Name	
SUBMIT IN TRI	PLICATE - Other instruc	tions on reverse sid	e. JAN 2 T	7. If Unit or CA/.	Agreement, Name and/or No.	
1. Type of Well 3. Oil Well 3. Gas Well Oth			RECE		d No. WEST UNIT 006H	
2. Name of Operator MEWBOURNE OIL COMPANY E-Mail: jlathan@mewbourne.com				9. API Well No. 30-025-40 6	05	
3a. Address PO BOX 5270 HOBBS, NM 88241		3b. Phone No. (include a Ph: 575-393-5905 Fx: 575-397-6252	area code)	10. Field and Poo BONE SPR		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Pa	rish, and State	
Sec 9 T26S R32E SESW 150FSL 1650FWL				LEA COUN	TY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE NATU	RE OF NOTI	CE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepen		Production (Start/Resume	e) 🔲 Water Shut-Off	
Subsequent Report	Alter Casing	🗖 Fracture Trea	_	Reclamation	Well Integrity	
_ , .	Casing Repair	□ New Construc		Recomplete	🛛 Other Well Spud	
Final Abandonment Notice	 Change Plans Convert to Injection 	Plug and Aba Plug Back		Temporarily Abandon Water Disposal	· •	
13. Describe Proposed or Completed Ope If the proposal is to deepen directiona Attach the Bond under which the won following completion of the involved testing has been completed. Final Ab determined that the site is ready for fin 12/13/13 Spud 17 1/2" hole. T	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation res pandonment Notices shall be file inal inspection.) D hole @ 1060'. Ran 106	give subsurface locations a the Bond No. on file with I sults in a multiple completi- ed only after all requiremen 0' of 13 3/8" 48# H40	nd measured an BLM/BIA. Req on or recomplet ts, including rec ST&C csg. C	d true vertical depths of all p uired subsequent reports sha ion in a new interval, a Form clamation, have been comple	pertinent markers and zones. Il be filed within 30 days a 3160-4 shall be filed once	
600 sks Econo Cem-HLC w/a Mixed @ 14.8 #/g w/1.34 yd P.M. 12/17/13, tested BOPE 8 Chart & schematic attached.	dditives. Mixed @ 12.5 #/g Plug down @ 7:00 PM 12 k.csg to 1250# for 30 mins	g w/2.12 yd. Tail w/20 /16/13. Circ 117 sks c s, held OK. Drilled out	0 sks HalCer of cmt to the j with 12 1/4."	n-C w/1% CaCl2 pit. At 6:30 bit. M. CEPTED	FOR RECORD	
Bond on file: NM1693 nationw	ide & NMB000919			BUREAN OF	2 0 2014	
14. I hereby certify that the foregoing is	Electronic Submission #2	32258 verified by the E	BLM Well Info	mation System		
For MEWBOURNE OIL CO Committed to AFMSS for processing by Name (Printed/Typed) JACKIE LATHAN			JOHNNY DICKERSON on 04/16/2014 () Title AUTHORIZED REPRESENTATIVE			
				· ·		
Signature (Electronic S		R FEDERAL OR S				
<u></u>					<u> </u>	
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu	not warrant or subject lease Office	Petrol	eum Engineer	Date N 27 2014		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a c	crime for any person knowi	ngly and willfu sdiction.	Ily to make to any department	nt or agency of the United	

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED *

JAN 27 2014

Company MeWBourne	Date/2=17=13	
Lease Red Hills West UNIT OOGH	County Lea N.M.	
8 I	A.	410XH
	ifold Pressure: <u>19.50</u> Annular P	

MAN WELDING SERVICES, INC

Accumulator Function Test - OO&GO#2

To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)

- Make sure all rams and annular are open and if applicable HCR is closed.
- Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
 - 1. Open HCR Valve, (If applicable)
 - 2. Close annular.
 - 3. Close all pipe rams.
 - 4. Open one set of the pipe rams to simulate closing the blind ram.
 - 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
 - 6. Record remaining pressure 1800 psi. Test Fails if pressure is lower than required.
 - a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system } 7. If annular is closed, open it at this time and close HCR.
 - 7. It minimal is closed, open it at this time and close HCK.

To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure: a. [800 psi for a 1500 psi system] b. [1100 psi for 2000 and 3000 psi system]
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
 - 3. Record pressure drop <u>750</u> psi. Test fails if pressure drops below minimum.
- Minimum: a {700 psi for a 1500 psi system } b. {900 psi for a 2000 & 3000 psi system}

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off value to the tank, {manifold psi should go to 0 psi} close bleed value.
 - 1. Open the HCR valve, {if applicable}
 - 2. Close annular


o


- 3. With pumps only, time how long it takes to regain the required manifold pressure.
- 4. Record elapsed time $\frac{1.15}{5}$. Test fails if it takes over 2 minutes.
- a. (950 psi for a 1500 psi system) b. (1200 psi for a 2000 & 3000 psi system)

WELDING + BOP TESTING NIPPLE UP SERVICE + BOP LIFTS + TANDEM MUD AND GAS SEPARATORS WELDING SERVIC Pg. _ of 1 Lovington, NM . 676-388-4540 company Mew But De Invoice #B 6262 Date: 12-17-13 Lease Rod Hill - Westunit at H - Attenson UT 36 -Inng Cu ancian 12 X H Plug Size & Type: Installed BOP 2000 Appropriate Casing Valve Hust Bo Open During BOP Test d To Test Kill Line Valves * * Check Valve Must Bo Op /Disab Dart Valva #19 fic bach Stand Pipe Valve #24 Annular #15 Tor Driv TIW Valve #18 150P Pipe Rums #12 øЗ Blind Rams #13 [مد] ₩00⊐ Mud Gauge Valve Manual IBOP #16 ાજીવ 幼 **DE**IN C Pump Val Pump Valve #21 0 milit 3Î 121 #11 #10 #25 Ē Pipe Rams #14 =')' Super Choke Casing TEST LONGTH LOW PSI HIGH PSI 10 /10 250 1250 **NEMARKS** ITEMS TESTED TEST !! Value uffer Kelly 250 10 Rins led c 10 hec I 1 18 10 10 19 3 10 Ő 30 30 30 30 4 Ŷ 15, 30 30 5 5.10,8 15,11,3,4,5 15,11,1,6,2 Ð 6 Palcheckyalve Back IN 7 30 Bin test 5,11,25,6,26 8

•

•





•

•

. . .

