State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary Jami Bailey, Division Director Oil Conservation Division



February 13, 2014

HOBBS OCD

Mr. Mark Plummer Chestnut Exploration and Production, Inc. 2201 North Central Expressway, Suite 240 Richardson, TX 75080

RECEIVED

FEB 1 8 2014

RE: Packer Setting Depth Exception

Injection Authority: Administrative Order SWD-326

Pool: SWD; Seven Rivers formation

D & E Federal Well No. 1 API 30-025-02448

Unit N, Sec 22, T20S, R34E, NMPM, Lea County, New Mexico

Mr. Plummer:

Reference is made to your request on behalf of Chestnut Exploration and Production, Inc. (OGRID 262294; "Chestnut") received by the Division on January 13, 2014, for the above named well. Chestnut applied for exception for setting the packer within 100 feet of the top of the approved injection interval.

It is our understanding that during the completion of a mechanical integrity testing conducted in January on this well that the packer set was determined to be at a depth of 3308 feet. The packer was installed at this location in order to achieve proper seating of the packer set. This location of the packer is approximately 170 feet above the top of the perforated injection interval that begins at 3478 feet. Administrative Order SWD-326 approved July 20, 1987, authorized injection through perforations from 3478 feet to 3496 feet and through open hole from 3533 feet to 3690 feet.

For the reasons stated in the application and because it appears that correlative rights are protected, waste will not occur and this modification will not endanger any fresh water aquifer or the environment, the exception is granted. The packer location within this well shall not be set higher than 170 feet unless the operator receives written approval from the Division Director.



Packer Setting Depth Exception Chestnut Exploration and Production, Inc. February 13, 2014 Page 2 of 2

The Division Director may rescind this exception if it becomes apparent that the injected fluid is not being confined to the permitted interval or is endangering any fresh water aquifer.

Sincerely,

JAMPBAILEY

Director

JB/prg

cc: Oil Conservation Division - Hobbs Office

SWD-326

Well File API 30-025-02448

United States Bureau of Land Management - Carlsbad Office