

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-03222
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Injection Well <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator State of NM formerly Xeric Oil & Gas Corp.		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N French Drive Hobbs, NM 88240		7. Lease Name or Unit Agreement Name East Pearl Queen Unit
4. Well Location Unit Letter F : 1980 feet from the North line and 1980 feet from the West line Section 27 Township 19S Range 35E NMPM County Lea		8. Well Number 26
		9. OGRID Number
		10. Pool name or Wildcat Pearl Queen
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6-05-13 MIRU. POOH w/ tbg & pkr.

6-06-13 GIH w/ tbg. Tag at 4666'. Spot 25 sx. WOC. Tag at 4723'. Spot 25 sx at 4723'. WOC.

6-07-13 Tag at 4339'. POOH to 3347'. Spot 25 sx cmt. WOC. Tag at 3166'. Perf at 1750'. Sqz w/ 25 sx cmt. WOC.

6-10-13 Tag at 1676'. Perf at 354'. Circ 100 sx cmt to surface inside/outside 5 1/2" csg. Install dry hole marker.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Mah White

TITLE

Compliance Officer

DATE

02/13/2014

Type or print name

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

Mary Brown

TITLE

Compliance Officer

DATE

2/14/2014

Conditions of Approval (if any)

FEB 18 2014

RPM
dm