
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-200

FILE IN TRIPLICATE	HOBBS OF TOOMSERV	ATION DIVISION		Revised 5-27-2004
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240	1220 50411	St. Francis Dr. NM 87505	WELL API NO. 30-025-28343	
<u>DISTRICT II</u>	FEB 1 4 2014 Santa Fe,		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE STATE	FEE X
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	RECEIVED		6. State Oil & Gas Lease No.	
	TICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agreen	nent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			South Hobbs (G/SA) Unit	
1. Type of Well: Oil Well X	Gas Well Other		8. Well No. 140	
2. Name of Operator		"	9. OGRID No. 157984	/
Occidental Permian Ltd. 3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	79323			
4. Well Location				
Unit Letter L 1485	Feet From The South	Line and 1245 Fee	t From The West	Line
Section 4	Township 19-S	Range 38-I	E NMPM	Lea County
	11. Elevation (Show whether DF, RF 3605' GL	KB, RI GR, etc.)		
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction Ma	terial	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTE	ENTION TO:	SUBS	SEQUENT REPORT O	F:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERINO	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	NS. PLUG & A	BANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	NT JOB	
OTHER:		OTHER: ESP repair/C	CO	X
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RUPU & RU. RU wire line & perforate tubing @3995'. RD wire line. ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag TD @4210'. POOH w/bit. RIH w/ESP equipment set on 124 jts of 2-7/8" tubing. Intake set @4030' ND BOP/NU well head. RDPU & RU. Clean location and return well to production. 				
RUPU 10/09/2013 RDPU 10/14/2013				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or				
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	e OCD-approved	
SIGNATURE SIGNATURE DATE 02/13/2014				
TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280				
For State Use Only	<i>y D D D D D D D D D D</i>	/ h	~ 0 A 1	- 1 1
APPROVED BY	Hown	_ TITLE COMOLE	ance Officers	120/2014
CONDITIONS OF APPROVAL IF ANY			W	7 /

Work Plan Report for Well:SHOU-140L04



Survey Viewer