Submit 3 Copies To Appropriate District  Office  State of New Mexico  Office  Energy Minerals and Natural Resources				Form C-103			
District 1					irces	June 19, 2008 WELL API NO.	
1625 N. French Dr., Hobbs, NM 87240 District II OIL CONSERVATION DIVISION OIL CONSERVATION DIVISION					ION	30-025-41578	/
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.					5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505						STATE X FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505						6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7. Lease Name or Unit Agreement Name:  North Hobbs G/SA Unit		
1. Type of Well: Oil Well X Gas Well Other					8. Well Number 948		
2. Name of Operator						9. OGRID Number	_
Occidental Permian Ltd.					157984	V	
3. Address of Operator					10. Pool name or Wildcat	,	
P.O. Box 4294, Houston, TX 77210-4294  I. Well Location					Hobbs: Grayburg-San Andres	/"	
Unit Le	tter <u>F</u> :	<u>2094</u> f	eet from the Nor	rth 1	ine and	1963 feet from the West line	
Section	33	Т	ownship 18-S	Range	38-E	NMPM County Lea	
		11. Eleva	ition (Show whether 364)	<i>DR, RKB,</i> L.9' GR	RT, GR, etc	c.)	
	12 Check Ar	nronriate	· · · · · · · · · · · · · · · · · · ·		f Notice F	Report, or Other Data	
	12. Check Ap	ppropriate	Dox to maleate	i vature o	i Notice, i	report, or Other Data	
NOTICE OF INTENTION TO:					SEQUENT REPORT OF:		
ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK						☐ ALTERING CASING ☐	
EMPORARILY ABANDON					NCE DRILLI	ING OPNS. P AND A	
ULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMENT J					<del></del>		
OWNHOLE COMMINGLE							
O VIII IOLL V		•					
THER:				OTHER:	Spud & R	Run Surface Casing	
13. Describe	proposed or completed	operations.	. (Clearly state all pe	rtinent det	ails, and giv	ve pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion							
or recom	pletion.					HOBBS OCD	
						MAR 1 1 2014	
			See At	tached		Condition on Post	
See Australia						RECEIVED	
						KEON A PE	
	3/2/14						
pud Date:	oud Date: 3/2/14 Rig Release Da		se Date:				
nereby certify	that the information al	bove is true	and complete to the	best of my	y knowledge	e and belief.	
IGNATURE.	Mark 5h	ephen	TIT	LE_Regul	atory Com	pliance Analyst DATE 3/11/14	
ype or print name Mark Stephens E-mail address: E-mail address:						ephens@oxy.com PHONE (713) 366-5158	
or State Use	Only			A	Detre lemma	rEngineer MAR 18 20	14
PPROVED E		we)	د TIT		CHUICHI	DATE MAR 50	
	Approval (if any):			As ingian	A STATE OF THE PARTY OF THE PAR	the state of the s	

Page 2 (C-103 Attachment)

North Hobbs G/SA Unit No. 948 API No. 30-025-41578

3/1/14 -

3/2/14: MI x RU.

3/2/14: Spud 12-1/4" hole at 7:00 p.m. (NMOCD notified).

3/2/14 -

3/6/14: Drill 12-1/4" surface hole to 1638'. Rig up CRT and run 39 jts. 9-5/8", 36#, J-55, ST&C casing with 11 centralizers and set at 1638'. RU Halliburton x cement with 450 sx., 13.5 ppg. Premium Plus (lead) and 200 sx., 14.8 ppg. Premium Plus (tail). Circulate 269 sx. to surface. Cut off casing x weld on wellhead. Test weld to 1400 psi. NU BOP stack. Test BOP's and related equipment to 3000 psi. Test casing to 1800 psi x 30 min. Drill out x tag cement at 1500'. Drill cement x float equipment to 1638'. Commence directional drilling of 8-3/4" production hole.