HOBBS OCD

For Wedge Of Conservation Division, Righting [

Form 3160-5 (March 2012) APR 08 2014 UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** 2025 M. French Drive Partez NO. 88240

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No. LC-062486 6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.						
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well					0.11/ (1.51	
Oil Well Gas Well X Other					Well Name and No. Drickey Queen Sand Unit #837	
2. Name of Operator Celero Energy II, LP					9. API Well No. 30-005-10158	
3a. Address 3b. Phone No. (include area code)					10. Field and Pool or Exploratory Area	
400 W. Illinois, Ste. 1601 Midland TX 79701 (432)686-1883					Caprock; Queen	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) (B) Sec 4, T14S, R31E					11. County or Parish, Sta	
(B) Sec 4, 1145, R31E 1320' FNL & 2475' FEL					Chaves, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA						
TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent	Acidize	Deepe	en	Produ	Production (Start/Resume) Water Shut-Off	
	Alter Casing	Fractu	ire Treat	Recla	mation	Well Integrity
X Subsequent Report	Casing Repair	New (Construction	Reco	mplete Other	
Subsequent report	Change Plans	X Plug a	and Abandon	Temp	orarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug I	Back	Wate	r Disposal	
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 3/17/14 - Install 4 1/2" x 2 3/8" WH, NUBOP. Ran 2 3/8" tbg WS with 2 3/8" x 4' BPPS to 285'. Unable to go deeper. Tie onto tbg and circulate hole. TOH w/ tbg, remove, BPPS and ran tbg w/ 3 1/4" bit. Tag at 285' & lower to 287'. Unable to go deeper. TOH w/ bit. TIH w/ 3 1/2" OD impression block. Ran to 287'. 3/18/14 - TIH w/ 3 3/4" bit, 4 - 3 1/8" OD drill collars and 2 3/8" OD tbg WS. Tag at 287'. D/O bridge in 4 1/2" csg from 287 to 292'. Ran & tag at 2750'. Circ hole clean. Pulled 1 joint to 2718". 3/19/14 - POH with tbg, LD DC's & bit, welder patched hole in csg at the surface. RIH with 3.5" GR tag at 2750'. RIH with 4 ½ CIBP, tag at 2750', set plug. POH, RIH with OE tbg, tag plug at 2750'. Circ with 9.5# salt gel attempt to pressure casing. Psi to 300#, had another leak in the csg at surface. Spot 25 sks cmt on top of CIBP. POH, WOC 2 hrs. PU, RIH with 4 1/2 pkr to 64', set and pressure csg to 200#, leaked off to 0 psi 3 min. Release pkr, run to and set at 315', psi to 200#. Still had same leak 0 psi in 3 min. Release pkr POH. RIH and set at 64', psi csg to 200# same leak 0 psi 3 min. Release pkr, POH. *Continued on attached sheet						
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)					, AS,	R 0 4 2014
Lísa Hunt			Title Regula	tory Anal		Angel Mayes
Signature Lisa	Hund		Date 03/27/2		Mare	
THIS SPACE FOR FEDERAL OR STATE OFFICE USEAssistant Field Manager						
Approved by				1.	Lands,	And Minerals
			Title		Da	
Conditions of approval, if any, are attached hat the applicant holds legal or equitable t intitle the applicant to conduct operations	itle to those rights in the subject le		ertify	R	SWELL FIELD C	
Title 18 U.S.C. Section 1001 and Title 43	IISC Section 1212 make it a cri	me for any ne	reon knowingly a	nd willfully to	make to any department	or agency of the United States any false

Drickey Queen Sand Unit #837 - C103 continued

<u>3/20/14</u> - RIH with bull plug on end of tbg, tag cmt at 2378'. POH stand back 1700', LD the rest. RIH with 4 1/2 pkr to 1700', circ well with 9.5# salt gel set packer. Perf 4 shots at 1950'. Had gas and pressure at surface, pump up packoff, secure well make sure all connections are good for flowback open well through choke had very little gas and small amount of fluid. RU attempt to pump into perfs at 1950' pressured up to 1000 to 1500 psi could not pump into perfs. BLM per Bob Hoskinson approved to spot 25 sk plug at 2000'. Release pkr, POH. Run in with OE tbg to 2016', circ bottoms up clean, pump 25 sk cmt. Spot at 2000' had circulation throughout job, pull tbg, PU pkr, run and set at 1000'.

<u>3/21/14</u> - Tag cement plug at 1574'. POH. Perf 4 1/2 csg at 1200' (no pressure). POH, attempt to pump into perforations, pressured to 1200 psi. BLM said we could spot 25 sk 50' below. Release pkr, POH. RIH with open end tubing to 1250', circulate with 9.5# salt gel, spot 25 sks cmt. Had circulation throughout job, pull tubing.

3/24/14 - WOC 65 hrs. Lower tbg and tag TOC at 724'. TOH w/ tbg. Perf 4 1/2" casing w/ 1 11/16" strip jet gun, 4 - 12.5 gram shots per foot at 152'. TIH w/ tbg & 4 1/2 " pkr. Ran to 60'. Pumped down tbg thru perfs at 152' w/ 5 BPW. Had good circulation out 4 1/2" x 8 5/8" annulus. TOH w/ pkr. TIH w/ tbg open ended to 224'. Pump 70 sx of Class "C" cmt w/ 2% CaCl2 and circ 50 sx of cmt out 4 1/2" x 8 5/8" annulus and filled the 4 1/2" csg with 20 sx of cmt. LD tbg, NDBOP & NDWH. WOC.

3/26/14 - Dug out cellar. Cut off WH's & 4 ½" & 8 5/8" casings. Weld on dry hole marker. Remove well anchors. Well is now P&A'd.