

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources  
**HOBBS OCD**  
**OIL CONSERVATION DIVISION**  
220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised August 1, 2011

<b>RECEIVED</b>	
<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	WELL API NO. 30-025-03250
2. Name of Operator State of New Mexico formerly Xeric Oil & Gas Corp	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240	6. State Oil & Gas Lease No.
4. Well Location Unit Letter <u>  M  </u> : <u>  660  </u> feet from the <u>  South  </u> line and <u>  660  </u> feet from the <u>  West  </u> line Section <u>  29  </u> Township <u>  19S  </u> Range <u>  35E  </u> NMPM <u>  Lea  </u> County <u>  </u>	7. Lease Name or Unit Agreement Name West Pearl Queen Unit
	8. Well Number <u>  130  </u>
	9. OGRID Number 25482
	10. Pool name or Wildcat Pearl Queen
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**  
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

**SUBSEQUENT REPORT OF:**  
REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒ XX  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/30/2014 MIRU and installed BOP. Released packer.

5/1/2014 Laid down 34 jts of 2 3/8" tubing. RIH with work string and scrapper to 4778'. POOH and RIH with 4 1/2" CIBP. Set CIBP at 4750'. Circulated MLF and spotted 25 sx cement on CIBP. POOH to 3510' and spotted 25 sx cement. POOH and SION.

5/2/2014 RIH and tagged at 3199'. POOH and spotted 25 sx cement at 1950'. WOC and tagged at 1577'. Confirmed hole in 4 1/2" casing at 1115'. Could pump into hole but would pressure up. RIH to 1170' and spotted 25 sx cement. SION.

5/5/2014 RIH and tagged at 1101'. Spotted 25 sx cement at 1101'. WOC and tagged at 802'. Perforated at 200. Established circulation and pumped cement down 4 1/2" casing to perfs at 200' and up annulus to surface. Pumped 60sx but no cement to surface. Rigged down.

5/6/2014 Cut off wellhead and one inched annulus to surface from 60'. Filled up 4 1/2" casing to surface with cement. Installed marker and cut off anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_

**For State Use Only**

APPROVED BY: Mary Brown TITLE: Dist Supervisor DATE: 5/14/2014  
Conditions of Approval (if any):