Form 3160-5 (March 2012)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No. NMLC-030174B

6. If Indian, Allottee or Tribe Name

## SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

SUBMIT IN TRIPLICATE – Other instructions on page 2.				Jnit of CA/Agreer	nent, Name and/or No.		
1. Type of Well			MAY 0 1 (088	1137 137			
	- injection			al NCT 1 #008			
2. Name of Operator PPC OPERATING COMPANY LLC			9. AP 30-0	I Well No. 25-12055			
3a. Address 500 Industrial Blvd, Ste. 102			nclude area codBECEIVELO. Field and Pool or Exploratory Area				
Abilene, TX 79602 325-267-604				Rhodes; Yates-Seven Rivers			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 60' FSL & 660' FWL, UNIT LETTER "M", SECTION 26, T-26S, R-37E, NMPM				11. County or Parish, State LEA COUNTY, NEW MEXICO			
12. CHEC	CK THE APPROPRIATE BO	X(ES) TO INDICATE N	ATURE OF NOTICE, RE	PORT OR OTHE	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION .						
✓ Notice of Intent	Acidize	Deepen	Production	roduction (Start/Resume) Water Shut-Off			
	Alter Casing	Fracture Treat	Reclamation	ı	Well Integrity		
Subsequent Report	Casing Repair	New Constructi	on Recomplete		Other		
	Change Plans	Plug and Aband	on 🔲 Temporarily	Temporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Water Dispo	osal			
testing has been completed. Final determined that the site is ready for this is to notify that this well was provas scheduled for a workover (also shallow casing leak. Operations we hallow casing leak. Operations we hallow casing set at 1177' ce 1/2" production casing set at 3158 in liner set at 3255' set 20 feet up in 2 3/8" tubing & packer set at 3022' A backhoe was brought to location coints of 5 1/2" casing with 5 1/2, 15. The well has been shut-in since 4/5/	r final inspection.) essure tested on 4/5/2013 scheduled with the NMOC ere shut down to await instremented to surface w/ 350 to cemented with 300 sx to 5 1/2" casing.  on 1/3/14. There is a shalk 1.5#, J=55, ST&C casing.	(NMOCD was notifed 4 D). Jesse Madrid cont uctions from the BLM.  sx cement  by hole in the 5 1/2" catecause the 5 1/2 is high	sing 5 feet from ground her than the 8 5/8 casir	Il failed and was rning to notify th 	immediately shut-in. The at the well apparently had at the well apparently had been solved to be to able to bring the TOC to	e well s a	
					•		
I hereby certify that the foregoing is trans Spraberry	rue and correct. Name (Printea		fice Adminstrator	AF	PPROVED		
Signature Sen	Carrydon	Date 0	1/03/2014		AY 1 6/2019/		
	THIS SPACE	FOR FEDERAL O	R STATE OFFICE	USE //	mail II	DO	
Approved by	•			BURÉAU ARL	OF LAND MANAGEMEN SBAD FIELD OFFICE		
		Titl	e	D	ate		

(Instructions on page 2)

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

MUB/OCD 5/22/2014

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

Office

### Conditions of Approval PPC Operating Company LLC W H Rhodes B NCT 1 - 08 API 30-02512055, T26S-R37E, Sec 26 May 16, 2014

#### Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

#### Work to be completed by August 16, 2014.

- 1. Subject to like approval by the New Mexico Oil Conservation Division.
- 2. Surface disturbance beyond the existing pad shall have prior approval.
- 3. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 4. Functional H<sub>2</sub>S monitoring equipment shall be on location.
- 5. 2000 (2M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. A ram system including a blind ram and pipe ram(s) designed to close on all of the work string(s) used is required equipment. Manual BOP closure (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 6. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Determine top of cement behind the 5 ½" casing. Submit results to BLM. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 3100 or below to top of cement. The CBL may be attached to a <a href="mailto:pswartz@blm.gov">pswartz@blm.gov</a> email.
- 8. If more than the top two joints are replaced operator must obtain approval from the BLM. Any replaced  $5\frac{1}{2}$  csg is to conform to grade, weight, and coupling per the approved NOI.
- 9. Cement from TOC to top of surface casing.
- 10. Conduct a Mechanical Integrity Test as described on the next page.

#### Well with a Packer - Operations

- 1) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established. Repair that seal any time more than five barrels of packer fluid is replaced within 30 days.
- 2) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- 3) Document the pressure test on a one hour full rotation calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.
- 4) Make arrangements 24 hours before the test for BLM to witness. In Lea County phone 575-393-3612. If no answer, leave a voice mail or email with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 5) Submit a subsequent Sundry Form 3160-5 relating the MIT activity. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness, or the notified person and date of notification. NMOCD is to retain the original recorded MIT chart.
- 6) Use of tubing internal protection, tubing on/off equipment just above the packer, a profile nipple, and an in line tubing check valve below the packer or between the on/off tool and packer is a "Best Management Practice". The setting depths and descriptions of each are to be included in the subsequent sundry. List (by date) descriptions of daily activity of any previously unreported wellbore workover.
- 7) Submit the original subsequent sundry with three copies to BLM Carlsbad.
- 8) Compliance with a NMOCD Administrative Order is required, submit documentation of that authorization.
  - a) Approved injection pressure compliance is required.
  - b) If injection pressure exceeds the approved pressure you are required to reduce that pressure and notify the BLM within 24 hours.
  - c) When injection pressure is within 50 psig of the maximum pressure, install automation equipment that will prevent exceeding that maximum. Submit a subsequent report (Sundry Form 3160-5) describing the installed automation equipment within 30 days.
- 9) Unexplained significant variations of rate or pressure to be reported within 5 days of notice.
- 10) The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity. A BLM inspector may request verification of a full annular fluid level at any time.
- 11) A "Best Management Practice" is to maintain the annulus full of packer fluid at atmospheric pressure. Equipment that will display on site, continuous open to the air fluid level is necessary to achieve this goal.

- 12) Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Carlsbad Field Office, Petroleum Engineering within 5 days.
- 13) A suggested format for monthly records documenting that the casing annulus is fluid filled is available from the BLM Carlsbad Field Office.

Submit a original and three copies of (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test as per item 1) above. Include the date(s) of the well work, and the setting depths of installed equipment: internally corrosive protected tubing, tubing on/off equipment just above the packer, and an in line tubing check valve below the packer or between the on/off tool and packer. The setting depths and descriptions of each are to be included in the subsequent sundry. List daily descriptions of any previously unreported wellbore workover(s) and reason(s) the well annular fluid was replaced.

**JAM/PRS 051614**