Submit I Copy To Appropriate District Office District I = (575) 393-6161 State of New Mexico Energy, Minerals and Natural Resou	Form Q-103 rces Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II ~ (575) 748-1283 81 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION OF CONSERVATION OF CONSERVATION DIVISION OF CONSERVATION DIVISION OF CONSERVATION OF CONSERVATION OF CONSERVATION DIVISION OF CONSERVATION OF CONSERVATION DIVISION OF CONSERVATION OF CONSERVATION DIVISION OF CONSERVATION DIVISION OF CONSERVATION DIVISION OF CONSERVATION OF CONSERVATION DIVISION OF CONSERV	ON 5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec; NM 87410 Santa Fe, NM 87505	STATE FEE 🗆
1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	8. Well Number 2
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator Brammer Engineering, Inc	9. OGRID Number
Brantiner Engineering, inc	305165
Address of Operator 400 Texas Street, Suite 600, Shreveport, LA 71101	10. Pool name or Wildcat
4. Well Location	
Unit Letter 0 : 330 feet from the South line and 1330 feet from the East line	
Section 4 Township 23S Range 37E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3307' GR	
12. Check Appropriate Poy to Indicate Nature of Natice. Percent of Other Date	
12. Check Appropriate Box to Indicate Nature of Notice, Report of Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	AL WORK ☐ ALTERING CASING ☐ NCE DRILLING OPNS.☐ P AND A 🗵
	CEMENT JOB
DOWNHOLE COMMINGLE	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
4/15/2014 Mix and pump 65 sxs of Class C to set plug #1 at 1088-1400'.	
Mix and pump 26.5 sxs of Class C to set plug #2 at 988-1088'.	
Mix and pump 26.5 sxs of Class C to set plug #3 at 38-138'. 4/16/2014 //nstall.dry hole tree and release rig. Make decision whether to permanently plug or not.	
5/2 <u>1/2014</u> Cut off 8-5/8" casing 6' BGL and weld on 1/4" steel plate cap and 4" x 10' abandonment post on top.	
P & A completed.	
,	
	
Spud Date: 4/9/2014 / Rig Release Date:	4/16/2014
<u> </u>	
I hereby certify that the information above is true and complete to the best of my ki	nowledge and belief.
1 1	
SIGNATURE DATE 8/6/2014 SIGNATURE DATE 8/6/2014	
Type or print name Adonya Dryden E-mail address: adonya.dryden@brammer.com PHONE: 318-429-2277 For State Use Only A A	
APPROVED BY: MANUEL Superior Dist. Superior Date 8/6/2014	
Conditions of Approval (if any):	