Submit 1 Copy To Appropriate District Office	State of New Mexi	Form C-103					
District I – (575) 393-6161	Energy, Minerals and Natural	Revised July 18, 2013 WELL API NO.					
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OH CONCERNATION D	· - 1					
811 S. First St., Artesia, NM 88210							
	·		STATE FEE				
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 8750	05	6. State Oil & Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM 87505		NA					
SUNDRY NO	TICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name				
PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR	босн					
1. Type of Well: Oil Well	Gas Well 🗵 Other Swb		8. Well Number 1				
2. Name of Operator			9. OGRID Number 244835				
			10 De-1 Wilder Manager CA				
	.5		10. Pool name or wildcat Monument SA				
	220 fact from the	line and	1090 foot from the E line				
		-					
Section 8		<u> </u>					
	11. Elevation (Snow whether DR, Ro	XD, K1, GK, etc.)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
		,	•				
-	- I						
	— — — — — — — — — — — — — — — — — — —						
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PAND COMMENCE DRILLING OPNS. PAND PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB COMMENCE COMMINGLE COMMINGLE OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, included the complete dates.)			-				
	_	ASING/CEMEN	I JOB				
		THER:					
of starting any proposed v	ork). SEE RULE 19.15.7.14 NMAC.						
	•	notified.					
Work began to repair on 7-7-	14. a complete description of work attac	hed, with schema	atic.				
,, 	- · · · · · · · · · · · · · · · · · · ·		HOBBS GCD				
	OCT A 4 9666						
**Would like to keen well SI	UCI 01 Z014						
would like to keep well SI							
	SURMIT- CION IN	TENT	RECEIVED				
	SOMILITIES	al no P	ρ/Δ				
	S. Fines, A. H. S. M. M. SELO S. FINES, A. H. S. M. M. SELO S. FINES, A. H. S. M. M. SELO S. M. M. SELO S. M. M. SELO S. M. M. S. S. M. S. M. S. M. S. M. S. S. M. S. M. S. M. S. M. S. S. M. S. S. M. S. M. S. S. M. S. S. M. S. M. S. M. S. M. S. S. M. S. S. M. S.						
· · · · · · · · · · · · · · · · · · ·							
Spud Date:	Rig Release Date:						
<u> </u>							
I hereby certify that the information	above is true and complete to the best	of my knowledge	e and belief.				
0	1						
SIGNATURE ZILL W	TITLE Agent		DATE 9/29/2014				
SIGNATURE COSTS	TITLE Agent	<u></u>	DATE 9/29/2014				
Type or print name <u>Eddie W. Sea</u>	E-mail address: sea	y04@leaco.net	PHONE: <u>575-392-2236</u>				
For State Use Only			, 1				
APPROVED BY:	KLAUTA STITLE DiAT	5.00.	KAND DATE INLIZAND				
	THE THE	3. Super	DAIE 1017				
	ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB CASING/CEMENT						

7-7-2014

Miru. Tyler Pulling unit nipple down well head and nipple up blow out preventer. OP release paker in 4 hours lay down 12 joints and had holes in 3 of those joints. Shut down over night

J Cooper Enterprises

7-8-2014

Continue trip out of the hole laying down 3 1/2" tubing laid down 35 joints with holes and 107 of good joints. Shut down over night

J Cooper Enterprises

7-9-2014

Unload and rack up joints of 3 1/8' EUE 8rd 9.3# J-55 tubing Pick up arrow set packer trip in hole. Picking up 3 $\frac{1}{2}$ " tubing to 4255' and set packer. Unable to load casing with 100 barrels packer fluid. Shut down over night

J Cooper Enterprises

7-10-2014

Stood by wireline truck from 9:00 am until 12:00 Pick up 2 313 profile plug. TIH and set plug in packer unable to lock plug in packer in 2 runs. Relief arrow set packer trip out of hold with 3 ½" tubing and packer. SDON

J Cooper Enterprises

7-11-2014

Continue trip in hole with tubing to 4253 and set retrievable breech plug pull up hole and set packer at 4220'. Set packer test RBP to 1000# and lost 120# in 7 min. Move plug to 4237' and set RBP and packer at 4220' and test to 800# and lost 60# in 3 min. drop s.v. and test tubing to 1000# (ok) move RBP to 4220' and set packer at 4183' and test to 1000# and lost 300# in 45 min. Move RBP to 4205' and packer at 4183' and test to 940# and lost 100# in 4 min. Move RBP to 4188' and packer to 4150' and test to 950# and lost 100# in 5 min. Move RBP to 4156' and packer at 4118' and test to 950# and lost 100# in 4min. Move RBP to 4091' and packer to 4052' and test to 900# and lost 50# in 3 min. Move RBP to 4027' and packer to 3988' test to 950# and lost 100# in 5 min. Move RBP to 3707' and packer to 3668' and test to 1000# and lost 130# in 4 min. Run in hole to 4188 and set RBP pull up hole to 3517' and test to 940# and lost 120# in 5 min. Pull up hole with packer to 2549' and set packer and test to 900# lost

110# in 5 min. PUH with packer to 1582' and test to 1000# lost 1000# in 1 min. RIH with tubing to 1810' and on vacc. At .2 bpm. Run in hole to 2003' and on vacc at .5 bpm. Run in hole to BMT 2132' and set packer test to 940# and lost 100# in 4 min. Pull up hole to 2068' and set packer and on vacc .2 bpm. RIH and set packer at BTM 2099' and set packer test to 920# lost 90# in 7 min. Pull up hole to 2068' and set packer load casing and test still had leak.

J Cooper Enterprises

7-14-2014

Anderson #1 SWD

Pull up hole to 1745 set packer and unable to load casing. Pull up hole to 1419 set packer unable to load casing. Trip out of hole with tubing and compression packer. Rig up tension packer. Trip in hole to 1419 and set packer unable to load casing. Release packer PUH to 1096' set packer test casing to 500# and lost 50# in 5 min. Release packer RIH to 1225' and set packer. Test casing to 500# lost 500# in 5 min. PUH to 1159' set packer test casing to 550# for 15 min (ok) Isolate casing leak between (1159'-2099') 940'

J Cooper Enterprises

7-15-2014

Rig up cased hole Wireline truck Gamma gun and 4 3/4" CIBP. TIH and pull correlation log to 3200' and set CIBP at 4300' TOH rig down wire line. TIH with 3 %" IPC tubing. TOH laying down 3 %" tubing . Shut down over night

J Cooper Enterprises

7-16-2014

Shut down

J Cooper Enterprises

7-17-2014

Set Frac tank and half tank lay line from 8 5/8" to tank

7-18-2014

RU Basic Energy Services and sqz. 5 ½" casing with 20 bbl liquid glass and 200 sks. Thixotropic cmt mixed at 14.8# ppg and displace with 23.8 bbl FW. CWI and shut down over night

J Cooper Enterprises

7-21-2014

Pick up 4 ¾" bit and bit sub. TIH with tubing to 1325' and tag cmt. RUP reverse unit and unable to cir hole with 100 BFW. TOH with tubing and bit CWI and shut down over night. Waiting on cmt.

J Cooper Enterprises

7-22-2014

Stood by for Basic until 11:00 am. Rig up and pump 20 bbl liquid glass and 200 sks thixotropic mixed at 13.2 ppg and 300 sks. CLS "C" neat cmt with 2% ccl. Mixed at 4.8 ppg and 12 bbl FW behind wiper plug. All down 5 ½" casing CWI and SDON

J Cooper Enterprises

7-23-2014

Nipple down plug head and nipple up BOP. Pull up 4 $\frac{3}{4}$ " bit TIH with tubing to 1252' and tag top of cement TOH with tubing and bit. Nipple down BOP and nipple up 5 $\frac{1}{4}$ " plug head. CWI and SDON

J Cooper Enterprises

7-24-2014

Rig up Basic Energy Services and pump 20 bbl liguid glass and 200 sks Thixotropic mixed at 13.2 ppg and 200 sks. Cls "c" neat mixed at 14.8 ppg and 100 sks . Cls "c" neat mixed at 14.8 ppg and 2% CCL and displaced with 8 BFW behind wiper plug. CWI and SDON

J Cooper Enterprises

7-25-2014

Nipple down plug head and nipple up BOP. Pull up 4 %" bit, TIH with tubing to 1251' and tag top of cmt. Had 1' of fill. Rig up reverse unit. Broke cir out tubing at 3.9 bpm with ½ BPM returns. TOH with tubing and bit. CWI and SDON

7-26-2014

Rig Up Basic Energy Services. Pump 20 bbl liquid glass and 200 sks Thixotropic mixed at 13.2 ppg and 200 sks Cls "Ĉ" neat mixed at 14.8 ppg and 2& CCL Displaced with 8 BFW behind wiper plug. CWI and SDON

J Cooper Enterprises

7-28-2014

Nipple down plug head and nipple up BOP. Pull up $4 \, \frac{3}{4}$ " bit. TIH with tubing to 1245' and tag cmt top. Rig up reverse unit and load hole with 30 BFW. Was losing 1 $\frac{1}{2}$ BPM while cir. Shut tubing valve and pump into leak at 2 bpm at 300# TOH with tubing and bit. Nipple down BOP and nipple up 5 $\frac{1}{2}$ " plug head. CWI and SDON

J Cooper Enterprises

7-29-2014

Rig up Basic Energy Services. Pump 20 bbl liquid glass and 200 sks Cls "C" with 690 gel and 590 salt and 3 PPS kol-seal mixed at 12.5ppg and 400 sks Cls "C" neat mixed at 14.8 ppg and 100 sks cls "C" with 2% CCL mixed at 14.8 ppg 0" to 290" to 0" while pumping cmt. Displaced with 6 BFW. Rig down Basic CWI and SDON

J Cooper Enterprises

7-30-2014

Nipple down plug head and nipple up BOP. Pull up 4 $\frac{1}{4}$ " bit TIH with tubing and tag top of cmt at 1225′. Rig up reverse unit and load hole with 18 BW cir. Hole at 2 $\frac{1}{4}$ " bpm with 1 $\frac{1}{4}$ " BBL. Returns shut in for 30 min and took $\frac{1}{4}$ bbl to regain cir shut in 15 min and took $\frac{1}{4}$ bbl to regain cir. TOH with tubing and bit. TIH with open ended tubing to 1224′. CWI and SDO

J Cooper Enterprises

7-31-2014

Rig up Basic Energy Services. Spot 75 SKS cls "C" neat mixed with 2% ccl at 1224' TOH with tubing. Load casing with 3 BFW. TIH wait 4 hr. TIH with tubing and tag cmt at 455' TOH. SDON

8-1-2014

Pull up 4 %" bit and 6- 3 %" drill collars. TIH with tubing to rig up reverse unit. D.O. good cmt from 455' to 673' (218') cir clean. CWI and SDON

J Cooper Enterprises

8-4-2014

Continue D.O. good cmt from 73' to 897' (224') and cir clean. CWI and SDON

J Cooper Enterprises

8-5-2014

TOH with tubing and bit pull up 4 more 3 $\frac{1}{2}$ " drill collars (total 10) TIH with bit and tubing to 897' Rig up reverse unit. Continue D.O. good cmt to 1108' and cir clean. Test casing to 500# for 10 min (ok) CWI and SDON

J Cooper Enterprises

8-6-2014

Rig up reverse unit. Continue D.O. good cmt from 1108' to 1173' and cir clean. Test casing to 500# for 10 min (ok). Drill to 1205' cir. Clean and test to 510' for 15 min and lost 20# in 15 min. Continue D.O. cmt to 1224 and fell out to 1234' and tag lost cir. Unable to regain with 40 bfw. TOH with tubing bit. SDON

J Cooper Enterprises

8-7-2014

Waiting on cmt.

J Cooper Enterprises

8-8-2014

Stood by for Basic until 10:00 am. Rig up and pump 10 bbl liquid glass and 300 sks. Cls "C" with 6% gel and 5% salt and 3# ppg Kol-seal mixed at 12.5 ppg. 100 sks cls "C" neat mixed at 14.8 ppg and 100 sks Cls "C" with 2% CCL mixed at 14.8 ppg and flushed with 10 BFW. CWI and SDON

8-11-2014

Pull up 4 ¾" bit. TIH with tubing to 1228' and tag cmt. TOH with tubing and bit. Pull up 10 3 ½" drill collars and bit. TIH with tubing to 1228'. Rig up reverse unit. D.O. to 1234' and test casing to 300# and 500# (ok) D.O. to 1237' and started losing water. Test to 300# and lost to 0# in 2 min. Unable to regain cir. With 40 BFW at 4 bpm sucking .8 bpm. TOH with tubing and bit. SDON

J Cooper Enterprises

8-12-2014

Shut down waiting on cement trucks

J Cooper Enterprises

8-13-2014

Rig up Basic Energy Services and pump 10 bbl liquid glass and 300 sks with 6 % gel and 5% salt and 5# p/s. Kol-Seal and ¾" Celo flakes mixed at 12.5 ppg and 200 sks Cls "C" with 2% CACL mixed at 14.8 ppg and flushed with 10 BFW. CWI and SDON

J Cooper Enterprises

8-14-2014

WOC

J Cooper Enterprises

8-15-2014

WOC

J Cooper Enterprises

8-16-2014

WOC

8-17-2014

woc

J Cooper Enterprises

8-18-2014

Pull up 4 ¾" bit. TIH with 10 drill collars and tubing to 1207' and tag cmt. Rig up reverse unit D.O. fair cmt to 1235' and lost cir. Unable to load hole with 25 BW. TOH with tubing and lay down 10 drill collars. Pull up 5 ½" cmt retainer. TIH with tubing to 1105' and set cmt retainer load casing.

J Cooper Enterprises

8-19-2014

Rig up Basic Energy Services. Pump 150 sks Cls "C" neat mixed at 14.8 ppg thru retainer. Pull out of retainer. Reverse out 1 bbl cmt. TOH laying down 2 7/8" tubing. Nipple down BOP. NUWH. CWI and rig down pulling unit. Job Complete

WELLBORE SCHEMATIC AND HISTORY

			RE SCHEMATIC		11						•			
<u> </u>			TION SCHEMATIC	;		APINUM				a.				
FORM	DEPT	H	5 (Wast 1	Erres process	OP 1 = 1	EHATOF	ع, ر	∞V	er Er	reco	2021V	NAVEL 1 11	·	
1						SENAME UL:		SEC:	8	TWN:	208	WELL N	0 1 37E	
					LOCATION:	UL.	330			1 4414.		FEL	3/E	
1					TD	680	PBD		KB	L	T DF			
					DHC				GL	3539				
					POOL					PERFS		5118-517	78	
		13 3/8			Monument Paddock OPEN HOLE									
.)		@ 250								' 6				
· 	•	Monument Blinebry OPEN Ho								6362-646	6			
		Ì			Monument	Tubb				OPEN I		0002-040	· · · · · ·	
		ŀ			POOL						PERFS			
1 .						<u> </u>		_		OPEN H	OLE			
Rustler	106	0	1 2 2 2 2 1 S	Z CON	nt Retain	. 11	95	<.		_				
	,					וו יאנ	02	ેવ	1900	X				
1		8 5/8 @ 1215	3255	Hole	CASING RI									
			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1224.	CASING RI	SIZE	DEP	TH	CMT		HOLE S	SIZE	TOC	
	·	1		$\mathcal{J}_{\!$	SURF.	13 3/8			260 sxs		17		Círc	
			j j.	1238	INTER. 1	8 5/8	1215		470 sxs		12 1/4		Circ	
#		1 .	} }	- 0	PROD.	5 1/2	6539		820 sxs		7.7/8		1600 est	
1		1	F 1	`			•							
1:				TOC 1600 est										
1			TE AND		^		. /	24.	+ ~	~/0				
j		ļ		1300	10 Con	109	200	14	6 2	196				
				5q. 4	430 SK	· Ta	3 An		+ 13	e o				
Yates	2432	}			•		7 0	٠,,,,,	,					
Seven Rive	re													
Joseph Taron			PK.											
Queen	3171		And Strip	Š										
l														
Grayburg		•		_ C1BP Parts -										
San Andres	3638			40.	4300		-							
				~ C10.	•		+.4	84E)	-				
				1.fc-	From "	1320	י פו נ	00						
ج ا				F /2//=										
Glorieta	5105			à.										
Giorioia	0.00			Perfs 5118-5178									,	
Paddock	5370												l	
				l										
·	l													
				1										
Diast-														
Blinebry	5590	•		Perfs 5593-5700									ı	
	J			Latie 2222-2100	•								į	
				Perfs 5708-5726										
	1			,										
Tubb	ESOE												ļ	
Tubb	6305			Perfs 6362-6371									· [
	İ			3002.00/1									!	
	- 1			Perfs 6452-6466	Sqz								1	
	- 1												ļ	
	1		3											
	5	1/2 @ 6539		1									l	
				f	PREPARE	D BY:				Ju	PDATE	D		
<u></u>							· · · · · · · · · · · · · · · · · · ·							