Submit 1 Copy To Appropriate District Office	State of New Mexico New Mexico		Form C-103 Revised July 18, 2013	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Whitural Resou	WELL API NO		
District II - (575) 748-1283	OIL CONGEDIVATION BOMBONI		0-025-23828	
District III - (505) 334-6178	S. First St., Artesia, NM 88210 OIL CONSERVATION trict III – (505) 334-6178 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM	3 100		COLE STATE	
87505 SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name	or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			14	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Numbe		
2. Name of Operator		9. OGRID Nun	9. OGRID Number	
VANGUARD PERMIAN LLC			258350	
3. Address of Operator 5847 SAN FELIPE SUITE 3000, HOUSTON, TEXAS 77057			10. Pool name or Wildcat PENROSE SKELLY GRAYBURG Sapandres	
4. Well Location			DLT GRATBORG SavAndres	
Unit Letter F: 2310 feet from theNORTH_line and1650 feet from the WEST line				
Section 16 Township 22S Range 37E NMPM LEA County				
	11. Elevation (Show whether DR, RKB, RT		t et a la l	
	3396 GL			
12 Check	Appropriate Box to Indicate Nature of	Notice Report or Othe	er Data	
		•	,	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
<u> </u>	ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASING				
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM				
OTHER:		: RECOMPLETION	•	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
PENROSE SKEUP, COMPINES				
DOO. NOTE OUT WITHING				
POOL DOED NOT PROCEED !				
PENNONE SKEWY GRAYBURG POOL DOES NOT INCIDIOS SEE ATTACHMENT SAN ANDRES				
	SEE ATTACHWII			
·				
Spud Date:	Rig Release Date:			
<i>N</i>	above is true and complete to the best of my			
GNATURE COLLENDING	TITLE AGENT AGENT	DATE	10-28-14	
	√			
· · · · —	many E-mail address: cgermany@oilrepor	tsinc.com PHONE: 575		
For State Use Only				
APPROVED BY: TITLE Petroleum Engineer DATE				
Conditions of Approval (if any):		E-PERMITTING	S	
Zone Temporarily Plugged (ZTP)		%A R	
Eunice San Ander	500 Sil)	INT to P&A	pur	
CSNG CHG Loc \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\				
		TA		

VANGUARD PERMIAN LLC

COLE STATE #14

F Sec 16 T22S R37E API #30-025-23828

Cole State #14

6/9/14 - 6/25/14

MIRU PU and unhang well, pull out production equipment, make cleanout run with bit and scraper.

RU wireline and RIH with CBP, set CBP at 3770'. PU guns and perforate Penrose Skelly; Grayburg interval 3476' – 3480', 3526' – 3530', 3656' – 3662' with 2 spf, 120 phasing, RD wireline.

PU packer and RIH, set packer at 3411'.

Pump 2000 gals 15% NEFE with 28 ball sealers to break down perforations.

Make swab runs to recover spent acid, POOH with packer and 2-3/8" tubing.

PU and RIH with 3-1/2" frac string tubing and %-1/2" packer. Set packer at 3402'.

Rigged up frac crew and frac'd with 110,300#'s 20/40 Brady sand and 40,480#'s of RC sand at 33.0 bbl/min.

Bleed off pressure, released packer and POOH with 3-1/2" frac string.

PU 2-3/8" tubing and sand bailer and RIH, tag sand at 3735' and start bailing. Bail to plug at 3710', POOH.

RIH with completion tubing, set TAC at 3269', SN at 3678' and EOT at 3710'. Run rods and pump.

Put well on production.

24 hr test: Penrose Skelly (50350) 1BOPD, 27 mcf



Cole State #14

P. Skelly/Graygurg/San Andres - 30-025-23828

Lea County, New Mexico

COMPLETION - 6/2014

